

Described maintenance is airworthy with respect to work performed.

DATE: 9/29/2020

SIGNED:

Danny Huchton

Work Order

Printed by EBis 3 (datcomedi



Tail Number: N689PG
Serial No. 1889

Aircraft Maintenance Log

ACFT Tach: 3247.6

Model: Cirrus SR20

Hobbs: 4281.1

ACFTT: 3247.6

Inspection Performed: Performed an Annual. Inspection in accordance with Cirrus Design maintenance Checklist.

Maintenance Performed: Complied with an Annual inspection in accordance with Cirrus Design SR2X maintenance manual and Chapter 5 Checklist. Cleaned Gaskolator, verified ELT operation. Removed and Reinstalled #6 Cylinder after repair by Sal's Aircraft Cylinders.

AD Compliance: Verified AD Compliance through Bi-Weekly 2021-06. No new Applicable AD's.

I Certify that this Airframe has been inspected in accordance with an Annual inspection. With respect to the work performed, this airframe is approved for return to service. Details of work performed are on file with Texas Skies Flight School under work order: WO_68.

Patrick Reeve

Date

Mar 25/2021

Annual Inspection Logbook Entry