



Appendix S to the Water Treatment Plant Factual Report, Photo 3, Irregular shaped concrete chunk found above rupture.