



Photo 1 – Front view of accident airplane (photo courtesy of the FAA)



Photo 2 - Front view of right-wing damage (photo courtesy of the FAA)



Photo 3 - Rear view of right-wing damage (photo courtesy of the FAA)



Photo 4 – View of auxiliary fuel pump placard (photo courtesy of the FAA)