

	L	M	N	O	P	Q	R	S	T	U	V
1	Cause of Leak	Other Cause	Repair Date	Repair Method	Address Line 1	Address Line 2	City	ZIP5	ZIP 4	Coupling Manufacturer	Coupling Model
2	Corrosion		20180302	Pipe Replaced	3761 cortez Dr		Dallas	00000		XXX	XXX
3	Gouge		20180223	Clamp Installed	9934 constance st.		Dallas	00000		XXX	XXX
4	Not Excavated		20180223	Abandoned	3732 cortez		Dallas	00000		XXX	XXX
5	Stripped Threads		20180224	Pipe Replaced	9301 SUNNYBROOK LN		Dallas	00000		XXX	XXX
6	Gasket/O-Ring		20180302	Pipe Replaced	3717 Cortez Dr		Dallas	00000		Unknown	XXX
7	Not Excavated		20180302	Abandoned	3747 Cortez Dr		Dallas	00000		XXX	XXX
8	Not Excavated		20180302	Abandoned	3754 CORTEZ		Dallas	00000		XXX	XXX
9	Gasket/O-Ring		20180224	Pipe Replaced	3719 durango		Dallas	00000		Unknown	XXX
10	Gasket/O-Ring		20180226	Pipe Replaced	3514 PARK LN		Dallas	00000		Unknown	XXX
11	Gasket/O-Ring		20180227	Pipe Replaced	9963 Bowman Blvd		Dallas	00000		Dresser	XXX
12	Stripped Threads		20180305	Abandoned	3703 davila		Dallas	00000		XXX	XXX
13	Stripped Threads		20180305	Abandoned	3958 CLOVER LN		Dallas	00000		XXX	XXX
14	Corrosion		20180224	Pipe Replaced	3858 Eaton		Dallas	00000		XXX	XXX
15	Stripped Threads		20180224	Component Replaced	3874 Van Ness Ln		Dallas	00000		XXX	XXX
16	Stripped Threads		20180312	Pipe Replaced	3117 TOWER TRL.		Dallas	00000		XXX	XXX
17	Not Excavated		20180302	Abandoned	3826 HAWICK LN		Dallas	00000		XXX	XXX
18	Gasket/O-Ring		20180224	Pipe Replaced	3764 Dunhaven Dr		Dallas	00000		Unknown	XXX
19	Gasket/O-Ring		20180226	Pipe Replaced	3520 Park Ln		Dallas	00000		Unknown	XXX
20	Stripped Threads		20180227	Abandoned	3438 Bogata Pl		Dallas	00000		XXX	XXX
21	Stripped Threads		20180305	Abandoned	3761 davila		Dallas	00000		XXX	XXX
22	Gouge		20180227	Pipe Replaced	9700 BLK WEBB CHAPEL @ STOREY		Dallas	00000		XXX	XXX
23	Corrosion		20180225	Abandoned	3410 Hildago		Dallas	00000		XXX	XXX
24	Excessive Strain		20180226	Pipe Replaced	10317 Crittendon Dr		Dallas	00000		XXX	XXX
25	Other	Other	20180225	Split Sleeve	3805 Eaton		Dallas	00000		Dresser	XXX
26	Stripped Threads		20180225	Pipe Replaced	4049 Rochelle Dr.		Dallas	00000		Unknown	XXX
27	Stripped Threads		20180226	Pipe Replaced	4047 High Grove Dr		Dallas	00000		Unknown	XXX
28	Gasket/O-Ring		20180226	Pipe Replaced	10206 CARRY BACK CIR.		Dallas	00000		XXX	XXX
29	Corrosion		20180226	Pipe Replaced	3804 WEMDON DR		Dallas	00000		XXX	XXX
30	Stripped Threads		20180226	Pipe Replaced	3649 Hidalgo dr		Dallas	00000		XXX	XXX
31	Stripped Threads		20180302	Abandoned	3700 CLOVER LN		Dallas	00000		XXX	XXX
32	Gasket/O-Ring		20180225	Pipe Replaced	4032 PARK LN		Dallas	00000		Unknown	XXX
33	Gasket/O-Ring		20180305	Pipe Replaced	4906 MILL RUN RD.		Dallas	00000		Dresser	XXX
34	Stripped Threads		20180228	Pipe Replaced	3019 MERRELL RD.		Dallas	00000		Dresser	XXX
35	Stripped Threads		20180225	Component Replaced	3890 Van Ness Ln		Dallas	00000		XXX	XXX
36	Stripped Threads		20180225	Pipe Replaced	3818 Lenel Pl		Dallas	00000		XXX	XXX
37	Stripped Threads		20180225	Pipe Replaced	3918 Hawick Ln		Dallas	00000		XXX	XXX
38	Stripped Threads		20180225	Pipe Replaced	9304 Lenel Pl		Dallas	00000		XXX	XXX
39	Gasket/O-Ring		20180225	Pipe Replaced	3561 HIGHGROVE DR		Dallas	00000		XXX	XXX
40	Stripped Threads		20180225	Pipe Replaced	3732 MANANA DR		Dallas	00000		XXX	XXX
41	Stripped Threads		20180225	Pipe Replaced	3738 MANANA DR		Dallas	00000		XXX	XXX
42	Stripped Threads		20180226	Pipe Replaced	3832 EATON DR		Dallas	00000		XXX	XXX
43	Stripped Threads		20180226	Tighten	9753 webb chapel rd		Dallas	00000		XXX	XXX
44	Stripped Threads		20180307	Pipe Replaced	3771 VAN NESS LN		Dallas	00000		XXX	XXX
45	Packing		20180225	Greasing	LAKEMONT DR AND LOMITA LN		Dallas	00000		XXX	XXX
46	Corrosion		20180226	Pipe Replaced	3232 Community Dr		Dallas	00000		XXX	XXX
47	Corrosion		20180226	Split Sleeve	2828 Reward		Dallas	00000		XXX	XXX
48	Not Excavated		20180226	Abandoned	3767 MATADOR DR.		Dallas	00000		XXX	XXX
49	Not Excavated		20180226	Pipe Replaced	3733 MATADOR DR.		Dallas	00000		XXX	XXX
50	Not Excavated		20180226	Pipe Replaced	3757 MATADOR DR.		Dallas	00000		XXX	XXX
51	Not Excavated		20180227	Abandoned	9763 Webb Chapel Rd		Dallas	00000		XXX	XXX

	L	M	N	O	P	Q	R	S	T	U	V
52	Not Excavated		20180228	Pipe Replaced	9747 Larga		Dallas	00000		XXX	XXX
53	Other Third Party Excavators		20180227	Abandoned	9800 Webb Chapel Rd		Dallas	00000		XXX	XXX
54	Stripped Threads		20180227	Pipe Replaced	3739 ROCKDALE DR.		Dallas	00000		XXX	XXX
55	Stripped Threads		20180301	Pipe Replaced	6814 JOYCE WAY		Dallas	00000		XXX	XXX
56	Corrosion		20180312	Split Sleeve	9702 Brockbank Dr		Dallas	00000		Unknown	XXX
57	Gasket/O-Ring		20180301	Pipe Replaced	9990 Monroe		Dallas	00000		Unknown	XXX
58	Other	Other	20180302	Abandoned	3715 MANANA DR.		Dallas	00000		Dresser	XXX
59	Ground Movement		20180226	Doped/Caulked	walnut hill ln and dresden		Dallas	00000		XXX	XXX
60	Ground Movement		20180227	Pipe Replaced	9730 Webb Chapel Rd		Dallas	00000		XXX	XXX
61	Gasket/O-Ring		20180228	Pipe Replaced	3208 Community Dr		Dallas	00000		XXX	XXX
62	Corrosion		20180227	Clamp Installed	3807 Van Ness		Dallas	00000		XXX	XXX
63	Excessive Strain		20180227	Pipe Replaced	9986 Chireno St.		Dallas	00000		XXX	XXX
64	Gasket/O-Ring		20180226	Pipe Replaced	3715 Clover		Dallas	00000		XXX	XXX
65	Gasket/O-Ring		20180313	Pipe Replaced	4916 MILL RUN RD		Dallas	00000		XXX	XXX
66	Ground Movement		20180303	Pipe Replaced	MARSH LN AND MERRELL RD		Dallas	00000		XXX	XXX
67	Not Excavated		20180302	Abandoned	3729 park ln		Dallas	00000		XXX	XXX
68	Not Excavated		20180302	Abandoned	3739 park ln		Dallas	00000		XXX	XXX
69	Not Excavated		20180302	Abandoned	3846 Hawick		Dallas	00000		XXX	XXX
70	Not Excavated		20180302	Abandoned	3857 Lenel Dr		Dallas	00000		XXX	XXX
71	Not Excavated		20180302	Abandoned	9955 Bowman Blvd		Dallas	00000		XXX	XXX
72	Gasket/O-Ring		20180227	Pipe Replaced	3217 KINKAID		Dallas	00000		Unknown	XXX
73	Gasket/O-Ring		20180227	Pipe Replaced	9960 Dresden Dr		Dallas	00000		Unknown	XXX
74	Other	Other	20180226	Pipe Replaced	3029 Clydedale		Dallas	00000		Normac	XXX
75	Other	Other	20180226	Pipe Replaced	3127 Lanoue Dr		Dallas	00000		Dresser	XXX
76	Other	Other	20180227	Pipe Replaced	3126 KENDALE DR		Dallas	00000		Unknown	XXX
77	Stripped Threads		20180227	Pipe Replaced	3729 ROCKDALE DR.		Dallas	00000		Other	XXX
78	Gasket/O-Ring		20180226	Pipe Replaced	3894 Cortez Dr.		Dallas	00000		XXX	XXX
79	Ground Movement		20180226	Split Sleeve	Walnut Hill & Dresden		Dallas	00000		XXX	XXX
80	Stripped Threads		20180226	Abandoned	2814 Clydedale		Dallas	00000		XXX	XXX
81	Stripped Threads		20180226	Pipe Replaced	3771 Davilia St.		Dallas	00000		XXX	XXX
82	Stripped Threads		20180227	Pipe Replaced	3957 BEECHWOOD LN		Dallas	00000		XXX	XXX
83	Stripped Threads		20180305	Abandoned	3705 PARK LN.		Dallas	00000		XXX	XXX
84	Stripped Threads		20180305	Abandoned	9800 webb chapel@chapel creek		Dallas	00000		XXX	XXX
85	Stripped Threads		20180305	Abandoned	9955 bowman blvd		Dallas	00000		XXX	XXX
86	Gasket/O-Ring		20180226	Split Sleeve	3155 Storey Ln.		Dallas	00000		XXX	XXX
87	Excessive Strain		20180309	Pipe Replaced	2844 Lombardy		Dallas	00000		XXX	XXX
88	Gasket/O-Ring		20180226	Pipe Replaced	3153 NEWCASTLE		Dallas	00000		XXX	XXX
89	Stripped Threads		20180227	Tighten	3208 COMMUNITY DR STE B		Dallas	00000		XXX	XXX
90	Stripped Threads		20180305	Component Replaced	2850 Clydedale		Dallas	00000		XXX	XXX
91	Weld (Steel)		20180227	Pipe Replaced	9940 Bowman		Dallas	00000		XXX	XXX
92	Ground Movement		20180228	Pipe Replaced	9946 Elmada Lane		Dallas	00000		XXX	XXX
93	Stripped Threads		20180227	Tighten	3476 Hidalgo Dr		Dallas	00000		XXX	XXX
94	Corrosion		20180227	Pipe Replaced	3935 VALLEY RIDGE RD		Dallas	00000		XXX	XXX
95	Corrosion		20180312	Split Sleeve	11760 Coral Hills		Dallas	00000		XXX	XXX
96	Gasket/O-Ring		20180227	Pipe Replaced	3801 Meadowdale Ln		Dallas	00000		Unknown	XXX
97	Gasket/O-Ring		20180227	Pipe Replaced	9837 WILLIAMSBURG RD		Dallas	00000		Unknown	XXX
98	Gasket/O-Ring		20180228	Pipe Replaced	3730 VAN NESS		Dallas	00000		Dresser	XXX
99	Other	Other	20180227	Pipe Replaced	3839 SHADY HILL DR		Dallas	00000		Unknown	XXX
100	Stripped Threads		20180227	Pipe Replaced	10270 Better Dr		Dallas	00000		Unknown	XXX
101	Stripped Threads		20180227	Split Sleeve	3220 CHAPEL CREEK DR		Dallas	00000		Unknown	XXX
102	Stripped Threads		20180228	Split Sleeve	9458 MARSH LN		Dallas	00000		Unknown	XXX

	L	M	N	O	P	Q	R	S	T	U	V
103	Stripped Threads		20180228	Pipe Replaced	3609 Seguin		Dallas	00000	XXX	XXX	
104	Stripped Threads		20180228	Pipe Replaced	CROMWELL AND FOREST LN		Dallas	00000	XXX	XXX	
105	Corrosion		20180228	Pipe Replaced	3632 Timberview dr		Dallas	00000	XXX	XXX	
106	Corrosion		20180314	Split Sleeve	10003 Marsh		Dallas	00000	XXX	XXX	
107	Ground Movement		20180302	Clamp Installed	10208 CRESTCOVE DR		Dallas	00000	XXX	XXX	
108	Ground Movement		20180312	Pipe Replaced	3208 Latham		Dallas	00000	XXX	XXX	
109	Not Excavated		20180302	Abandoned	3731 La joya dr		Dallas	00000	XXX	XXX	
110	Not Excavated		20180302	Abandoned	9750 mixon		Dallas	00000	XXX	XXX	
111	Not Excavated		20180302	Abandoned	9910 BOWMAN		Dallas	00000	XXX	XXX	
112	Not Excavated		20180302	Pipe Replaced	9745 post drive		Dallas	00000	XXX	XXX	
113	Stripped Threads		20180227	Pipe Replaced	10343 MARSH LN		Dallas	00000	XXX	XXX	
114	Gasket/O-Ring		20180228	Pipe Replaced	10209 Hedgeway Dr		Dallas	00000	Unknown	XXX	
115	Gasket/O-Ring		20180411	Abandoned	3152 WALNUT HILL LN.		Dallas	00000	Dresser	XXX	
116	Inadequate/Failure to Follow Procedures		20180301	Pipe Replaced	9852 WEBB CHAPEL RD		Dallas	00000	Unknown	XXX	
117	Stripped Threads		20180227	Pipe Replaced	10316 Hedgeway Dr		Dallas	00000	Unknown	XXX	
118	Stripped Threads		20180228	Split Sleeve	4206 IRVIN SIMMONS DR		Dallas	00000	Unknown	XXX	
119	Ground Movement		20180227	Pipe Replaced	3414 Manana Dr		Dallas	00000	XXX	XXX	
120	Ground Movement		20180227	Pipe Replaced	3415 Linda Dr		Dallas	00000	XXX	XXX	
121	Ground Movement		20180227	Pipe Replaced	3843 Cortez Dr		Dallas	00000	XXX	XXX	
122	Stripped Threads		20180227	Pipe Replaced	3839 Gaspar		Dallas	00000	XXX	XXX	
123	Stripped Threads		20180227	Pipe Replaced	4150 BEAVER BROOK LN		Dallas	00000	XXX	XXX	
124	Stripped Threads		20180228	Pipe Replaced	3162 Modela		Dallas	00000	XXX	XXX	
125	Stripped Threads		20180305	Abandoned	9935 bowman		Dallas	00000	XXX	XXX	
126	Stripped Threads		20180309	Pipe Replaced	3544 AINSWORTH DR		Dallas	00000	XXX	XXX	
127	Stripped Threads		20180309	Pipe Replaced	3833 SHADY HILL DR		Dallas	00000	XXX	XXX	
128	Ground Movement		20180228	Component Replaced	4132 CLOVER LN		Dallas	00000	XXX	XXX	
129	Ground Movement		20180228	Component Replaced	4133 LOMITA LN		Dallas	00000	XXX	XXX	
130	Ground Movement		20180228	Pipe Replaced	3725 Durango Dr		Dallas	00000	XXX	XXX	
131	Ground Movement		20180228	Pipe Replaced	3863 LENEL		Dallas	00000	XXX	XXX	
132	Stripped Threads		20180227	Pipe Replaced	3773 Manana Dr		Dallas	00000	XXX	XXX	
133	Stripped Threads		20180228	Pipe Replaced	3615 Sequin Dr		Dallas	00000	XXX	XXX	
134	Stripped Threads		20180529	Pipe Replaced	10208 CRESTOVER DR		Dallas	00000	XXX	XXX	
135	Gasket/O-Ring		20180304	Greasing	4048 DEEP VALLEY		Dallas	00000	XXX	XXX	
136	Corrosion		20180301	Clamp Installed	9994 Chireno		Dallas	00000	XXX	XXX	
137	Not Excavated		20180301	Abandoned	9925 CHIRENO		Dallas	00000	XXX	XXX	
138	Not Excavated		20180301	Abandoned	9946 WITHAM ST		Dallas	00000	XXX	XXX	
139	Not Excavated		20180301	Pipe Replaced	9902 CONSTANCE ST		Dallas	00000	XXX	XXX	
140	Not Excavated		20180302	Abandoned	3645 VALLEY RIDGE		Dallas	00000	XXX	XXX	
141	Other Third Party Excavators		20180301	Pipe Replaced	3418 Bogata		Dallas	00000	XXX	XXX	
142	Corrosion		20180228	Pipe Replaced	2860 Lombardy Ln.		Dallas	00000	Dresser	XXX	
143	Gasket/O-Ring		20180228	Pipe Replaced	10431 Goodyear Dr		Dallas	00000	Unknown	XXX	
144	Gasket/O-Ring		20180301	Pipe Replaced	10603 MARSH LN.		Dallas	00000	Unknown	XXX	
145	Other	Other	20180228	Pipe Replaced	3918 VALLEY RIDGE		Dallas	00000	Other	XXX	
146	Stripped Threads		20180314	Pipe Replaced	3744 Merrell Rd		Dallas	00000	Unknown	XXX	
147	Excessive Strain		20180228	Pipe Replaced	3668 valley ridge rd		Dallas	00000	XXX	XXX	
148	Packing		20180228	Greasing	3535 FOREST LN.		Dallas	00000	XXX	XXX	
149	Stripped Threads		20180228	Pipe Replaced	10323 Cromwell Dr.		Dallas	00000	XXX	XXX	
150	Stripped Threads		20180301	Pipe Replaced	2906 CONGRESSMAN		Dallas	00000	XXX	XXX	
151	Stripped Threads		20180301	Pipe Replaced	2926 CONGRESSMAN		Dallas	00000	XXX	XXX	
152	Packing		20180309	Pipe Replaced	4214 Middleton Rd		Dallas	00000	XXX	XXX	
153	Corrosion		20180228	Pipe Replaced	3416 TIMBERVIEW		Dallas	00000	XXX	XXX	

	L	M	N	O	P	Q	R	S	T	U	V
154	Corrosion		20180228	Pipe Replaced	9844 WILLIAMSBURG RD		Dallas	00000	XXX	XXX	
155	Corrosion		20180228	Pipe Replaced	9851 WILLIAMSBURG RD		Dallas	00000	XXX	XXX	
156	Corrosion		20180302	Split Sleeve	4130 S. Better Dr.		Dallas	00000	XXX	XXX	
157	Corrosion		20180302	Split Sleeve	marsh ln and high vista dr		Dallas	00000	XXX	XXX	
158	Not Excavated		20180302	Abandoned	3615 seguin dr		Dallas	00000	XXX	XXX	
159	Not Excavated		20180302	Abandoned	3709 Bolivar Dr		Dallas	00000	XXX	XXX	
160	Not Excavated		20180302	Abandoned	3848 Cortez Dr		Dallas	00000	XXX	XXX	
161	Not Excavated		20180302	Abandoned	3862 Cortez Dr		Dallas	00000	XXX	XXX	
162	Not Excavated		20180302	Abandoned	9846 Bowman Blvd		Dallas	00000	XXX	XXX	
163	Not Excavated		20180302	Abandoned	9938 Gooding Dr		Dallas	00000	XXX	XXX	
164	Not Excavated		20180302	Abandoned	9950 BOWMAN		Dallas	00000	XXX	XXX	
165	Stripped Threads		20180301	Pipe Replaced	9908 Gooding		Dallas	00000	XXX	XXX	
166	Gasket/O-Ring		20180228	Pipe Replaced	9931 witham st.		Dallas	00000	Unknown	XXX	
167	Gasket/O-Ring		20180301	Pipe Replaced	3458 TIMBERVIEW RD		Dallas	00000	Unknown	XXX	
168	Gasket/O-Ring		20180301	Pipe Replaced	4141 WILLOW GROVE RD		Dallas	00000	Other	XXX	
169	Gasket/O-Ring		20180302	Pipe Replaced	9958 CHIRENO ST		Dallas	00000	Unknown	XXX	
170	Gasket/O-Ring		20180304	Pipe Replaced	3481 Webb Garden Dr.		Dallas	00000	Normac	XXX	
171	Inadequate/Failure to Follow Procedures		20180301	Pipe Replaced	3427 MANANA		Dallas	00000	Unknown	XXX	
172	Other	Other	20180315	Split Sleeve	PARK LN & BOEDEKER ST		Dallas	00000	Dresser	XXX	
173	Stripped Threads		20180228	Pipe Replaced	3812 Durango Dr		Dallas	00000	Unknown	XXX	
174	Stripped Threads		20180301	Pipe Replaced	9938 Gooding		Dallas	00000	Dresser	XXX	
175	Stripped Threads		20180302	Split Sleeve	10100 BLK FIELDFARE DR		Dallas	00000	Unknown	XXX	
176	Stripped Threads		20180308	Pipe Replaced	3814 Eaton Dr		Dallas	00000	Dresser	XXX	
177	Stripped Threads		20180529	Pipe Replaced	3839 Constitution Dr		Dallas	00000	Unknown	XXX	
178	Stripped Threads		20180530	Pipe Replaced	10210 Cromwell Dr.		Dallas	00000	Unknown	XXX	
179	Backfill		20180314	Abandoned	10163 Midway		Dallas	00000	XXX	XXX	
180	Excessive Strain		20180301	Abandoned	3522 manana dr		Dallas	00000	XXX	XXX	
181	Excessive Strain		20180301	Pipe Replaced	10141 Marsh Ln.		Dallas	00000	XXX	XXX	
182	Gasket/O-Ring		20180302	Pipe Replaced	10114 Shady Oak Ln		Dallas	00000	XXX	XXX	
183	Ground Movement		20180228	Pipe Replaced	3411 Nogales Dr		Dallas	00000	XXX	XXX	
184	Ground Movement		20180301	Pipe Replaced	3422 Linda Dr		Dallas	00000	XXX	XXX	
185	Ground Movement		20180301	Pipe Replaced	3538 manana dr		Dallas	00000	XXX	XXX	
186	Ground Movement		20180316	Pipe Replaced	12335 HIGH MEADOW DR.		Dallas	00000	XXX	XXX	
187	Stripped Threads		20180228	Pipe Replaced	9911 Constance St		Dallas	00000	XXX	XXX	
188	Stripped Threads		20180301	Pipe Replaced	3808 Davila Dr		Dallas	00000	XXX	XXX	
189	Stripped Threads		20180305	Abandoned	3714 Davila Dr		Dallas	00000	XXX	XXX	
190	Stripped Threads		20180305	Abandoned	3751 Seguin Dr.		Dallas	00000	XXX	XXX	
191	Stripped Threads		20180305	Abandoned	3852 Eaton		Dallas	00000	XXX	XXX	
192	Stripped Threads		20180305	Abandoned	3881 Durango		Dallas	00000	XXX	XXX	
193	Stripped Threads		20180305	Abandoned	9840 Bowman Blvd		Dallas	00000	XXX	XXX	
194	Stripped Threads		20180305	Pipe Replaced	9856 WEBB CHAPEL RD		Dallas	00000	XXX	XXX	
195	Stripped Threads		20180307	Pipe Replaced	10137 Cromwell Dr.		Dallas	00000	XXX	XXX	
196	Stripped Threads		20180318	Pipe Replaced	3406 Salisbury Dr		Dallas	00000	XXX	XXX	
197	Gasket/O-Ring		20180301	Pipe Replaced	10144 Rockmoor Cir.		Dallas	00000	XXX	XXX	
198	Stripped Threads		20180228	Component Replaced	3757 ROYAL COVE DR		Dallas	00000	XXX	XXX	
199	Gasket/O-Ring		20180301	Greasing	3638 matador		Dallas	00000	XXX	XXX	
200	Gasket/O-Ring		20180328	Pipe Replaced	4223 MIDDLETON RD		Dallas	00000	XXX	XXX	
201	Packing		20180228	Pipe Replaced	3528 manana dr		Dallas	00000	XXX	XXX	
202	Packing		20180301	Pipe Replaced	3534 manana dr		Dallas	00000	XXX	XXX	
203	Packing		20180301	Split Sleeve	3908 Princess Cir.		Dallas	00000	XXX	XXX	
204	Packing		20180308	Greasing	MIDWAY RD @ MONTWOOD LN		Dallas	00000	XXX	XXX	

	L	M	N	O	P	Q	R	S	T	U	V
205	Factory Defect		20180301	Component Replaced	3873 ROYAL LN		Dallas	00000		XXX	XXX
206	Corrosion		20180302	Pipe Replaced	3120 valley meadow		Dallas	00000		XXX	XXX
207	Corrosion		20180302	Split Sleeve	3772 vinecrest		Dallas	00000		XXX	XXX
208	Gasket/O-Ring		20180303	Pipe Replaced	MARSH LN & PRINCESS DR		Dallas	00000		Unknown	XXX
209	Other	Other	20180301	Pipe Replaced	10229 timber trail dr.		Dallas	00000		Unknown	XXX
210	Stripped Threads		20180301	Pipe Replaced	4131 BEAVER BROOK LN		Dallas	00000		Unknown	XXX
211	Stripped Threads		20180302	Pipe Replaced	4331 Royal Ridge		Dallas	00000		Other	XXX
212	Stripped Threads		20180605	Pipe Replaced	10824 SNOW WHITE		Dallas	00000		Dresser	XXX
213	Stripped Threads		20180326	Pipe Replaced	11224 PINOCCHIO DR.		Dallas	00000		XXX	XXX
214	Packing		20180302	Greasing	MIDWAY RD AND IRVIN SIMMONS		Dallas	00000		XXX	XXX
215	Corrosion		20180301	Pipe Replaced	3840 WHITEHALL DR		Dallas	00000		XXX	XXX
216	Corrosion		20180305	Pipe Replaced	3230 Dartmoor Dr		Dallas	00000		XXX	XXX
217	Corrosion		20180306	Pipe Replaced	3236 Saint Croix		Dallas	00000		XXX	XXX
218	Corrosion		20180310	Pipe Replaced	4033 killion		Dallas	00000		XXX	XXX
219	Not Excavated		20180302	Abandoned	3415 PARK LN		Dallas	00000		XXX	XXX
220	Not Excavated		20180302	Abandoned	3760 Davila Dr.		Dallas	00000		XXX	XXX
221	Not Excavated		20180302	Abandoned	3813 Durango Dr.		Dallas	00000		XXX	XXX
222	Not Excavated		20180302	Abandoned	3822 Davila Dr.		Dallas	00000		XXX	XXX
223	Not Excavated		20180302	Abandoned	3846 Davila Dr		Dallas	00000		XXX	XXX
224	Not Excavated		20180302	Abandoned	3885 Durango Dr.		Dallas	00000		XXX	XXX
225	Weld (Steel)		20180315	Pipe Replaced	10811 BEAUTY LN		Dallas	00000		XXX	XXX
226	Gasket/O-Ring		20180301	Pipe Replaced	3543 TIMBERVIEW RD		Dallas	00000		Unknown	XXX
227	Gasket/O-Ring		20180301	Pipe Replaced	3627 TIMBERVIEW RD		Dallas	00000		Unknown	XXX
228	Gasket/O-Ring		20180302	Pipe Replaced	3489 Webb Garden Dr.		Dallas	00000		Unknown	XXX
229	Gasket/O-Ring		20180307	Pipe Replaced	4149 LOMITA LN		Dallas	00000		Dresser	XXX
230	Gasket/O-Ring		20180320	Pipe Replaced	10411 GOOD YEAR DR		Dallas	00000		Unknown	XXX
231	Gasket/O-Ring		20180322	Pipe Replaced	3526 TIMERVIEW RD		Dallas	00000		Unknown	XXX
232	Inadequate/Failure to Follow Procedures		20180302	Abandoned	3895 Highgrove Dr.		Dallas	00000		Unknown	XXX
233	Stripped Threads		20180308	Pipe Replaced	3245 DARTMOOR CT		Dallas	00000		Other	XXX
234	Stripped Threads		20180530	Pipe Replaced	3780 vinecrest		Dallas	00000		Unknown	XXX
235	Gasket/O-Ring		20180302	Pipe Replaced	3531 Merrell Rd		Dallas	00000		XXX	XXX
236	Gasket/O-Ring		20180302	Pipe Replaced	3539 Merrell Rd		Dallas	00000		XXX	XXX
237	Gasket/O-Ring		20180302	Pipe Replaced	3542 Warick Dr		Dallas	00000		XXX	XXX
238	Gasket/O-Ring		20180302	Pipe Replaced	3547 Merrell Rd		Dallas	00000		XXX	XXX
239	Gasket/O-Ring		20180302	Pipe Replaced	3563 Merrell Rd		Dallas	00000		XXX	XXX
240	Stripped Threads		20180301	Pipe Replaced	9902 Gooding		Dallas	00000		XXX	XXX
241	Excessive Strain		20180303	Encapsulation	9408 THORNBERRY LN.		Dallas	00000		XXX	XXX
242	Not Excavated		20180302	Abandoned	3944 HAWICK LN		Dallas	00000		XXX	XXX
243	Gasket/O-Ring		20180302	Pipe Replaced	10817 Aladdin Dr		Dallas	00000		Unknown	XXX
244	Gasket/O-Ring		20180302	Pipe Replaced	9943 bowman		Dallas	00000		Dresser	XXX
245	Gasket/O-Ring		20180303	Pipe Replaced	MARSH LANE AND JUBILEE TRAIL		Dallas	00000		XXX	XXX
246	Stripped Threads		20180302	Pipe Replaced	10643 Les Jardins Dr		Dallas	00000		XXX	XXX
247	Stripped Threads		20180302	Pipe Replaced	4420 Melissa Ln		Dallas	00000		XXX	XXX
248	Stripped Threads		20180302	Pipe Replaced	9429 GREEN TERRACE DR.		Dallas	00000		XXX	XXX
249	Stripped Threads		20180310	Pipe Replaced	4189 VALLEY RIDGE RD		Dallas	00000		XXX	XXX
250	Packing		20180309	Pipe Replaced	Midway & Echo Glen		Dallas	00000		XXX	XXX
251	Corrosion		20180307	Pipe Replaced	3803 martha		Dallas	00000		XXX	XXX
252	Excessive Strain		20180302	Pipe Replaced	9850 Lakemont Dr.		Dallas	00000		XXX	XXX
253	Not Excavated		20180302	Abandoned	3990 DURANGO DR		Dallas	00000		XXX	XXX
254	Stripped Threads		20180303	Pipe Replaced	10915 snow white		Dallas	00000		XXX	XXX
255	Stripped Threads		20180310	Pipe Replaced	10433 MARSH LN		Dallas	00000		XXX	XXX

	L	M	N	O	P	Q	R	S	T	U	V
256	Gasket/O-Ring		20180310	Pipe Replaced	3836 LENEL		Dallas	00000		Dresser	XXX
257	Stripped Threads		20180306	Pipe Replaced	3605 Royal Ln.		Dallas	00000		Unknown	XXX
258	Corrosion		20180307	Pipe Replaced	3509 Royal Ln.		Dallas	00000		XXX	XXX
259	Gasket/O-Ring		20180319	Pipe Replaced	4126 Courtshire Dr.		Dallas	00000		XXX	XXX
260	Ground Movement		20180302	Pipe Replaced	2943 Townsend Dr		Dallas	00000		XXX	XXX
261	Ground Movement		20180305	Pipe Replaced	4182 Saranac Dr.		Dallas	00000		XXX	XXX
262	Ground Movement		20180306	Pipe Replaced	4131 HOCKADAY		Dallas	00000		XXX	XXX
263	Ground Movement		20180306	Pipe Replaced	4178 Saranac Dr.		Dallas	00000		XXX	XXX
264	Ground Movement		20180311	Pipe Replaced	4242 Meadowdale Ln		Dallas	00000		XXX	XXX
265	Ground Movement		20180320	Pipe Replaced	4120 Saranac Dr.		Dallas	00000		XXX	XXX
266	Stripped Threads		20180305	Abandoned	11314 Cox Ln.		Dallas	00000		XXX	XXX
267	Stripped Threads		20180305	Abandoned	9905 Glenrio Ln.		Dallas	00000		XXX	XXX
268	Stripped Threads		20180309	Pipe Replaced	3543 Royal Ln.		Dallas	00000		XXX	XXX
269	Stripped Threads		20180310	Pipe Replaced	3808 Lenel		Dallas	00000		XXX	XXX
270	Stripped Threads		20180310	Pipe Replaced	4007 Alta Vista		Dallas	00000		XXX	XXX
271	Stripped Threads		20180311	Pipe Replaced	10838 pinocchio		Dallas	00000		XXX	XXX
272	Stripped Threads		20180524	Pipe Replaced	3322 JUBILEE TRL		Dallas	00000		XXX	XXX
273	Weld (Steel)		20180305	Split Sleeve	3745 Northaven Rd.		Dallas	00000		XXX	XXX
274	Gasket/O-Ring		20180304	Pipe Replaced	11416 Coral Hills Dr.		Dallas	00000		XXX	XXX
275	Stripped Threads		20180622	Component Replaced	3780 W. NORTHWEST HWY		Dallas	00000		XXX	XXX
276	Weld (Steel)		20180313	Pipe Replaced	4183 Beechwood Lane		Dallas	00000		XXX	XXX
277	Weld (Steel)		20180313	Pipe Replaced	4194 Valley Ridge Rd.		Dallas	00000		XXX	XXX
278	Corrosion		20180315	Pipe Replaced	9466 THORNBERRY LN		Dallas	00000		XXX	XXX
279	Corrosion		20180304	Split Sleeve	4833 Irvin Simmons		Dallas	00000		XXX	XXX
280	Gasket/O-Ring		20180304	Pipe Replaced	3796 Vinecrest Dr		Dallas	00000		XXX	XXX
281	Other Third Party Excavators		20180303	Abandoned	11479 harry hines blvd		Dallas	00000		XXX	XXX
282	Stripped Threads		20180304	Pipe Replaced	4057 Northaven Road		Dallas	00000		XXX	XXX
283	Corrosion		20180305	Doped/Caulked	3909 ALTA VISTA LN		Dallas	00000		XXX	XXX
284	Ground Movement		20180306	Pipe Replaced	3141 TALISMAN DR.		Dallas	00000		XXX	XXX
285	Ground Movement		20180306	Pipe Replaced	3154 TALISMAN DR.		Dallas	00000		XXX	XXX
286	Ground Movement		20180307	Pipe Replaced	3940 SHADY HILL DR		Dallas	00000		XXX	XXX
287	Ground Movement		20180308	Pipe Replaced	4157 COURTSIRE DR.		Dallas	00000		XXX	XXX
288	Ground Movement		20180402	Pipe Replaced	2911 NORTHAVEN RD		Dallas	00000		XXX	XXX
289	Corrosion		20180304	Pipe Replaced	3131 JUBILEE TRAIL		Dallas	00000		Dresser	XXX
290	Corrosion		20180308	Pipe Replaced	4141 SHADY HILL DR.		Dallas	00000		Dresser	XXX
291	Gasket/O-Ring		20180303	Pipe Replaced	3534 WARICK DR		Dallas	00000		Dresser	XXX
292	Gasket/O-Ring		20180304	Component Replaced	3155 JUBILEE TRAIL		Dallas	00000		Dresser	XXX
293	Gasket/O-Ring		20180304	Pipe Replaced	4321 GLENAIRE DR		Dallas	00000		Dresser	XXX
294	Stripped Threads		20180303	Pipe Replaced	3784 Alta Vista Ln.		Dallas	00000		Dresser	XXX
295	Stripped Threads		20180529	Pipe Replaced	3752 Alta Vista Ln.		Dallas	00000		Unknown	XXX
296	Gasket/O-Ring		20180304	Pipe Replaced	4240 SAN GABRIEL DR		Dallas	00000		XXX	XXX
297	Stripped Threads		20180305	Pipe Replaced	3571 Royal Ln		Dallas	00000		XXX	XXX
298	Stripped Threads		20180307	Pipe Replaced	11023 Beauty		Dallas	00000		XXX	XXX
299	Stripped Threads		20180307	Pipe Replaced	3516 Coral Gables Dr.		Dallas	00000		XXX	XXX
300	Stripped Threads		20180310	Pipe Replaced	3533 Vinecrest		Dallas	00000		XXX	XXX
301	Stripped Threads		20180319	Pipe Replaced	6326 Meadow Rd		Dallas	00000		XXX	XXX
302	Gasket/O-Ring		20180304	Greasing	4048 Deep Valley Dr.		Dallas	00000		XXX	XXX
303	Gasket/O-Ring		20180304	Greasing	4052 Deep Valley		Dallas	00000		XXX	XXX
304	Stripped Threads		20180305	Greasing	11429 Webb Chapel Rd.		Dallas	00000		XXX	XXX
305	Corrosion		20180304	Abandoned	3257 Lancelot Dr		Dallas	00000		XXX	XXX
306	Stripped Threads		20180304	Pipe Replaced	4207 BOBBITT DR		Dallas	00000		XXX	XXX

	L	M	N	O	P	Q	R	S	T	U	V
307	Gasket/O-Ring		20180304	Pipe Replaced	4316 MENDENHALL DR		Dallas	00000		Dresser	XXX
308	Stripped Threads		20180304	Pipe Replaced	4230 MELISSA LN		Dallas	00000		Unknown	XXX
309	Stripped Threads		20180305	Pipe Replaced	4421 Allencrest Dr		Dallas	00000		XXX	XXX
310	Stripped Threads		20180310	Pipe Replaced	10740 LATHROP LN		Dallas	00000		XXX	XXX
311	Backfill		20180305	Pipe Replaced	3323 Newcastle		Dallas	00000		XXX	XXX
312	Corrosion		20180304	Clamp Installed	4314 MELISSA LN		Dallas	00000		XXX	XXX
313	Corrosion		20180306	Pipe Replaced	3250 St. Croix Dr.		Dallas	00000		XXX	XXX
314	Ground Movement		20180305	Pipe Replaced	4631 Allencrest Ln		Dallas	00000		XXX	XXX
315	Ground Movement		20180308	Pipe Replaced	4311 Northview Ln.		Dallas	00000		XXX	XXX
316	Ground Movement		20180308	Pipe Replaced	4422 MYERWOOD Ln		Dallas	00000		XXX	XXX
317	Ground Movement		20180308	Pipe Replaced	4525 ALTA VISTA LN.		Dallas	00000		XXX	XXX
318	Gasket/O-Ring		20180305	Pipe Replaced	3278 Lockmoor		Dallas	00000		Unknown	XXX
319	Gasket/O-Ring		20180305	Pipe Replaced	4607 nashwood ln		Dallas	00000		Dresser	XXX
320	Gasket/O-Ring		20180305	Pipe Replaced	4608 Meyerwood Ln.		Dallas	00000		Dresser	XXX
321	Gasket/O-Ring		20180306	Pipe Replaced	3205 kinkaid		Dallas	00000		Unknown	XXX
322	Stripped Threads		20180305	Pipe Replaced	3755 northview ln.		Dallas	00000		Unknown	XXX
323	Backfill		20180304	Pipe Replaced	3164 Newcastle		Dallas	00000		XXX	XXX
324	Backfill		20180306	Pipe Replaced	4715 Gulfstream Dr.		Dallas	00000		XXX	XXX
325	Gasket/O-Ring		20180305	Greasing	Merrell & Rosser		Dallas	00000		XXX	XXX
326	Gasket/O-Ring		20180305	Pipe Replaced	3747 Shady Hill Dr.		Dallas	00000		XXX	XXX
327	Stripped Threads		20180304	Pipe Replaced	4608 Willow Ln		Dallas	00000		XXX	XXX
328	Corrosion		20180305	Pipe Replaced	4407 Irvin Simmons		Dallas	00000		XXX	XXX
329	Corrosion		20180305	Clamp Installed	4832 BOBBITT DR		Dallas	00000		XXX	XXX
330	Corrosion		20180308	Pipe Replaced	4911 Harvest Hill		Dallas	00000		XXX	XXX
331	Other Third Party Excavators		20180310	Pipe Replaced	9146 cochran heights		Dallas	00000		XXX	XXX
332	Packing		20180305	Greasing	Boedeker St & Caruth Haven Ln		Dallas	00000		XXX	XXX
333	Stripped Threads		20180306	Pipe Replaced	7541 Villanova Dr		Dallas	00000		XXX	XXX
334	Gasket/O-Ring		20180307	Tighten	4209 Myerwood Ln.		Dallas	00000		Other	XXX
335	Other	Other	20180305	Pipe Replaced	3866 Crest Cove Cir		Dallas	00000		Unknown	XXX
336	Gasket/O-Ring		20180305	Pipe Replaced	4535 Allencrest Ln.		Dallas	00000		XXX	XXX
337	Stripped Threads		20180305	Pipe Replaced	4808 Ridgeside dr.		Dallas	00000		XXX	XXX
338	Stripped Threads		20180316	Pipe Replaced	3216 WALDROP DR.		Dallas	00000		XXX	XXX
339	Packing		20180307	Tighten	4207 Nashwood Ln.		Dallas	00000		XXX	XXX
340	Corrosion		20180305	Pipe Replaced	4931 Nashwood Ln.		Dallas	00000		XXX	XXX
341	Corrosion		20180306	Clamp Installed	3425 Northaven Rd.		Dallas	00000		XXX	XXX
342	Corrosion		20180309	Pipe Replaced	12426 high meadow dr		Dallas	00000		XXX	XXX
343	Corrosion		20180316	Split Sleeve	4608 Willow Ln.		Dallas	00000		XXX	XXX
344	Ground Movement		20180306	Pipe Replaced	3818 Port Royal Dr.		Dallas	00000		XXX	XXX
345	Stripped Threads		20180530	Pipe Replaced	4231 northhaven rd		Dallas	00000		XXX	XXX
346	Weld (Steel)		20180309	Split Sleeve	3462 FLAIR DR		Dallas	00000		XXX	XXX
347	Gasket/O-Ring		20180305	Pipe Replaced	4728 Thunder		Dallas	00000		Dresser	XXX
348	Gasket/O-Ring		20180306	Abandoned	4919 Heatherbrook Dr.		Dallas	00000		Unknown	XXX
349	Gasket/O-Ring		20180306	Pipe Replaced	4450 Mendenhall		Dallas	00000		Other	XXX
350	Other	Other	20180305	Pipe Replaced	3836 Crest Cove Cir.		Dallas	00000		Unknown	XXX
351	Stripped Threads		20180311	Pipe Replaced	4847 Forest Bend		Dallas	00000		Other	XXX
352	Stripped Threads		20180312	Pipe Replaced	3719 High Vista Dr		Dallas	00000		Dresser	XXX
353	Stripped Threads		20180312	Split Sleeve	4715 GULFSTREAM DR		Dallas	00000		Dresser	XXX
354	Stripped Threads		20180530	Pipe Replaced	3546 WOODLIEGH DR		Dallas	00000		Unknown	XXX
355	Excessive Strain		20180311	Pipe Replaced	4838 Mill Run		Dallas	00000		XXX	XXX
356	Gasket/O-Ring		20180307	Split Sleeve	4436 mill creek rd		Dallas	00000		XXX	XXX
357	Gasket/O-Ring		20180320	Pipe Replaced	3610 WALDORF DR.		Dallas	00000		XXX	XXX

	L	M	N	O	P	Q	R	S	T	U	V
358	Ground Movement		20180305	Pipe Replaced	3765 High Vista Dr		Dallas	00000		XXX	XXX
359	Ground Movement		20180306	Tighten	3796 WALDORF		Dallas	00000		XXX	XXX
360	Stripped Threads		20180305	Pipe Replaced	3608 Timberview		Dallas	00000		XXX	XXX
361	Stripped Threads		20180305	Pipe Replaced	3609 ROYAL LN		Dallas	00000		XXX	XXX
362	Packing		20180305	Greasing	HARVEST HILL/WELCH		Dallas	00000		XXX	XXX
363	Stripped Threads		20180306	Component Replaced	4475 ROYAL LN		Dallas	00000		XXX	XXX
364	Corrosion		20180309	Pipe Replaced	4558 hockaday		Dallas	00000		Dresser	XXX
365	Equipment Malfunction		20180307	Pipe Replaced	5110 RADBROOK PI		Dallas	00000		Unknown	XXX
366	Equipment Malfunction		20180315	Pipe Replaced	9838 Witham		Dallas	00000		Unknown	XXX
367	Gasket/O-Ring		20180312	Pipe Replaced	4310 REAUMUR		Dallas	00000		Dresser	XXX
368	Stripped Threads		20180306	Split Sleeve	4048 DEEP VALLEY DR		Dallas	00000		Unknown	XXX
369	Gasket/O-Ring		20180307	Component Replaced	4215 ROSA COURT		Dallas	00000		XXX	XXX
370	Stripped Threads		20180306	Split Sleeve	4086 Crown Shore Dr		Dallas	00000		XXX	XXX
371	Stripped Threads		20180311	Pipe Replaced	3349 Whitehall Dr.		Dallas	00000		XXX	XXX
372	Corrosion		20180307	Clamp Installed	3667 Whitehall		Dallas	00000		XXX	XXX
373	Corrosion		20180307	Clamp Installed	4214 Willow Grove Rd		Dallas	00000		XXX	XXX
374	Corrosion		20180307	Pipe Replaced	11475 Cromwell Ct.		Dallas	00000		XXX	XXX
375	Corrosion		20180307	Pipe Replaced	11628 Coral Hills Ct.		Dallas	00000		XXX	XXX
376	Corrosion		20180311	Clamp Installed	Mangold Cir & Strait Ln		Dallas	00000		XXX	XXX
377	Corrosion		20180312	Clamp Installed	10106 Timber trail Dr.		Dallas	00000		XXX	XXX
378	Corrosion		20180320	Split Sleeve	11323 Coral Hills Dr.		Dallas	00000		XXX	XXX
379	Stripped Threads		20180307	Pipe Replaced	4439 Bonham St.		Dallas	00000		XXX	XXX
380	Stripped Threads		20180505	Pipe Replaced	3253 Kinkaid		Dallas	00000		XXX	XXX
381	Weld (Steel)		20180307	Doped/Caulked	3230 Dartmoor Dr.		Dallas	00000		XXX	XXX
382	Equipment Malfunction		20180307	Pipe Replaced	11349 Coral Hills Dr.		Dallas	00000		Unknown	XXX
383	Equipment Malfunction		20180308	Pipe Replaced	4435 San Gabriel Dr		Dallas	00000		Unknown	XXX
384	Gasket/O-Ring		20180308	Pipe Replaced	11220 Strait Ln		Dallas	00000		Unknown	XXX
385	Inadequate/Failure to Follow Procedures		20180307	Pipe Replaced	4525 harrys ln		Dallas	00000		Unknown	XXX
386	Stripped Threads		20180309	Pipe Replaced	3234 Altman Dr.		Dallas	00000		Dresser	XXX
387	Stripped Threads		20180409	Abandoned	3471 Timberview Rd.		Dallas	00000		Dresser	XXX
388	Stripped Threads		20180606	Pipe Replaced	3449 Timberview Rd.		Dallas	00000		Unknown	XXX
389	Gasket/O-Ring		20180307	Pipe Replaced	4230 Walnut Hill Ln		Dallas	00000		XXX	XXX
390	Ground Movement		20180307	Pipe Replaced	4170 MEADOWDALE		Dallas	00000		XXX	XXX
391	Stripped Threads		20180306	Pipe Replaced	3237 Duchess Trl		Dallas	00000		XXX	XXX
392	Stripped Threads		20180311	Component Replaced	4418 Merrell Rd.		Dallas	00000		XXX	XXX
393	Packing		20180416	Pipe Replaced	3352 Princess Ln		Dallas	00000		XXX	XXX
394	Corrosion		20180307	Tighten	3211 ALTMAN		Dallas	00000		XXX	XXX
395	Corrosion		20180308	Clamp Installed	3237 Catamore Ln		Dallas	00000		XXX	XXX
396	Corrosion		20180308	Pipe Replaced	4337 MILL CREEK RD		Dallas	00000		XXX	XXX
397	Gasket/O-Ring		20180308	Pipe Replaced	4110 Crossing Ln		Dallas	00000		XXX	XXX
398	Other Third Party Excavators		20180308	Abandoned	10600 Preston Rd.		Dallas	00000		XXX	XXX
399	Gasket/O-Ring		20180308	Pipe Replaced	10616 COOGAN DR.		Dallas	00000		Dresser	XXX
400	Stripped Threads		20180307	Abandoned	10561 CHANNEL DR.		Dallas	00000		Unknown	XXX
401	Stripped Threads		20180308	Pipe Replaced	4307 Ridge Rd.		Dallas	00000		Other	XXX
402	Stripped Threads		20180308	Split Sleeve	4205 Lively Ln		Dallas	00000		Dresser	XXX
403	Stripped Threads		20180313	Pipe Replaced	4138 Willow Grove Road		Dallas	00000		Dresser	XXX
404	Stripped Threads		20180307	Pipe Replaced	4848 Forest Bend Rd		Dallas	00000		XXX	XXX
405	Stripped Threads		20180312	Pipe Replaced	3672 Pallos Verdas Dr		Dallas	00000		XXX	XXX
406	Corrosion		20180307	Clamp Installed	4062 LBJ I 635E		Dallas	00000		XXX	XXX
407	Corrosion		20180320	Split Sleeve	3638 Northaven Rd		Dallas	00000		XXX	XXX
408	Dent		20180606	Clamp Installed	10770 COOGAN		Dallas	00000		XXX	XXX

	L	M	N	O	P	Q	R	S	T	U	V
409	Dent		20180608	Clamp Installed	10774 COOGAN		Dallas	00000		XXX	XXX
410	Gasket/O-Ring		20180309	Split Sleeve	3314 Darbyshire		Dallas	00000		XXX	XXX
411	Stripped Threads		20180311	Pipe Replaced	4946 Mill Run Rd		Dallas	00000		XXX	XXX
412	Stripped Threads		20180505	Pipe Replaced	3312 DARVANY DRIVE		Dallas	00000		XXX	XXX
413	Corrosion		20180320	Pipe Replaced	2910 CARRIZO ST.		Dallas	00000		Dresser	XXX
414	Gasket/O-Ring		20180307	Pipe Replaced	4408 Allencrest		Dallas	00000		Unknown	XXX
415	Gasket/O-Ring		20180311	Pipe Replaced	10225 Dale Crest Dr.		Dallas	00000		Dresser	XXX
416	Gasket/O-Ring		20180316	Pipe Replaced	2970 CARRIZO ST.		Dallas	00000		Unknown	XXX
417	Gasket/O-Ring		20180317	Pipe Replaced	11023 ROSSER		Dallas	00000		Unknown	XXX
418	Stripped Threads		20180310	Pipe Replaced	10106 Brockbank Dr		Dallas	00000		Unknown	XXX
419	Stripped Threads		20180316	Pipe Replaced	10737 ALLEGHENY DR.		Dallas	00000		Unknown	XXX
420	Stripped Threads		20180402	Pipe Replaced	4840 Ellensburg Dr		Dallas	00000		Unknown	XXX
421	Stripped Threads		20180606	Pipe Replaced	4243 NORTHVIEW LN.		Dallas	00000		Unknown	XXX
422	Corrosion		20180308	Doped/Caulked	3508 Midpines Dr.		Dallas	00000		XXX	XXX
423	Stripped Threads		20180315	Pipe Replaced	4610 N. Lindhurst Ave.		Dallas	00000		XXX	XXX
424	Stripped Threads		20180510	Pipe Replaced	4150 ALLENCREST		Dallas	00000		XXX	XXX
425	Gasket/O-Ring		20180321	Abandoned	4243 Middleton Rd.		Dallas	00000		XXX	XXX
426	Stripped Threads		20180321	Pipe Replaced	4207 WALNUT HILL LN		Dallas	00000		XXX	XXX
427	Stripped Threads		20180605	Pipe Replaced	4314 Crowley Dr.		Dallas	00000		XXX	XXX
428	Stripped Threads		20180606	Pipe Replaced	10555 CHANNEL DR.		Dallas	00000		XXX	XXX
429	Stripped Threads		20180608	Pipe Replaced	10565 CHANNEL DR.		Dallas	00000		XXX	XXX
430	Gasket/O-Ring		20180322	Pipe Replaced	11300 Blk Marsh Ln		Dallas	00000		XXX	XXX
431	Stripped Threads		20180308	Tighten	4274 S CRESTHAVEN RD		Dallas	00000		XXX	XXX
432	Corrosion		20180309	Pipe Replaced	4326 Margate Dr		Dallas	00000		XXX	XXX
433	Gasket/O-Ring		20180309	Split Sleeve	3314 DARBYSHIRE		Dallas	00000		XXX	XXX
434	Gasket/O-Ring		20180310	Pipe Replaced	4830 TWIN POST RD.		Dallas	00000		XXX	XXX
435	Ground Movement		20180309	Pipe Replaced	3523 Flair Dr		Dallas	00000		XXX	XXX
436	Weld (Steel)		20180309	Split Sleeve	3747 WALNUT HILL LN		Dallas	00000		XXX	XXX
437	Weld (Steel)		20180312	Pipe Replaced	Webb Chapel & Regent		Dallas	00000		XXX	XXX
438	Equipment Malfunction		20180309	Pipe Replaced	5632 brookstown		Dallas	00000		Unknown	XXX
439	Gasket/O-Ring		20180308	Pipe Replaced	3140 NEWCASTLE DRIVE		Dallas	00000		Unknown	XXX
440	Gasket/O-Ring		20180309	Pipe Replaced	9800 BLK INWOOD RD		Dallas	00000		Unknown	XXX
441	Gasket/O-Ring		20180329	Pipe Replaced	5812 Orchid Ln		Dallas	00000		Unknown	XXX
442	Stripped Threads		20180308	Split Sleeve	9100 Rockbrook Dr		Dallas	00000		Unknown	XXX
443	Stripped Threads		20180309	Pipe Replaced	4828 Forest Bend Rd.		Dallas	00000		XXX	XXX
444	Corrosion		20180309	Pipe Replaced	9801 DALE CREST DR		Dallas	00000		XXX	XXX
445	Corrosion		20180314	Pipe Replaced	5805 Desco Drive		Dallas	00000		XXX	XXX
446	Corrosion		20180331	Pipe Replaced	JOURDAN AND AVERILL		Dallas	00000		XXX	XXX
447	Corrosion		20180402	Clamp Installed	5505 DELOACHE AVE		Dallas	00000		XXX	XXX
448	Ground Movement		20180323	Pipe Replaced	4933 HARVEST HILL RD.		Dallas	00000		XXX	XXX
449	Stripped Threads		20180311	Pipe Replaced	3636 High Bluff Dr		Dallas	00000		XXX	XXX
450	Stripped Threads		20180505	Pipe Replaced	3330 DARVANY DRIVE		Dallas	00000		XXX	XXX
451	Stripped Threads		20180505	Pipe Replaced	3335 KINKAID DRIVE		Dallas	00000		XXX	XXX
452	Stripped Threads		20180505	Pipe Replaced	3342 DARVANY DRIVE		Dallas	00000		XXX	XXX
453	Weld (Steel)		20180321	Split Sleeve	3646 HIGH VISTA DR		Dallas	00000		XXX	XXX
454	Corrosion		20180321	Pipe Replaced	10434 Channel Dr.		Dallas	00000		Dresser	XXX
455	Gasket/O-Ring		20180309	Pipe Replaced	3158 WALNUT HILL LANE		Dallas	00000		Dresser	XXX
456	Gasket/O-Ring		20180311	Pipe Replaced	2919 CARRIZO ST.		Dallas	00000		Dresser	XXX
457	Gasket/O-Ring		20180313	Pipe Replaced	3419 High Bluff Dr		Dallas	00000		Dresser	XXX
458	Gasket/O-Ring		20180404	Pipe Replaced	2951 SEYMOUR DR.		Dallas	00000		Unknown	XXX
459	Stripped Threads		20180313	Pipe Replaced	2938 BAY OAKS DR.		Dallas	00000		Dresser	XXX

	L	M	N	O	P	Q	R	S	T	U	V
460	Gasket/O-Ring		20180309	Pipe Replaced	3306 LOCKMOOR LANE		Dallas	00000	XXX	XXX	
461	Stripped Threads		20180310	Pipe Replaced	9101 Rockbrook Dr		Dallas	00000	XXX	XXX	
462	Stripped Threads		20180313	Pipe Replaced	9934 HATHAWAY ST		Dallas	00000	XXX	XXX	
463	Gasket/O-Ring		20180612	Component Replaced	5818 Waggoner dr		Dallas	00000	XXX	XXX	
464	Stripped Threads		20180327	Pipe Replaced	4562 royal ln		Dallas	00000	XXX	XXX	
465	Stripped Threads		20180416	Component Replaced	4302 Enfield Dr		Dallas	00000	XXX	XXX	
466	Stripped Threads		20180608	Pipe Replaced	11826 HIGH VALLEY		Dallas	00000	XXX	XXX	
467	Stripped Threads		20180608	Pipe Replaced	3655 CORAL GABLES DR		Dallas	00000	XXX	XXX	
468	Corrosion		20180310	Clamp Installed	10330 Strait Ln		Dallas	00000	XXX	XXX	
469	Other Third Party Excavators		20180309	Split Sleeve	10720 PRESTON RD		Dallas	00000	XXX	XXX	
470	Stripped Threads		20180313	Pipe Replaced	5629 Ridgetown Cir.		Dallas	00000	XXX	XXX	
471	Equipment Malfunction		20180309	Abandoned	3747 Walnut Hill Ln		Dallas	00000	Unknown	XXX	
472	Equipment Malfunction		20180311	Pipe Replaced	5858 WAGGONER DR		Dallas	00000	Unknown	XXX	
473	Gasket/O-Ring		20180310	Pipe Replaced	5320 SpringMeadow Dr		Dallas	00000	Dresser	XXX	
474	Stripped Threads		20180309	Split Sleeve	5315 Royal Ln		Dallas	00000	Dresser	XXX	
475	Stripped Threads		20180309	Split Sleeve	TIMBERLINE DR AND SUMTER DR		Dallas	00000	Unknown	XXX	
476	Corrosion		20180311	Pipe Replaced	4137 dunhaven rd		Dallas	00000	XXX	XXX	
477	Corrosion		20180611	Clamp Installed	5314 Yolanda Ln		Dallas	00000	XXX	XXX	
478	Corrosion		20180613	Clamp Installed	5012 BROOKVIEW		Dallas	00000	XXX	XXX	
479	Corrosion		20180614	Pipe Replaced	4510 Glenleigh Drive		Dallas	00000	XXX	XXX	
480	Other	Other	20180314	Split Sleeve	9806 Inwood		Dallas	00000	XXX	XXX	
481	Stripped Threads		20180310	Pipe Replaced	3747 walnut hill ln		Dallas	00000	XXX	XXX	
482	Weld (Steel)		20180316	Doped/Caulked	5522 Williamstown Rd.		Dallas	00000	XXX	XXX	
483	Equipment Malfunction		20180310	Pipe Replaced	5512 Melshire Dr.		Dallas	00000	Unknown	XXX	
484	Gasket/O-Ring		20180403	Pipe Replaced	3657 High Vista Dr		Dallas	00000	Unknown	XXX	
485	Stripped Threads		20180313	Pipe Replaced	5628 Lindenshire Ln		Dallas	00000	Unknown	XXX	
486	Stripped Threads		20180316	Pipe Replaced	3941 Cobblestone Dr		Dallas	00000	Dresser	XXX	
487	Stripped Threads		20180404	Split Sleeve	5440 pebbbrook Dr		Dallas	00000	Unknown	XXX	
488	Stripped Threads		20180611	Tighten	6130 Stichter Ave.		Dallas	00000	XXX	XXX	
489	Stripped Threads		20180402	Pipe Replaced	4423 melissa ln		Dallas	00000	XXX	XXX	
490	Stripped Threads		20180402	Pipe Replaced	5731 CALADIUM DR		Dallas	00000	XXX	XXX	
491	Stripped Threads		20180611	Component Replaced	5839 MEADOW CREST DR		Dallas	00000	XXX	XXX	
492	Stripped Threads		20180612	Component Replaced	5902 averill wsy		Dallas	00000	XXX	XXX	
493	Weld (Steel)		20180330	Pipe Replaced	5731 NORTHAVEN RD		Dallas	00000	XXX	XXX	
494	Corrosion		20180312	Pipe Replaced	Hillcrest & Northaven		Dallas	00000	XXX	XXX	
495	Corrosion		20180314	Pipe Replaced	5333 WALNUT HILL LANE		Dallas	00000	XXX	XXX	
496	Factory Defect		20180311	Component Replaced	6457 ABERDEEN		Dallas	00000	XXX	XXX	
497	Factory Defect		20180313	Pipe Replaced	5320 NORTHAVEN RD		Dallas	00000	XXX	XXX	
498	Other Third Party Excavators		20180310	Abandoned	3711 HAWICK LN		Dallas	00000	XXX	XXX	
499	Stripped Threads		20180310	Pipe Replaced	10123 goodyear		Dallas	00000	XXX	XXX	
500	Gasket/O-Ring		20180310	Abandoned	5723 Williamstown Road		Dallas	00000	Unknown	XXX	
501	Gasket/O-Ring		20180311	Split Sleeve	3019 Plaudit		Dallas	00000	Dresser	XXX	
502	Other	Other	20180310	Pipe Replaced	5714 meletio		Dallas	00000	Dresser	XXX	
503	Corrosion		20180408	Pipe Replaced	9430 Hathaway		Dallas	00000	XXX	XXX	
504	Stripped Threads		20180321	Pipe Replaced	5830 Meletio Ln		Dallas	00000	XXX	XXX	
505	Stripped Threads		20180409	Pipe Replaced	3008 townsend		Dallas	00000	XXX	XXX	
506	Stripped Threads		20180409	Pipe Replaced	6152 Preston haven		Dallas	00000	XXX	XXX	
507	Weld (Steel)		20180411	Split Sleeve	3667 NORTHAVEN		Dallas	00000	XXX	XXX	
508	Equipment Malfunction		20180311	Abandoned	5614 BROOKSTOWN LEAK B		Dallas	00000	Unknown	XXX	
509	Equipment Malfunction		20180312	Pipe Replaced	5714 Del Roy Drive		Dallas	00000	Dresser	XXX	
510	Gasket/O-Ring		20180312	Pipe Replaced	5715 Boca Raton Drive		Dallas	00000	Dresser	XXX	

	L	M	N	O	P	Q	R	S	T	U	V
511	Gasket/O-Ring		20180403	Abandoned	6429 Azalea		Dallas	00000		Unknown	XXX
512	Gasket/O-Ring		20180403	Pipe Replaced	5017 Willow		Dallas	00000		Dresser	XXX
513	Gasket/O-Ring		20180403	Pipe Replaced	5538 PRESTON HAVEN DR		Dallas	00000		Unknown	XXX
514	Gasket/O-Ring		20180403	Pipe Replaced	5538 Preston Haven Dr		Dallas	00000		Unknown	XXX
515	Other	Other	20180313	Pipe Replaced	5722 meletio		Dallas	00000		Dresser	XXX
516	Stripped Threads		20180312	Pipe Replaced	5842 Azalea Ln		Dallas	00000		Unknown	XXX
517	Stripped Threads		20180408	Pipe Replaced	6814 Royal Ln		Dallas	00000		Dresser	XXX
518	Corrosion		20180312	Pipe Replaced	5932 Meletio Ln		Dallas	00000		XXX	XXX
519	Gasket/O-Ring		20180409	Component Replaced	2920 Forest Ln.		Dallas	00000		XXX	XXX
520	Stripped Threads		20180319	Abandoned	5618 Meletio Ln		Dallas	00000		XXX	XXX
521	Stripped Threads		20180404	Pipe Replaced	11831 Jamestown Road		Dallas	00000		XXX	XXX
522	Gasket/O-Ring		20180403	Pipe Replaced	3557 Ainsworth Dr		Dallas	00000		XXX	XXX
523	Stripped Threads		20180403	Pipe Replaced	6722 Aberdeen Ave		Dallas	00000		XXX	XXX
524	Stripped Threads		20180613	Component Replaced	6034 del Roy		Dallas	00000		XXX	XXX
525	Stripped Threads		20180614	Pipe Replaced	.4310 NORTHVIEW LN		Dallas	00000		XXX	XXX
526	Weld (Steel)		20180331	Pipe Replaced	8601 JOURDAN WAY		Dallas	00000		XXX	XXX
527	Gasket/O-Ring		20180312	Pipe Replaced	5523 PARK LN		Dallas	00000		Dresser	XXX
528	Stripped Threads		20180313	Split Sleeve	COLHURST ST & PRESTON RD		Dallas	00000		Unknown	XXX
529	Stripped Threads		20180311	Pipe Replaced	6542 Azalea Lane		Dallas	00000		XXX	XXX
530	Corrosion		20180316	Split Sleeve	3353 ROYAL		Dallas	00000		XXX	XXX
531	Corrosion		20180405	Pipe Replaced	PRESTON HAVEN @ Forest Ln		Dallas	00000		XXX	XXX
532	Corrosion		20180412	Pipe Replaced	5500 mEADERS IN		Dallas	00000		XXX	XXX
533	Corrosion		20180615	Clamp Installed	10264 Sherbrook Ln		Dallas	00000		XXX	XXX
534	Corrosion		20180615	Clamp Installed	3756 VANCOUVER		Dallas	00000		XXX	XXX
535	Stripped Threads		20180330	Pipe Replaced	3306 Darvany In		Dallas	00000		XXX	XXX
536	Stripped Threads		20180406	Split Sleeve	5635 Yolana Cir		Dallas	00000		XXX	XXX
537	Equipment Malfunction		20180402	Pipe Replaced	6757 Prestonshire		Dallas	00000		Other	XXX
538	Gasket/O-Ring		20180404	Pipe Replaced	3116 Long Bow Ct.		Dallas	00000		Unknown	XXX
539	Other	Other	20180317	Pipe Replaced	3250 LEAHY		Dallas	00000		Dresser	XXX
540	Stripped Threads		20180311	Pipe Replaced	10203 Hollow Way Rd		Dallas	00000		Dresser	XXX
541	Stripped Threads		20180314	Pipe Replaced	4140 LIVELY LN		Dallas	00000		Unknown	XXX
542	Stripped Threads		20180410	Pipe Replaced	6532 Willow Ln		Dallas	00000		Dresser	XXX
543	Gasket/O-Ring		20180413	Pipe Replaced	6027 Lake Hurst Ave		Dallas	00000		XXX	XXX
544	Stripped Threads		20180405	Split Sleeve	12143 High Meadow Dr.		Dallas	00000		XXX	XXX
545	Gasket/O-Ring		20180410	Tighten	6475 GLENDORA		Dallas	00000		XXX	XXX
546	Stripped Threads		20180317	Pipe Replaced	6839 walnut hill		Dallas	00000		XXX	XXX
547	Stripped Threads		20180319	Pipe Replaced	6739 walnut hill		Dallas	00000		XXX	XXX
548	Stripped Threads		20180619	Pipe Replaced	6219 LAKEHURST AVE		Dallas	00000		XXX	XXX
549	Stripped Threads		20180619	Pipe Replaced	6539 TULIP		Dallas	00000		XXX	XXX
550	Corrosion		20180315	Pipe Replaced	4307 WILLIAMSBURG RD.		Dallas	00000		XXX	XXX
551	Other Third Party Excavators		20180312	Pipe Replaced	8310 CHADBOURNE RD		Dallas	00000		XXX	XXX
552	Backfill		20180312	Component Replaced	3517 HIGH MESA DR		Dallas	00000		XXX	XXX
553	Corrosion		20180627	Clamp Installed	9230 Meadowbrook Dr.		Dallas	00000		XXX	XXX
554	Corrosion		20180628	Split Sleeve	10336 Crestover Dr		Dallas	00000		XXX	XXX
555	Stripped Threads		20180406	Doped/Caulked	4637 MEADOWOOD RD.		Dallas	00000		XXX	XXX
556	Equipment Malfunction		20180625	Pipe Replaced	5120 Radbrook Pl		Dallas	00000		Unknown	XXX
557	Equipment Malfunction		20180627	Pipe Replaced	4110 cochran chapel rd		Dallas	00000		Normac	XXX
558	Gasket/O-Ring		20180405	Pipe Replaced	5455 Northbrook Dr.		Dallas	00000		Unknown	XXX
559	Gasket/O-Ring		20180405	Pipe Replaced	6418 Royalton Dr		Dallas	00000		Dresser	XXX
560	Other	Other	20180405	Split Sleeve	6006 joyce way		Dallas	00000		Unknown	XXX
561	Other	Other	20180410	Pipe Replaced	11026 TIBBS ST		Dallas	00000		Unknown	XXX

	L	M	N	O	P	Q	R	S	T	U	V
562	Other	Other	20180502	Abandoned	4922 W Northwest Hwy		Dallas	00000		Dresser	XXX
563	Stripped Threads		20180315	Pipe Replaced	5623 williamstown		Dallas	00000		Unknown	XXX
564	Stripped Threads		20180313	Split Sleeve	6311 Aberdeen Ave.		Dallas	00000		XXX	XXX
565	Gasket/O-Ring		20180404	Pipe Replaced	6831 ORCHID LN		Dallas	00000		XXX	XXX
566	Stripped Threads		20180621	Abandoned	4639 N LINDHURST AVE		Dallas	00000		XXX	XXX
567	Stripped Threads		20180621	Pipe Replaced	3559 high mesa dr		Dallas	00000		XXX	XXX
568	Packing		20180625	Greasing	4163 Dunhaven Rd.		Dallas	00000		XXX	XXX
569	Stripped Threads		20180313	Greasing	4343 W. NORTHWEST HWY		Dallas	00000		XXX	XXX
570	Corrosion		20180314	Pipe Replaced	4308 BEECHWOOD LN.		Dallas	00000		XXX	XXX
571	Corrosion		20180315	Pipe Replaced	4214 WILLOW GROVE RD.		Dallas	00000		XXX	XXX
572	Factory Defect		20180314	Component Replaced	5917 Azalea Ln		Dallas	00000		XXX	XXX
573	Corrosion		20180315	Pipe Replaced	5511 Pebblebrook Dr		Dallas	00000		Dresser	XXX
574	Equipment Malfunction		20180313	Pipe Replaced	5939 meadow crest		Dallas	00000		Normac	XXX
575	Gasket/O-Ring		20180315	Pipe Replaced	11256 RUSSWOOD CIR		Dallas	00000		Dresser	XXX
576	Stripped Threads		20180313	Pipe Replaced	5617 LINDNSHIRE LN		Dallas	00000		Dresser	XXX
577	Factory Defect		20180314	Pipe Replaced	4421 Walnut Hill Ln.		Dallas	00000		XXX	XXX
578	Stripped Threads		20180315	Pipe Replaced	10400 Strait Ln.		Dallas	00000		XXX	XXX
579	Corrosion		20180314	Split Sleeve	Northhaven & Hillcrest		Dallas	00000		XXX	XXX
580	Gasket/O-Ring		20180405	Pipe Replaced	5815 Azalae Ln		Dallas	00000		Dresser	XXX
581	Gasket/O-Ring		20180407	Pipe Replaced	4808 ELLENSBURG DR		Dallas	00000		Dresser	XXX
582	Gasket/O-Ring		20180410	Pipe Replaced	5110 Pebblebrook Dr		Dallas	00000		Unknown	XXX
583	Gasket/O-Ring		20180411	Pipe Replaced	3831 BOCA BAY DR		Dallas	00000		Unknown	XXX
584	Gasket/O-Ring		20180502	Pipe Replaced	4042 Dunhaven		Dallas	00000		Dresser	XXX
585	Other	Other	20180407	Pipe Replaced	4840 Hallmark Dr.		Dallas	00000		Unknown	XXX
586	Stripped Threads		20180407	Doped/Caulked	5117 meadow crest		Dallas	00000		XXX	XXX
587	Stripped Threads		20180407	Pipe Replaced	11430 Strait In.		Dallas	00000		XXX	XXX
588	Packing		20180406	Greasing	4611 Northaven Rd.		Dallas	00000		XXX	XXX
589	Corrosion		20180314	Split Sleeve	3720 Pallos Verdaz		Dallas	00000		XXX	XXX
590	Equipment Malfunction		20180315	Abandoned	12000 preston rd		Dallas	00000		Unknown	XXX
591	Other	Other	20180316	Pipe Replaced	6007 MEADOW RD.		Dallas	00000		Unknown	XXX
592	Stripped Threads		20180315	Pipe Replaced	6110 DEL NORTE LN		Dallas	00000		XXX	XXX
593	Corrosion		20180319	Pipe Replaced	12557 High Meadow Dr.		Dallas	00000		XXX	XXX
594	Corrosion		20180407	Split Sleeve	6432 Del Norte		Dallas	00000		XXX	XXX
595	Corrosion		20180410	Split Sleeve	11410 Royalshire Dr.		Dallas	00000		XXX	XXX
596	Gasket/O-Ring		20180416	Pipe Replaced	4309 Park Ln		Dallas	00000		Dresser	XXX
597	Stripped Threads		20180316	Split Sleeve	3855 PALLOS VERDAS DR.		Dallas	00000		Dresser	XXX
598	Stripped Threads		20180410	Pipe Replaced	6115 Northwood rd		Dallas	00000		XXX	XXX
599	Stripped Threads		20180410	Pipe Replaced	6545 Greenwich In		Dallas	00000		XXX	XXX
600	Stripped Threads		20180411	Pipe Replaced	6432 Preston Crest		Dallas	00000		XXX	XXX
601	Stripped Threads		20180418	Pipe Replaced	5942 glendora		Dallas	00000		XXX	XXX
602	Stripped Threads		20180315	Pipe Replaced	3828 VINECREST		Dallas	00000		XXX	XXX
603	Stripped Threads		20180315	Tighten	10715 Preston Rd.		Dallas	00000		XXX	XXX
604	Other Third Party Excavators		20180315	Abandoned	2536 FOREST LN		Dallas	00000		XXX	XXX
605	Stripped Threads		20180315	Pipe Replaced	11714 PARWEN DR.		Dallas	00000		XXX	XXX
606	Stripped Threads		20180316	Split Sleeve	10066 MARSH LN.		Dallas	00000		XXX	XXX
607	Corrosion		20180315	Pipe Replaced	3191 TOWNSEND DR.		Dallas	00000		Unknown	XXX
608	Stripped Threads		20180315	Split Sleeve	Hillcrest @ Joyce		Dallas	00000		Unknown	XXX
609	Gasket/O-Ring		20180317	Pipe Replaced	3795 Crown Shore Drive		Dallas	00000		Unknown	XXX
610	Gasket/O-Ring		20180409	Pipe Replaced	12331 High Meadow		Dallas	00000		Unknown	XXX
611	Gasket/O-Ring		20180410	Pipe Replaced	12210 high meadow dr.		Dallas	00000		Unknown	XXX
612	Stripped Threads		20180411	Pipe Replaced	3405 High Mesa Dr.		Dallas	00000		Unknown	XXX

	L	M	N	O	P	Q	R	S	T	U	V
613	Weld (Steel)		20180410	Split Sleeve	4180 LIVELY LN		Dallas	00000		XXX	XXX
614	Packing		20180409	Greasing	Inwood Rd & Pebblebrook Dr		Dallas	00000		XXX	XXX
615	Packing		20180410	Greasing	3312 FOREST LN.		Dallas	00000		XXX	XXX
616	Stripped Threads		20180424	Pipe Replaced	4205 HARVEST HILL RD.		Dallas	00000		XXX	XXX
617	Factory Defect		20180316	Pipe Replaced	6712 Prestonsire		Dallas	00000		XXX	XXX
618	Corrosion		20180316	Pipe Replaced	3535 REGENT DR.		Dallas	00000		Other	XXX
619	Corrosion		20180411	Split Sleeve	6026 Averill		Dallas	00000		XXX	XXX
620	Excessive Strain		20180414	Pipe Replaced	10750 les jardins dr		Dallas	00000		XXX	XXX
621	Gasket/O-Ring		20180410	Pipe Replaced	6053 meadow rd		Dallas	00000		Dresser	XXX
622	Gasket/O-Ring		20180411	Tighten	VILLAVERDE AVE. & MARSH LN.		Dallas	00000		Dresser	XXX
623	Excessive Strain		20180406	Pipe Replaced	5619 Northmoore Dr.		Dallas	00000		XXX	XXX
624	Corrosion		20180318	Split Sleeve	9965 Monroe Dr.		Dallas	00000		XXX	XXX
625	Stripped Threads		20180318	Pipe Replaced	9840 Monroe Dr		Dallas	00000		Unknown	XXX
626	Stripped Threads		20180317	Abandoned	3824 SLEEPY LANE		Dallas	00000		XXX	XXX
627	Ground Movement		20180409	Pipe Replaced	11450 SAINT MICHAELS		Dallas	00000		XXX	XXX
628	Excessive Strain		20180406	Pipe Replaced	5310 castlewood		Dallas	00000		XXX	XXX
629	Stripped Threads		20180525	Pipe Replaced	10221 Timber Trail		Dallas	00000		XXX	XXX
630	Not Excavated		20180319	Pipe Replaced	2862 Lombardy In		Dallas	00000		XXX	XXX
631	Gasket/O-Ring		20180318	Abandoned	10830 Grissom Ln.		Dallas	00000		Unknown	XXX
632	Gasket/O-Ring		20180318	Pipe Replaced	2820 MERRELL RD		Dallas	00000		Dresser	XXX
633	Gasket/O-Ring		20180318	Pipe Replaced	3056 Dothan Drive		Dallas	00000		Unknown	XXX
634	Gasket/O-Ring		20180320	Greasing	10325 Denton Dr		Dallas	00000		XXX	XXX
635	Ground Movement		20180411	Pipe Replaced	10225 BROCKBANK DR		Dallas	00000		XXX	XXX
636	Gasket/O-Ring		20180318	Pipe Replaced	10621 Allegheny		Dallas	00000		Unknown	XXX
637	Other	Other	20180410	Pipe Replaced	9417 Overlake Dr.		Dallas	00000		Dresser	XXX
638	Stripped Threads		20180318	Pipe Replaced	2948 DOTHAN LN		Dallas	00000		Unknown	XXX
639	Stripped Threads		20180320	Pipe Replaced	2917 Lombardy Ln		Dallas	00000		Other	XXX
640	Excessive Strain		20180409	Pipe Replaced	3038 Oradell Ln.		Dallas	00000		XXX	XXX
641	Stripped Threads		20180516	Pipe Replaced	11523 Harry Hines Blvd		Dallas	00000		XXX	XXX
642	Corrosion		20180320	Clamp Installed	Denton Dr @ Willowbrook Ln		Dallas	00000		XXX	XXX
643	Other Third Party Excavators		20180319	Abandoned	2904 STANFORD AVE		Dallas	00000		XXX	XXX
644	Other Third Party Excavators		20180319	Abandoned	4745 Crooked Ln		Dallas	00000		XXX	XXX
645	Stripped Threads		20180319	Component Replaced	5133 Forest Lane Pl		Dallas	00000		XXX	XXX
646	Corrosion		20180410	Split Sleeve	2905 Talisman Dr		Dallas	00000		XXX	XXX
647	Excessive Strain		20180420	Split Sleeve	3240 Flowerdale		Dallas	00000		XXX	XXX
648	Stripped Threads		20180411	Pipe Replaced	10727 Allengheny Dr.		Dallas	00000		XXX	XXX
649	Backfill		20180409	Component Replaced	3055 Kinkaid		Dallas	00000		XXX	XXX
650	Corrosion		20180320	Abandoned	6239 Deloache Ave		Dallas	00000		XXX	XXX
651	Corrosion		20180320	Pipe Replaced	6231 Stefani Dr.		Dallas	00000		XXX	XXX
652	Corrosion		20180320	Split Sleeve	10249 Denton Dr		Dallas	00000		XXX	XXX
653	Ground Movement		20180322	Pipe Replaced	11122 MORRISON LN		Dallas	00000		XXX	XXX
654	Other	Other	20180321	Pipe Replaced	11819 Webb Chapel Rd		Dallas	00000		Dresser	XXX
655	Stripped Threads		20180320	Split Sleeve	2622 MYRTLE SPRINGS AVE		Dallas	00000		Unknown	XXX
656	Stripped Threads		20180321	Pipe Replaced	11155 MORRISON LN		Dallas	00000		Unknown	XXX
657	Stripped Threads		20180320	Pipe Replaced	6037 Northwood		Dallas	00000		XXX	XXX
658	Backfill		20180419	Pipe Replaced	11215 Shady Trail		Dallas	00000		XXX	XXX
659	Stripped Threads		20180409	Pipe Replaced	6151 Preston Haven Dr		Dallas	00000		XXX	XXX
660	Stripped Threads		20180413	Pipe Replaced	11354 Royalshire Dr.		Dallas	00000		XXX	XXX
661	Equipment Malfunction		20180409	Pipe Replaced	6032 Preston Haven Dr		Dallas	00000		Unknown	XXX
662	Gasket/O-Ring		20180320	Pipe Replaced	6529 LINDEN LN		Dallas	00000		Dresser	XXX
663	Gasket/O-Ring		20180409	Pipe Replaced	11437 Royalshire Dr		Dallas	00000		Dresser	XXX

	L	M	N	O	P	Q	R	S	T	U	V
664	Other	Other	20180419	Pipe Replaced	2614 Andjon		Dallas	00000		Dresser	XXX
665	Stripped Threads		20180330	Pipe Replaced	2104 Crown		Dallas	00000		Unknown	XXX
666	Stripped Threads		20180503	Pipe Replaced	3245 Northhaven Rd.		Dallas	00000		Unknown	XXX
667	Stripped Threads		20180411	Pipe Replaced	6230 Lupton Dr.		Dallas	00000		XXX	XXX
668	Stripped Threads		20180411	Pipe Replaced	6238 Aberdeen Ave		Dallas	00000		XXX	XXX
669	Stripped Threads		20180416	Pipe Replaced	6614 Lupton Dr.		Dallas	00000		XXX	XXX
670	Corrosion		20180322	Split Sleeve	2527 Royal In.		Dallas	00000		XXX	XXX
671	Other Third Party Excavators		20180322	Abandoned	2305 SOUTHWELL RD		Dallas	00000		XXX	XXX
672	Other Third Party Excavators		20180326	Abandoned	5411 SURREY CIR		Dallas	00000		XXX	XXX
673	Stripped Threads		20180321	Tighten	7215 LAVENDALE CIR		Dallas	00000		XXX	XXX
674	Packing		20180323	Pipe Replaced	11569 HARRY HINES		Dallas	00000		XXX	XXX
675	Stripped Threads		20180329	Doped/Caulked	DEEP VALLEY & MIDWAY		Dallas	00000		XXX	XXX
676	Corrosion		20180322	Split Sleeve	2622 Myrtle Springs Ave		Dallas	00000		XXX	XXX
677	Fire/Explosion First		20180323	Pipe Replaced	10220 BROCKBANK DR		Dallas	00000		XXX	XXX
678	Other Third Party Excavators		20180324	Component Replaced	4310 ROSSER SQ		Dallas	00000		XXX	XXX
679	Corrosion		20180419	Pipe Replaced	11253 Harry Hines		Dallas	00000		XXX	XXX
680	Stripped Threads		20180416	Pipe Replaced	6730 Brookshire Dr		Dallas	00000		XXX	XXX
681	Stripped Threads		20180324	Pipe Replaced	5506 Charlestown Dr.		Dallas	00000		Unknown	XXX
682	Packing		20180619	Greasing	9362 Hathaway		Dallas	00000		XXX	XXX
683	Corrosion		20180326	Clamp Installed	6131 STICHTER AVE		Dallas	00000		XXX	XXX
684	Corrosion		20180326	Pipe Replaced	6611 ABERDEEN AVE		Dallas	00000		XXX	XXX
685	Corrosion		20180325	Pipe Replaced	5834 Azalea		Dallas	00000		Dresser	XXX
686	Gasket/O-Ring		20180325	Pipe Replaced	5440 PEBBLEBROOK DR		Dallas	00000		Dresser	XXX
687	Corrosion		20180425	Clamp Installed	6523 Lupton		Dallas	00000		XXX	XXX
688	Stripped Threads		20180424	Pipe Replaced	5710 Northmoor Dr.		Dallas	00000		XXX	XXX
689	Ground Movement		20180326	Pipe Replaced	4833 WILLOW LN.		Dallas	00000		XXX	XXX
690	Gasket/O-Ring		20180326	Abandoned	2619 NOVA DR.		Dallas	00000		Unknown	XXX
691	Gasket/O-Ring		20180326	Pipe Replaced	10720 preston Rd		Dallas	00000		XXX	XXX
692	Corrosion		20180417	Pipe Replaced	4635 RIDGESIDE		Dallas	00000		XXX	XXX
693	Corrosion		20180426	Pipe Replaced	3143 LANOUE DR.		Dallas	00000		XXX	XXX
694	Stripped Threads		20180331	Pipe Replaced	11127 Eastview Cir		Dallas	00000		XXX	XXX
695	Stripped Threads		20180426	Pipe Replaced	11115 HillCrest Rd		Dallas	00000		XXX	XXX
696	Stripped Threads		20180426	Pipe Replaced	4830 Heatherbrook Dr		Dallas	00000		XXX	XXX
697	Packing		20180501	Tighten	WELCH & MILL RUN @ ALLEY		Dallas	00000		XXX	XXX
698	Stripped Threads		20180403	Pipe Replaced	5025 Willow Ln		Dallas	00000		XXX	XXX
699	Gasket/O-Ring		20180510	Pipe Replaced	4150 Allen Crest Ln		Dallas	00000		Dresser	XXX
700	Ground Movement		20180329	Pipe Replaced	6415 DELOACHE AVE.		Dallas	00000		XXX	XXX
701	Ground Movement		20180502	Pipe Replaced	6323 TULIP LN.		Dallas	00000		XXX	XXX
702	Stripped Threads		20180428	Pipe Replaced	5831 BURGUNDY		Dallas	00000		XXX	XXX
703	Stripped Threads		20180428	Pipe Replaced	5933 BURGUNDY		Dallas	00000		XXX	XXX
704	Stripped Threads		20180427	Pipe Replaced	6505 WOODLAND DR.		Dallas	00000		Unknown	XXX
705	Stripped Threads		20180430	Pipe Replaced	6515 CHEVY CHASE AVE.		Dallas	00000		Unknown	XXX
706	Stripped Threads		20180430	Pipe Replaced	5641 Boca Raton Dr.		Dallas	00000		XXX	XXX
707	Stripped Threads		20180430	Pipe Replaced	5955 Charlestown Dr.		Dallas	00000		XXX	XXX
708	Stripped Threads		20180328	Pipe Replaced	6806 PRESTONSHIRE LN. IN ALLEY		Dallas	00000		XXX	XXX
709	Stripped Threads		20180602	Pipe Replaced	3411 HIDALGO DR		Dallas	00000		XXX	XXX
710	Stripped Threads		20180329	Pipe Replaced	12741 HIGH MEADOW DR		Dallas	00000		XXX	XXX
711	Stripped Threads		20180329	Tighten	6715 CHEVY CHASE AVE.		Dallas	00000		XXX	XXX
712	Stripped Threads		20180529	Pipe Replaced	3438 Linda Dr.		Dallas	00000		XXX	XXX
713	Stripped Threads		20180429	Pipe Replaced	6804 WOODLAND DR.		Dallas	00000		Unknown	XXX
714	Stripped Threads		20180430	Pipe Replaced	6730 PARK LN.		Dallas	00000		Unknown	XXX

	L	M	N	O	P	Q	R	S	T	U	V
715	Other Third Party Excavators		20180329	Pipe Replaced	10535 Somerton Dr.		Dallas	00000		XXX	XXX
716	Stripped Threads		20180329	Pipe Replaced	10022 GOODYEAR DR		Dallas	00000		XXX	XXX
717	Corrosion		20180404	Clamp Installed	11128 ABLES LN.		Dallas	00000		XXX	XXX
718	Gasket/O-Ring		20180330	Split Sleeve	4824 RIDGESIDE DR		Dallas	00000		XXX	XXX
719	Gasket/O-Ring		20180510	Pipe Replaced	5922 FOREST LN.		Dallas	00000		Dresser	XXX
720	Corrosion		20180331	Pipe Replaced	6238 Desco Dr		Dallas	00000		XXX	XXX
721	Corrosion		20180430	Clamp Installed	6507 Lupton dr.		Dallas	00000		XXX	XXX
722	Gasket/O-Ring		20180501	Pipe Replaced	5842 BURGUNDY RD		Dallas	00000		XXX	XXX
723	Stripped Threads		20180401	Pipe Replaced	2919 Talisman Dr.		Dallas	00000		XXX	XXX
724	Stripped Threads		20180404	Pipe Replaced	6605 Park Lane		Dallas	00000		XXX	XXX
725	Gasket/O-Ring		20180402	Pipe Replaced	4824 RIDGESIDE DR		Dallas	00000		Unknown	XXX
726	Other	Other	20180410	Pipe Replaced	9421 overlake dr		Dallas	00000		Dresser	XXX
727	Stripped Threads		20180501	Pipe Replaced	6530 Desco Dr		Dallas	00000		Unknown	XXX
728	Corrosion		20180430	Component Replaced	6346 Prestonsire Ln		Dallas	00000		XXX	XXX
729	Stripped Threads		20180428	Pipe Replaced	6723 Lupton		Dallas	00000		XXX	XXX
730	Packing		20180430	Tighten	12555 LOCHMEADOWS DR		Dallas	00000		XXX	XXX
731	Corrosion		20180401	Split Sleeve	12300 Blk Marsh Lane		Dallas	00000		XXX	XXX
732	Stripped Threads		20180411	Pipe Replaced	3611 Ridgebriar Dr		Dallas	00000		XXX	XXX
733	Excessive Strain		20180503	Pipe Replaced	7014 Azalea In		Dallas	00000		XXX	XXX
734	Packing		20180501	Pipe Replaced	5808 Elderwood		Dallas	00000		XXX	XXX
735	Stripped Threads		20180502	Pipe Replaced	4807 TWIN POST RD		Dallas	00000		XXX	XXX
736	Gasket/O-Ring		20180501	Pipe Replaced	4839 RIDGESIDE		Dallas	00000		Dresser	XXX
737	Gasket/O-Ring		20180502	Pipe Replaced	3107 WALNUT HILL LN		Dallas	00000		Dresser	XXX
738	Stripped Threads		20180501	Split Sleeve	12236 cox In		Dallas	00000		Dresser	XXX
739	Stripped Threads		20180517	Split Sleeve	4741 Roxbury		Dallas	00000		Unknown	XXX
740	Stripped Threads		20180528	Split Sleeve	3004 merrell rd		Dallas	00000		Unknown	XXX
741	Weld (Steel)		20180509	Clamp Installed	5916 Saint Mark Cir.		Dallas	00000		XXX	XXX
742	Corrosion		20180510	Pipe Replaced	6615 Northport Dr		Dallas	00000		XXX	XXX
743	Vehicle (Auto/Truck/etc.)		20180223	Greasing	10834 RIDGE SPRING DR		Dallas	00000		XXX	XXX
744	Ground Movement		20180223	Pipe Replaced	2313 Sheridan St.		Dallas	00000		XXX	XXX
745	Gasket/O-Ring		20180311	Pipe Replaced	3825 HALIFAX ST		Dallas	00000		Unknown	XXX
746	Stripped Threads		20180321	Split Sleeve	4605 LA RUE ST.		Dallas	00000		Continental	XXX
747	Stripped Threads		20180323	Pipe Replaced	4673 LA RUE ST.		Dallas	00000		Dresser	XXX
748	Stripped Threads		20180404	Pipe Replaced	2730 WESTERN PARK		Dallas	00000		Unknown	XXX
749	Stripped Threads		20180406	Pipe Replaced	547 SUNBURST DR		Dallas	00000		Unknown	XXX
750	Packing		20180223	Pipe Replaced	E. 8TH & Ewing Ave		Dallas	00000		XXX	XXX
751	Stripped Threads		20180224	Pipe Replaced	6922 WILDGROVE AVE		Dallas	00000		XXX	XXX
752	Corrosion		20180313	Clamp Installed	8507 San Leandro Dr.		Dallas	00000		XXX	XXX
753	Corrosion		20180323	Split Sleeve	8320 COOLGREENE DR		Dallas	00000		XXX	XXX
754	Stripped Threads		20180310	Abandoned	1724 GLENLIVET DR.		Dallas	00000		XXX	XXX
755	Stripped Threads		20180316	Pipe Replaced	3010 Hillglenn Rd		Dallas	00000		Unknown	XXX
756	Stripped Threads		20180324	Pipe Replaced	8634 Tonawanda Dr		Dallas	00000		Unknown	XXX
757	Corrosion		20180322	Pipe Replaced	1719 Houghton Rd		Dallas	00000		XXX	XXX
758	Gasket/O-Ring		20180321	Component Replaced	6107 COPPERHILL DR		Dallas	00000		XXX	XXX
759	Stripped Threads		20180310	Tighten	3234 fairview ave		Dallas	00000		XXX	XXX
760	Ground Movement		20180225	Component Replaced	6261 VELASCO AVE		Dallas	00000		XXX	XXX
761	Packing		20180302	Encapsulation	Westmoreland rd & Shelley Blvd		Dallas	00000		XXX	XXX
762	Stripped Threads		20180224	Abandoned	5959 W Jefferson Blvd		Dallas	00000		XXX	XXX
763	Stripped Threads		20180310	Pipe Replaced	2660 Bruton Springs Dr		Dallas	00000		XXX	XXX
764	Stripped Threads		20180225	Pipe Replaced	422 CLIFFDALE AVE		Dallas	00000		Dresser	XXX
765	Stripped Threads		20180225	Pipe Replaced	10819 LEOTA DR		Dallas	00000		XXX	XXX

	L	M	N	O	P	Q	R	S	T	U	V
766	Stripped Threads		20180627	Pipe Replaced	2336 HILLGLENN RD		Dallas	00000		Unknown	XXX
767	Stripped Threads		20180305	Tighten	9226 ROYALPINE DR		Dallas	00000		XXX	XXX
768	Other Third Party Excavators		20180225	Pipe Replaced	6028 Belmont ave		Dallas	00000		XXX	XXX
769	Stripped Threads		20180226	Pipe Replaced	527 N Saint Augustine Dr		Dallas	00000		XXX	XXX
770	Stripped Threads		20180227	Abandoned	1939 YUCCA DR		Dallas	00000		XXX	XXX
771	Corrosion		20180622	Split Sleeve	1943 TORONTO ST		Dallas	00000		XXX	XXX
772	Stripped Threads		20180315	Pipe Replaced	13231 Kit Ln		Dallas	00000		Unknown	XXX
773	Stripped Threads		20180326	Pipe Replaced	3311 SHADY HOLLOW LN		Dallas	00000		Unknown	XXX
774	Corrosion		20180227	Pipe Replaced	3709 MOUNT PLEASANT ST		Dallas	00000		XXX	XXX
775	Other Third Party Excavators		20180226	Pipe Replaced	1420 GARDENSIDE DR		Dallas	00000		XXX	XXX
776	Stripped Threads		20180226	Pipe Replaced	3006 MOJAVE DR		Dallas	00000		XXX	XXX
777	Stripped Threads		20180226	Pipe Replaced	618 Elston Dr		Dallas	00000		XXX	XXX
778	Gasket/O-Ring		20180226	Split Sleeve	603 OGDEN		Dallas	00000		Unknown	XXX
779	Not Excavated		20180305	Pipe Replaced	6633 EMHOUSE ST		Dallas	00000		XXX	XXX
780	Stripped Threads		20180308	Pipe Replaced	9026 ANACONDA DR		Dallas	00000		XXX	XXX
781	Gasket/O-Ring		20180305	Pipe Replaced	1967 OAK HILL CIRCLE		Dallas	00000		Dresser	XXX
782	Stripped Threads		20180227	Pipe Replaced	BROOKHOLLOW & HARRY HINES BLVD		Dallas	00000		XXX	XXX
783	Stripped Threads		20180322	Tighten	14115 Haymeadow Dr		Dallas	00000		XXX	XXX
784	Corrosion		20180227	Tighten	15626 PRESTON RD		Dallas	00000		XXX	XXX
785	Other Third Party Excavators		20180227	Pipe Replaced	6900 S WESTMORELAND RD		Dallas	00000		XXX	XXX
786	Gasket/O-Ring		20180227	Pipe Replaced	8527 elam heights		Dallas	00000		Unknown	XXX
787	Stripped Threads		20180227	Pipe Replaced	1121 burns ave.		Dallas	00000		XXX	XXX
788	Stripped Threads		20180622	Pipe Replaced	8149 SHAFTER DR		Dallas	00000		Unknown	XXX
789	Corrosion		20180227	Pipe Replaced	15635 RANCHITA DR		Dallas	00000		XXX	XXX
790	Packing		20180621	Encapsulation	915 Lambert St		Dallas	00000		XXX	XXX
791	Backfill		20180322	Component Replaced	4718 CAPITOL AVE		Dallas	00000		XXX	XXX
792	Other Third Party Excavators		20180228	Tighten	7717 Los Alamitos Dr.		Dallas	00000		XXX	XXX
793	Other Third Party Excavators		20180228	Component Replaced	13027 HALWIN		Dallas	00000		XXX	XXX
794	Corrosion		20180301	Abandoned	538 PLEASANT DR		Dallas	00000		XXX	XXX
795	Other Third Party Excavators		20180228	Pipe Replaced	318 CALUMET AVE		Dallas	00000		XXX	XXX
796	Stripped Threads		20180305	Pipe Replaced	11557 Coral Dr		Dallas	00000		XXX	XXX
797	Backfill		20180228	Component Replaced	8928 Jennie Lee LN		Dallas	00000		XXX	XXX
798	Stripped Threads		20180228	Pipe Replaced	1651 CONNER		Dallas	00000		XXX	XXX
799	Stripped Threads		20180301	Pipe Replaced	5603 ARLINGTON PARK DR		Dallas	00000		XXX	XXX
800	Stripped Threads		20180625	Pipe Replaced	8488 SWIFT AVE		Dallas	00000		Unknown	XXX
801	Packing		20180302	Encapsulation	Rosewood Ave & Arroyo Ave		Dallas	00000		XXX	XXX
802	Stripped Threads		20180321	Component Replaced	2433 W FIVE MILE PKWY		Dallas	00000		XXX	XXX
803	Packing		20180319	Greasing	3417 W ILLINOIS		Dallas	00000		XXX	XXX
804	Corrosion		20180301	Tighten	4226 CHANUTE CT		Dallas	00000		XXX	XXX
805	Corrosion		20180302	Clamp Installed	322 N MURDEAUX LN		Dallas	00000		XXX	XXX
806	Excessive Strain		20180305	Abandoned	556 RAYENELL AVE		Dallas	00000		XXX	XXX
807	Other Third Party Excavators		20180301	Pipe Replaced	4649 MOCKINGBIRD LN		Dallas	00000		XXX	XXX
808	Stripped Threads		20180301	Tighten	8318 GROVECREST DR		Dallas	00000		XXX	XXX
809	Stripped Threads		20180302	Pipe Replaced	2320 FATIMA		Dallas	00000		XXX	XXX
810	Stripped Threads		20180404	Tighten	146 Hillburn Dr		Dallas	00000		Unknown	XXX
811	Stripped Threads		20180301	Pipe Replaced	222 N MURDEAUX LN		Dallas	00000		XXX	XXX
812	Fusion Defect (Plastic)		20180301	Component Replaced	PLATINUM WAY & COCKRELL HILL		Dallas	00000		XXX	XXX
813	Gasket/O-Ring		20180301	Pipe Replaced	8612 Woodcastle Dr		Dallas	00000		XXX	XXX
814	Gasket/O-Ring		20180301	Pipe Replaced	8616 woodcastle Dr		Dallas	00000		XXX	XXX
815	Stripped Threads		20180310	Abandoned	9511 CRESTSHIRE DR		Dallas	00000		XXX	XXX
816	Stripped Threads		20180321	Pipe Replaced	3417 Gladiolus Ln		Dallas	00000		Unknown	XXX

	L	M	N	O	P	Q	R	S	T	U	V
817	Stripped Threads		20180321	Split Sleeve	6333 moonglow dr.		Dallas	00000		Unknown	XXX
818	Stripped Threads		20180402	Pipe Replaced	8538 CARDELLA AVE		Dallas	00000		Unknown	XXX
819	Packing		20180314	Encapsulation	3206 MICHIGAN AVE		Dallas	00000		XXX	XXX
820	Corrosion		20180302	Pipe Replaced	2004 HEARNE AVE		Dallas	00000		XXX	XXX
821	Corrosion		20180302	Pipe Replaced	VICEROY DR & KING GEORGE DR		Dallas	00000		XXX	XXX
822	Corrosion		20180308	Split Sleeve	816 Bayonna St		Dallas	00000		XXX	XXX
823	Excessive Strain		20180305	Abandoned	2530 S BUCKNER		Dallas	00000		XXX	XXX
824	Stripped Threads		20180304	Split Sleeve	1248 hartsdale		Dallas	00000		XXX	XXX
825	Stripped Threads		20180304	Split Sleeve	OLD OAKS & W ILLINOIS AVE		Dallas	00000		XXX	XXX
826	Stripped Threads		20180306	Pipe Replaced	2303 Pittman St		Dallas	00000		XXX	XXX
827	Stripped Threads		20180330	Pipe Replaced	5720 margewood dr		Dallas	00000		XXX	XXX
828	Gasket/O-Ring		20180302	Pipe Replaced	3306 TUMALO TRL		Dallas	00000		Unknown	XXX
829	Gasket/O-Ring		20180330	Pipe Replaced	3218 Canada Dr		Dallas	00000		Unknown	XXX
830	Stripped Threads		20180302	Pipe Replaced	2615 DUNREATH DR		Dallas	00000		Unknown	XXX
831	Stripped Threads		20180302	Split Sleeve	2830 Bedford St		Dallas	00000		XXX	XXX
832	Gasket/O-Ring		20180302	Pipe Replaced	10932 RYLIE CREST		Dallas	00000		XXX	XXX
833	Equipment Malfunction		20180306	Pipe Replaced	6843 TRAMMEL DR		Dallas	00000		Unknown	XXX
834	Stripped Threads		20180324	Pipe Replaced	2605 DUNREATH DR		Dallas	00000		Unknown	XXX
835	Stripped Threads		20180331	Pipe Replaced	7155 elmridge		Dallas	00000		Dresser	XXX
836	Packing		20180402	Greasing	9310 HOMEPLACE DR		Dallas	00000		XXX	XXX
837	Stripped Threads		20180306	Tighten	10834 RIDGE SPRING DR		Dallas	00000		XXX	XXX
838	Excessive Strain		20180304	Tighten	131 Edgefield ave		Dallas	00000		XXX	XXX
839	Equipment Malfunction		20180304	Pipe Replaced	1307 N PLYMOUTH RD		Dallas	00000		Unknown	XXX
840	Stripped Threads		20180314	Pipe Replaced	4707 FRANK ST		Dallas	00000		XXX	XXX
841	Stripped Threads		20180322	Pipe Replaced	2719 michigan		Dallas	00000		Unknown	XXX
842	Stripped Threads		20180323	Pipe Replaced	4243 BARKSDALE CT.		Dallas	00000		Unknown	XXX
843	Excessive Strain		20180330	Pipe Replaced	2911 hedgerow		Dallas	00000		XXX	XXX
844	Other Third Party Excavators		20180305	Tighten	2525 w commerce st		Dallas	00000		XXX	XXX
845	Stripped Threads		20180304	Pipe Replaced	2115 Heater Glenn Dr		Dallas	00000		XXX	XXX
846	Stripped Threads		20180304	Pipe Replaced	6139 MOONGLOW DR		Dallas	00000		XXX	XXX
847	Stripped Threads		20180304	Pipe Replaced	6616 RACINE DR		Dallas	00000		XXX	XXX
848	Corrosion		20180307	Pipe Replaced	8 TH ST & EWING AVE		Dallas	00000		XXX	XXX
849	Gasket/O-Ring		20180308	Pipe Replaced	302 N LANCASTER AVE		Dallas	00000		XXX	XXX
850	Other Third Party Excavators		20180305	Pipe Replaced	4001 ROSS AVE		Dallas	00000		XXX	XXX
851	Other Third Party Excavators		20180306	Pipe Replaced	1700 S Akard St		Dallas	00000		XXX	XXX
852	Stripped Threads		20180305	Pipe Replaced	10963 YORKSPRING PL		Dallas	00000		XXX	XXX
853	Stripped Threads		20180305	Pipe Replaced	2615 GUS THOMASSON RD		Dallas	00000		XXX	XXX
854	Corrosion		20180329	Pipe Replaced	2215 volga ave		Dallas	00000		XXX	XXX
855	Stripped Threads		20180307	Pipe Replaced	1307 MOUNTAIN LAKE RD		Dallas	00000		XXX	XXX
856	Corrosion		20180307	Abandoned	2330 wycliff ave.		Dallas	00000		XXX	XXX
857	Gouge		20180306	Clamp Installed	929 N MARSALIS AVE		Dallas	00000		XXX	XXX
858	Other Third Party Excavators		20180306	Abandoned	301 8th st.		Dallas	00000		XXX	XXX
859	Other Third Party Excavators		20180306	Pipe Replaced	323 W 10TH ST		Dallas	00000		XXX	XXX
860	Other Third Party Excavators		20180309	Pipe Replaced	Cockrell Hill @ Division St		Dallas	00000		XXX	XXX
861	Stripped Threads		20180306	Pipe Replaced	4639 INSURANCE LN		Dallas	00000		XXX	XXX
862	Stripped Threads		20180309	Pipe Replaced	4627 N CENTRAL EXPY		Dallas	00000		XXX	XXX
863	Gasket/O-Ring		20180306	Pipe Replaced	3321 PARVIA AVE		Dallas	00000		Unknown	XXX
864	Stripped Threads		20180307	Abandoned	8620 woodcastle dr		Dallas	00000		XXX	XXX
865	Packing		20180326	Encapsulation	1303 Mountain Lake Rd		Dallas	00000		XXX	XXX
866	Stripped Threads		20180307	Tighten	1410 Glen Ave		Dallas	00000		XXX	XXX
867	Corrosion		20180309	Pipe Replaced	815 E HOBSON AVE		Dallas	00000		XXX	XXX

	L	M	N	O	P	Q	R	S	T	U	V
868	Fusion Defect (Plastic)		20180307	Pipe Replaced	10038 LANEYVALE AVE		Dallas	00000		XXX	XXX
869	Other Third Party Excavators		20180307	Pipe Replaced	6526 MALCOLM DR		Dallas	00000		XXX	XXX
870	Other Third Party Excavators		20180307	Pipe Replaced	ARCHER AVE & MEREDITH AVE		Dallas	00000		XXX	XXX
871	Gasket/O-Ring		20180308	Pipe Replaced	714 valencia st		Dallas	00000		Unknown	XXX
872	Stripped Threads		20180307	Clamp Installed	914 n marsalis ave		Dallas	00000		XXX	XXX
873	Stripped Threads		20180307	Pipe Replaced	9216 HIGHRIDGE DR		Dallas	00000		XXX	XXX
874	Corrosion		20180311	Abandoned	1812 summitt		Dallas	00000		XXX	XXX
875	Corrosion		20180502	Split Sleeve	9417 Edgecreek Dr		Dallas	00000		XXX	XXX
876	Gasket/O-Ring		20180310	Pipe Replaced	9415 BOUNDBROOK AVE		Dallas	00000		Dresser	XXX
877	Stripped Threads		20180326	Pipe Replaced	9432 EDGE CREEK DR		Dallas	00000		Unknown	XXX
878	Packing		20180312	Encapsulation	e. tenth and s. ewing		Dallas	00000		XXX	XXX
879	Packing		20180406	Encapsulation	203 e colorado		Dallas	00000		XXX	XXX
880	Corrosion		20180309	Pipe Replaced	6615 MILITARY PKWY		Dallas	00000		XXX	XXX
881	Other Third Party Excavators		20180308	Pipe Replaced	6805 Bert Ln		Dallas	00000		XXX	XXX
882	Stripped Threads		20180308	Clamp Installed	3333 Toronto St		Dallas	00000		XXX	XXX
883	Gasket/O-Ring		20180309	Pipe Replaced	4218 dutton dr		Dallas	00000		Unknown	XXX
884	Stripped Threads		20180308	Pipe Replaced	2717 LARKSPUR LN		Dallas	00000		Unknown	XXX
885	Stripped Threads		20180423	Abandoned	2506 Cedar Crest Blvd		Dallas	00000		XXX	XXX
886	Corrosion		20180320	Split Sleeve	2069 Prichard Ln		Dallas	00000		XXX	XXX
887	Corrosion		20180315	Pipe Replaced	1510 W SANER AVE		Dallas	00000		XXX	XXX
888	Excessive Strain		20180322	Pipe Replaced	3030 aster dr		Dallas	00000		XXX	XXX
889	Packing		20180314	Encapsulation	1125 WAWEENOC AVE		Dallas	00000		XXX	XXX
890	Stripped Threads		20180315	Pipe Replaced	10819 JOAQUIN DR		Dallas	00000		XXX	XXX
891	Stripped Threads		20180328	Encapsulation	5621 ELLSWORTH AVE		Dallas	00000		XXX	XXX
892	Corrosion		20180315	Pipe Replaced	1503 TRANQUILLA DR		Dallas	00000		XXX	XXX
893	Other Third Party Excavators		20180309	Pipe Replaced	5554 HARRY HINES BLVD		Dallas	00000		XXX	XXX
894	Other Third Party Excavators		20180310	Component Replaced	927 Liberty Ct		Dallas	00000		XXX	XXX
895	Stripped Threads		20180309	Pipe Replaced	2330 REXLAWN DR		Dallas	00000		XXX	XXX
896	Packing		20180310	Encapsulation	1906 Boyd st		Dallas	00000		XXX	XXX
897	Stripped Threads		20180309	Abandoned	3107 prosperity ave		Dallas	00000		XXX	XXX
898	Gasket/O-Ring		20180406	Pipe Replaced	7316 MARINGO DR		Dallas	00000		Unknown	XXX
899	Stripped Threads		20180326	Pipe Replaced	1527 Trailridge dr		Dallas	00000		Unknown	XXX
900	Packing		20180329	Encapsulation	1902 BOYD ST		Dallas	00000		XXX	XXX
901	Other Third Party Excavators		20180310	Clamp Installed	s akard & wood st		Dallas	00000		XXX	XXX
902	Gasket/O-Ring		20180312	Pipe Replaced	2817 CHERRY VALLEY BLVD		Dallas	00000		Dresser	XXX
903	Stripped Threads		20180310	Pipe Replaced	8434 CADENZA LN.		Dallas	00000		Other	XXX
904	Stripped Threads		20180326	Pipe Replaced	6529 Putting Green Dr		Dallas	00000		Unknown	XXX
905	Stripped Threads		20180319	Pipe Replaced	6307 Rock Canyon Trl		Dallas	00000		Unknown	XXX
906	Stripped Threads		20180326	Pipe Replaced	2019 CREST RIDGE		Dallas	00000		Unknown	XXX
907	Excessive Strain		20180501	Pipe Replaced	3651 N Buckner Blvd		Dallas	00000		XXX	XXX
908	Other Third Party Excavators		20180312	Abandoned	2622 Martin Luther King Jr. Bl		Dallas	00000		XXX	XXX
909	Other Third Party Excavators		20180312	Clamp Installed	5022 BELMONT		Dallas	00000		XXX	XXX
910	Gasket/O-Ring		20180312	Pipe Replaced	1037 HOKE SMITH DR		Dallas	00000		Dresser	XXX
911	Gasket/O-Ring		20180321	Pipe Replaced	4318 Falls Drive		Dallas	00000		Dresser	XXX
912	Stripped Threads		20180314	Pipe Replaced	812 Glen Oaks blvd		Dallas	00000		Dresser	XXX
913	Corrosion		20180315	Split Sleeve	13428 HUGHES LN.		Dallas	00000		Unknown	XXX
914	Stripped Threads		20180402	Pipe Replaced	5909 MARGEWOOD DR		Dallas	00000		Unknown	XXX
915	Stripped Threads		20180411	Pipe Replaced	3923 Harlingen St		Dallas	00000		XXX	XXX
916	Packing		20180509	Greasing	4000 N WESTMORELAND RD		Dallas	00000		XXX	XXX
917	Corrosion		20180315	Split Sleeve	1439 E KIEST BLVD		Dallas	00000		XXX	XXX
918	Backfill		20180314	Clamp Installed	fernwood and oakley		Dallas	00000		XXX	XXX

	L	M	N	O	P	Q	R	S	T	U	V
919	Corrosion		20180410	Pipe Replaced	812 TENISON MEMORIAL DR		Dallas	00000		XXX	XXX
920	Corrosion		20180413	Pipe Replaced	6823 E GRAND AVE		Dallas	00000		XXX	XXX
921	Stripped Threads		20180313	Pipe Replaced	6148 RICHMOND AVE.		Dallas	00000		Other	XXX
922	Packing		20180314	Encapsulation	1510 Presidio		Dallas	00000		XXX	XXX
923	Packing		20180315	Encapsulation	1507 Presidio Ave.		Dallas	00000		XXX	XXX
924	Other Third Party Excavators		20180314	Tighten	4721 LOMAX DR		Dallas	00000		XXX	XXX
925	Corrosion		20180315	Split Sleeve	HERMOSA DR AND TRANQUILLA DR		Dallas	00000		XXX	XXX
926	Fusion Defect (Plastic)		20180314	Pipe Replaced	1114 E OHIO AVE		Dallas	00000		XXX	XXX
927	Packing		20180314	Greasing	COCKRELL HILL & DAVIS ST		Dallas	00000		XXX	XXX
928	Gasket/O-Ring		20180409	Clamp Installed	W TILDEN ST @ N BECKLEY AVE		Dallas	00000		XXX	XXX
929	Stripped Threads		20180413	Pipe Replaced	2108 HOUSLEY DR		Dallas	00000		XXX	XXX
930	Packing		20180413	Encapsulation	3027 DUTTON DR		Dallas	00000		XXX	XXX
931	Operator Personnel/Contractors Excavating		20180315	Pipe Replaced	5244 FREESTONE CIR		Dallas	00000		XXX	XXX
932	Other Third Party Excavators		20180315	Pipe Replaced	3118 Al lipscomb way		Dallas	00000		XXX	XXX
933	Other Third Party Excavators		20180316	Abandoned	5516 VICKERY BLVD		Dallas	00000		XXX	XXX
934	Equipment Malfunction		20180315	Pipe Replaced	3333 BEAUCHAMP AVE		Dallas	00000		Unknown	XXX
935	Equipment Malfunction		20180315	Pipe Replaced	948 PEAVY DR		Dallas	00000		Dresser	XXX
936	Gasket/O-Ring		20180315	Pipe Replaced	5665 Elm Valley Ln.		Dallas	00000		Unknown	XXX
937	Stripped Threads		20180320	Pipe Replaced	1557 Drury Dr.		Dallas	00000		XXX	XXX
938	Corrosion		20180409	Tighten	5414 richmond ave		Dallas	00000		XXX	XXX
939	Stripped Threads		20180319	Tighten	9933 BURNHAM DR		Dallas	00000		XXX	XXX
940	Excessive Strain		20180410	Encapsulation	733 Rockwood St.		Dallas	00000		XXX	XXX
941	Corrosion		20180416	Pipe Replaced	1536 Oak Vista Dr		Dallas	00000		XXX	XXX
942	Stripped Threads		20180416	Pipe Replaced	1429 Brook Valley Pl.		Dallas	00000		XXX	XXX
943	Other Third Party Excavators		20180316	Tighten	3924 WALDEN WAY		Dallas	00000		XXX	XXX
944	Other Third Party Excavators		20180316	Component Replaced	2214 Michigan ave		Dallas	00000		XXX	XXX
945	Equipment Malfunction		20180317	Pipe Replaced	1438 CONNER DR		Dallas	00000		Unknown	XXX
946	Excessive Strain		20180320	Pipe Replaced	9035 FRINGEWOOD DR		Dallas	00000		XXX	XXX
947	Other Third Party Excavators		20180317	Component Replaced	1723 CENTERVILLE RD		Dallas	00000		XXX	XXX
948	Other Third Party Excavators		20180318	Component Replaced	2421 ROMINE		Dallas	00000		XXX	XXX
949	Stripped Threads		20180320	Abandoned	1126 FRANWOOD DR		Dallas	00000		XXX	XXX
950	Equipment Malfunction		20180317	Pipe Replaced	3512 SHADY HOLLOW LN		Dallas	00000		Unknown	XXX
951	Gasket/O-Ring		20180317	Abandoned	802 MONTE VISTA		Dallas	00000		Unknown	XXX
952	Stripped Threads		20180317	Pipe Replaced	3417 SHADY HOLLOW LN		Dallas	00000		XXX	XXX
953	Corrosion		20180329	Pipe Replaced	7210 Spring Valley Rd		Dallas	00000		XXX	XXX
954	Stripped Threads		20180403	Pipe Replaced	3926 DUTTON DR.		Dallas	00000		Unknown	XXX
955	Corrosion		20180323	Pipe Replaced	2834 Lapsley		Dallas	00000		XXX	XXX
956	Other Third Party Excavators		20180319	Tighten	5452 Anita		Dallas	00000		XXX	XXX
957	Other Third Party Excavators		20180319	Tighten	4001 Ross Ave		Dallas	00000		XXX	XXX
958	Other Third Party Excavators		20180320	Pipe Replaced	8310 SOUTHWESTERN BLVD		Dallas	00000		XXX	XXX
959	Stripped Threads		20180319	Pipe Replaced	902 Claude St		Dallas	00000		XXX	XXX
960	Stripped Threads		20180320	Pipe Replaced	807 Fouraker St		Dallas	00000		XXX	XXX
961	Packing		20180416	Encapsulation	834 Stewart Dr		Dallas	00000		XXX	XXX
962	Stripped Threads		20180331	Pipe Replaced	2735 Magna Vista Dr		Dallas	00000		XXX	XXX
963	Stripped Threads		20180403	Pipe Replaced	1719 ANDREWS ST		Dallas	00000		Unknown	XXX
964	Stripped Threads		20180407	Pipe Replaced	556 Glen Oaks Blvd.		Dallas	00000		Unknown	XXX
965	Stripped Threads		20180321	Pipe Replaced	9934 TANGLEVINE DR		Dallas	00000		XXX	XXX
966	Packing		20180616	Greasing	4406 La Rue Street		Dallas	00000		XXX	XXX
967	Other Third Party Excavators		20180320	Tighten	2634 EASTER AVE		Dallas	00000		XXX	XXX
968	Corrosion		20180320	Split Sleeve	403 N BAGLEY ST		Dallas	00000		XXX	XXX
969	Corrosion		20180411	Pipe Replaced	5106 Singleton Blvd		Dallas	00000		XXX	XXX

	L	M	N	O	P	Q	R	S	T	U	V
970	Ground Movement		20180320	Split Sleeve	TOPEKA & SEALE		Dallas	00000		XXX	XXX
971	Other Third Party Excavators		20180320	Abandoned	2521 Fernwood Ave		Dallas	00000		XXX	XXX
972	Other Third Party Excavators		20180320	Abandoned	381 E Greenbriar Ln		Dallas	00000		XXX	XXX
973	Other Third Party Excavators		20180320	Tighten	4216 BOWSER AVE		Dallas	00000		XXX	XXX
974	Stripped Threads		20180320	Abandoned	5514 Bonita Ave.		Dallas	00000		XXX	XXX
975	Stripped Threads		20180322	Pipe Replaced	4825 TOP LINE DR		Dallas	00000		XXX	XXX
976	Equipment Malfunction		20180324	Pipe Replaced	BEDFORD ST. & BATAAN ST.		Dallas	00000		Unknown	XXX
977	Gasket/O-Ring		20180321	Pipe Replaced	8711 CARDELLA AVE		Dallas	00000		Unknown	XXX
978	Gasket/O-Ring		20180321	Split Sleeve	2609 Parvia		Dallas	00000		Unknown	XXX
979	Stripped Threads		20180320	Pipe Replaced	1215 N Oak Cliff Blvd		Dallas	00000		XXX	XXX
980	Stripped Threads		20180320	Component Replaced	303 N Morocco Ave		Dallas	00000		XXX	XXX
981	Corrosion		20180320	Pipe Replaced	1827 Western Park Drive		Dallas	00000		XXX	XXX
982	Corrosion		20180418	Split Sleeve	2211 SINGLETON BLVD		Dallas	00000		XXX	XXX
983	Stripped Threads		20180418	Abandoned	431 Phinney Ave.		Dallas	00000		XXX	XXX
984	Equipment Malfunction		20180320	Pipe Replaced	4608 Old Spanish Trail		Dallas	00000		Unknown	XXX
985	Gasket/O-Ring		20180412	Pipe Replaced	4705 West Jefferson		Dallas	00000		Unknown	XXX
986	Stripped Threads		20180321	Abandoned	2708 FISH TRAP RD		Dallas	00000		Dresser	XXX
987	Stripped Threads		20180323	Pipe Replaced	4597 La Rue St		Dallas	00000		Dresser	XXX
988	Stripped Threads		20180330	Pipe Replaced	4605 WISTERIA ST		Dallas	00000		Unknown	XXX
989	Stripped Threads		20180405	Pipe Replaced	4526 Baystone Dr		Dallas	00000		Unknown	XXX
990	Stripped Threads		20180405	Pipe Replaced	4554 BAYSTONE DR		Dallas	00000		Unknown	XXX
991	Stripped Threads		20180406	Pipe Replaced	4610 LA RUE ST		Dallas	00000		Unknown	XXX
992	Stripped Threads		20180417	Pipe Replaced	5719 Bluffman Dr		Dallas	00000		XXX	XXX
993	Stripped Threads		20180626	Pipe Replaced	3606 Brandon St		Dallas	00000		XXX	XXX
994	Packing		20180322	Encapsulation	1452 Cedar Hill Ave		Dallas	00000		XXX	XXX
995	Gasket/O-Ring		20180417	Greasing	100 overton rd @ beckley		Dallas	00000		XXX	XXX
996	Backfill		20180321	Pipe Replaced	1023 N Dwight Ave		Dallas	00000		XXX	XXX
997	Dent		20180322	Pipe Replaced	1620 Seale		Dallas	00000		XXX	XXX
998	Other Third Party Excavators		20180321	Pipe Replaced	1940 elderleaf dr		Dallas	00000		XXX	XXX
999	Stripped Threads		20180321	Pipe Replaced	6758 AVALON AVE		Dallas	00000		XXX	XXX
1000	Stripped Threads		20180323	Pipe Replaced	2327 Langford St Rear unit		Dallas	00000		XXX	XXX
1001	Weld (Steel)		20180323	Clamp Installed	700 FABRICATION ST		Dallas	00000		XXX	XXX
1002	Corrosion		20180321	Abandoned	2711 Goldman St		Dallas	00000		Other	XXX
1003	Corrosion		20180322	Pipe Replaced	4444 W Illinois STE 212		Dallas	00000		Dresser	XXX
1004	Equipment Malfunction		20180321	Abandoned	Garfield & Red Bud		Dallas	00000		Normac	XXX
1005	Inadequate/Failure to Follow Procedures		20180323	Pipe Replaced	4411 Bridle Wood		Dallas	00000		Unknown	XXX
1006	Factory Defect		20180325	Pipe Replaced	3306 Glenhaven Blvd		Dallas	00000		XXX	XXX
1007	Gasket/O-Ring		20180326	Tighten	KERNACK ST. & SUNNYSIDE ST.		Dallas	00000		XXX	XXX
1008	Ground Movement		20180321	Abandoned	1402 FORT WORTH AVE		Dallas	00000		XXX	XXX
1009	Packing		20180322	Encapsulation	1400 beckley ave		Dallas	00000		XXX	XXX
1010	Packing		20180517	Encapsulation	1815 Mayflower Dr		Dallas	00000		XXX	XXX
1011	Gasket/O-Ring		20180321	Pipe Replaced	4230 Doves		Dallas	00000		XXX	XXX
1012	Packing		20180321	Component Replaced	232 Yorktown Street		Dallas	00000		XXX	XXX
1013	Stripped Threads		20180322	Pipe Replaced	3937 Dutton Dr		Dallas	00000		XXX	XXX
1014	Stripped Threads		20180323	Component Replaced	4214 Dawes Dr		Dallas	00000		XXX	XXX
1015	Gasket/O-Ring		20180411	Pipe Replaced	Glenhaven and Westmoreland		Dallas	00000		XXX	XXX
1016	Stripped Threads		20180322	Greasing	4340 W Davis St.		Dallas	00000		XXX	XXX
1017	Corrosion		20180410	Split Sleeve	1215 Keats		Dallas	00000		XXX	XXX
1018	Equipment Malfunction		20180325	Pipe Replaced	1715 Neal St.		Dallas	00000		Unknown	XXX
1019	Gasket/O-Ring		20180321	Pipe Replaced	4302 Falls Drive		Dallas	00000		Dresser	XXX
1020	Gasket/O-Ring		20180322	Pipe Replaced	4524 Image Ln		Dallas	00000		Unknown	XXX

	L	M	N	O	P	Q	R	S	T	U	V
1021	Gasket/O-Ring		20180323	Pipe Replaced	1722 kessler Pkwy		Dallas	00000		Unknown	XXX
1022	Gasket/O-Ring		20180323	Pipe Replaced	Remond Dr & Fullerton Dr		Dallas	00000		Unknown	XXX
1023	Gasket/O-Ring		20180413	Pipe Replaced	805 Ever Green Hills Rd.		Dallas	00000		Dresser	XXX
1024	Gasket/O-Ring		20180416	Split Sleeve	4634 Bayview Dr		Dallas	00000		Unknown	XXX
1025	Gasket/O-Ring		20180425	Pipe Replaced	123 S. Bagley		Dallas	00000		Dresser	XXX
1026	Stripped Threads		20180324	Split Sleeve	Avon St & Reverchon Dr		Dallas	00000		Dresser	XXX
1027	Stripped Threads		20180327	Pipe Replaced	Knott PL		Dallas	00000		Dresser	XXX
1028	Stripped Threads		20180330	Pipe Replaced	4687 TIMBERWOOD DR		Dallas	00000		Unknown	XXX
1029	Stripped Threads		20180404	Pipe Replaced	3911 Poinsettia Drive		Dallas	00000		Unknown	XXX
1030	Stripped Threads		20180405	Split Sleeve	4010 MOLER ST.		Dallas	00000		Unknown	XXX
1031	Stripped Threads		20180410	Pipe Replaced	4202 DUTTON DR		Dallas	00000		Unknown	XXX
1032	Stripped Threads		20180411	Pipe Replaced	4322 Dutton Dr		Dallas	00000		Unknown	XXX
1033	Stripped Threads		20180411	Split Sleeve	4674 Old Sanish Trl		Dallas	00000		Unknown	XXX
1034	Stripped Threads		20180412	Pipe Replaced	4011 Poinsettia Dr		Dallas	00000		Unknown	XXX
1035	Stripped Threads		20180412	Pipe Replaced	4319 Dutton Dr		Dallas	00000		Unknown	XXX
1036	Stripped Threads		20180413	Pipe Replaced	4110 Dutton Dr.		Dallas	00000		Unknown	XXX
1037	Stripped Threads		20180416	Pipe Replaced	3609 Poinsettia Dr		Dallas	00000		Unknown	XXX
1038	Stripped Threads		20180416	Pipe Replaced	3614 Dutton Dr		Dallas	00000		Unknown	XXX
1039	Stripped Threads		20180417	Pipe Replaced	4117 June Dr		Dallas	00000		Unknown	XXX
1040	Stripped Threads		20180417	Split Sleeve	3933 FALLS DR.		Dallas	00000		Unknown	XXX
1041	Stripped Threads		20180425	Pipe Replaced	1643 Montclair		Dallas	00000		Unknown	XXX
1042	Gasket/O-Ring		20180412	Encapsulation	819 Ever Green Hills		Dallas	00000		XXX	XXX
1043	Stripped Threads		20180412	Pipe Replaced	705 Archer Ave		Dallas	00000		XXX	XXX
1044	Stripped Threads		20180416	Encapsulation	1452 cedar hill ave		Dallas	00000		XXX	XXX
1045	Stripped Threads		20180416	Pipe Replaced	837 Ever Green Hills Rd.		Dallas	00000		XXX	XXX
1046	Stripped Threads		20180418	Tighten	1151 N. Plymouth Rd		Dallas	00000		XXX	XXX
1047	Stripped Threads		20180425	Abandoned	1022 BAYONNE ST		Dallas	00000		XXX	XXX
1048	Packing		20180416	Encapsulation	7012 Lakeshore Dr.		Dallas	00000		XXX	XXX
1049	Packing		20180420	Encapsulation	1333 Englewood rd		Dallas	00000		XXX	XXX
1050	Stripped Threads		20180411	Split Sleeve	219 S. Justin Ave		Dallas	00000		XXX	XXX
1051	Stripped Threads		20180418	Encapsulation	1435 cedar hill ave		Dallas	00000		XXX	XXX
1052	Stripped Threads		20180420	Split Sleeve	4133 Dutton Dr.		Dallas	00000		XXX	XXX
1053	Corrosion		20180425	Pipe Replaced	701 Ogden		Dallas	00000		XXX	XXX
1054	Gasket/O-Ring		20180321	Pipe Replaced	4234 Doves		Dallas	00000		XXX	XXX
1055	Ground Movement		20180321	Component Replaced	1401 w Commerce St		Dallas	00000		XXX	XXX
1056	Stripped Threads		20180323	Component Replaced	2013 N.Montclar Ave.		Dallas	00000		XXX	XXX
1057	Stripped Threads		20180404	Pipe Replaced	4414 Moler		Dallas	00000		XXX	XXX
1058	Stripped Threads		20180405	Pipe Replaced	3906 Dawes dr		Dallas	00000		XXX	XXX
1059	Stripped Threads		20180410	Pipe Replaced	4218 Dawes Dr		Dallas	00000		XXX	XXX
1060	Stripped Threads		20180411	Pipe Replaced	4533 Lynnacre Cir		Dallas	00000		XXX	XXX
1061	Stripped Threads		20180411	Pipe Replaced	4616 Nettleton		Dallas	00000		XXX	XXX
1062	Stripped Threads		20180412	Pipe Replaced	823 Ever Green Hills Rd.		Dallas	00000		XXX	XXX
1063	Stripped Threads		20180424	Pipe Replaced	11045 CARISSA DR		Dallas	00000		XXX	XXX
1064	Stripped Threads		20180616	Component Replaced	3818 Mt. Ranier		Dallas	00000		XXX	XXX
1065	Corrosion		20180322	Pipe Replaced	4572 briarglen dr		Dallas	00000		XXX	XXX
1066	Ground Movement		20180323	Pipe Replaced	2500 PARVIA AVE		Dallas	00000		XXX	XXX
1067	Stripped Threads		20180322	Pipe Replaced	8344 Waterwood Ln.		Dallas	00000		XXX	XXX
1068	Stripped Threads		20180323	Pipe Replaced	Jacqueline Dr & Fort Worth Ave		Dallas	00000		XXX	XXX
1069	Gasket/O-Ring		20180322	Pipe Replaced	4106 Texas Dr		Dallas	00000		Unknown	XXX
1070	Gasket/O-Ring		20180323	Pipe Replaced	4100 W. Jefferson Blvd		Dallas	00000		Unknown	XXX
1071	Packing		20180322	Encapsulation	5627 MERCEDES AVE		Dallas	00000		XXX	XXX

	L	M	N	O	P	Q	R	S	T	U	V
1072	Corrosion		20180522	Pipe Replaced	2812 sage valley ln		Dallas	00000		XXX	XXX
1073	Excessive Strain		20180420	Pipe Replaced	1810 Winnetka Ave.		Dallas	00000		XXX	XXX
1074	Gasket/O-Ring		20180419	Pipe Replaced	14116 EDGECREST DR		Dallas	00000		XXX	XXX
1075	Packing		20180324	Encapsulation	1052 Kessler Pkwy		Dallas	00000		XXX	XXX
1076	Gasket/O-Ring		20180324	Pipe Replaced	4130 Texas Dr.		Dallas	00000		Unknown	XXX
1077	Other	Other	20180424	Pipe Replaced	1914 Ivanhoe Ln		Dallas	00000		Unknown	XXX
1078	Stripped Threads		20180404	Pipe Replaced	4670 La Rue		Dallas	00000		Unknown	XXX
1079	Stripped Threads		20180404	Pipe Replaced	4679 Baystone		Dallas	00000		Unknown	XXX
1080	Stripped Threads		20180411	Pipe Replaced	4557 wyoming st		Dallas	00000		Unknown	XXX
1081	Stripped Threads		20180412	Pipe Replaced	2976 Reservoir		Dallas	00000		Unknown	XXX
1082	Stripped Threads		20180412	Pipe Replaced	2979 reservoir		Dallas	00000		Unknown	XXX
1083	Stripped Threads		20180416	Pipe Replaced	3615 Poinsetta		Dallas	00000		Unknown	XXX
1084	Excessive Strain		20180425	Pipe Replaced	1823 Akron St.		Dallas	00000		XXX	XXX
1085	Stripped Threads		20180412	Split Sleeve	1903 Ivanhoe Ln		Dallas	00000		XXX	XXX
1086	Stripped Threads		20180413	Pipe Replaced	4639 cedar tone dr		Dallas	00000		XXX	XXX
1087	Gasket/O-Ring		20180413	Encapsulation	3340 Irwindell		Dallas	00000		XXX	XXX
1088	Ground Movement		20180424	Encapsulation	1606 Eastus Dr.		Dallas	00000		XXX	XXX
1089	Packing		20180330	Encapsulation	1322 Kessler Pkwy		Dallas	00000		XXX	XXX
1090	Packing		20180418	Encapsulation	1941 Old Orchard Dr		Dallas	00000		XXX	XXX
1091	Packing		20180418	Encapsulation	4700 blk virginia @ prairie		Dallas	00000		XXX	XXX
1092	Packing		20180419	Encapsulation	1023 N. Plymouth Rd		Dallas	00000		XXX	XXX
1093	Packing		20180424	Encapsulation	5103 live oak		Dallas	00000		XXX	XXX
1094	Packing		20180424	Encapsulation	5907 Oram St.		Dallas	00000		XXX	XXX
1095	Packing		20180511	Encapsulation	6642 LAKESHORE DR		Dallas	00000		XXX	XXX
1096	Packing		20180511	Encapsulation	7234 Lakewood Blvd.		Dallas	00000		XXX	XXX
1097	Stripped Threads		20180419	Encapsulation	1117 N. Plymouth Rd		Dallas	00000		XXX	XXX
1098	Stripped Threads		20180412	Component Replaced	703 N. Dwight Ave.		Dallas	00000		XXX	XXX
1099	Stripped Threads		20180419	Component Replaced	2611 WORTHINGTON		Dallas	00000		XXX	XXX
1100	Stripped Threads		20180428	Pipe Replaced	1623 Eastus Dr.		Dallas	00000		XXX	XXX
1101	Packing		20180420	Greasing	1111 OTT Cir		Dallas	00000		XXX	XXX
1102	Packing		20180616	Greasing	2925 Knoxville		Dallas	00000		XXX	XXX
1103	Corrosion		20180324	Pipe Replaced	5413 N. Arcadia Dr.		Dallas	00000		XXX	XXX
1104	Other Third Party Excavators		20180323	Pipe Replaced	2804 THOMAS AVE		Dallas	00000		XXX	XXX
1105	Other Third Party Excavators		20180324	Pipe Replaced	518 SUNBURST DR		Dallas	00000		XXX	XXX
1106	Stripped Threads		20180323	Abandoned	2429 meyers st		Dallas	00000		XXX	XXX
1107	Gasket/O-Ring		20180324	Pipe Replaced	1400 Walmsley Ave		Dallas	00000		Dresser	XXX
1108	Packing		20180323	Encapsulation	5343 merrimac ave		Dallas	00000		XXX	XXX
1109	Ground Movement		20180325	Pipe Replaced	4687 silver lake dr		Dallas	00000		XXX	XXX
1110	Ground Movement		20180325	Pipe Replaced	4688 timber wood dr		Dallas	00000		XXX	XXX
1111	Not Excavated		20180413	Pipe Replaced	3322 Irwindell		Dallas	00000		XXX	XXX
1112	Stripped Threads		20180331	Pipe Replaced	1235 Hartsdale Dr Dallas, TX		Dallas	00000		XXX	XXX
1113	Stripped Threads		20180411	Pipe Replaced	4516 Ott Circle		Dallas	00000		XXX	XXX
1114	Gasket/O-Ring		20180324	Split Sleeve	905 Gallant Fox Dr		Dallas	00000		Unknown	XXX
1115	Other	Other	20180419	Split Sleeve	1111 Ott Cir.		Dallas	00000		Dresser	XXX
1116	Stripped Threads		20180324	Split Sleeve	2827 LOURDES ST		Dallas	00000		Dresser	XXX
1117	Stripped Threads		20180330	Pipe Replaced	1021 Parlay Cir		Dallas	00000		Unknown	XXX
1118	Stripped Threads		20180330	Pipe Replaced	1025 Parlay Cir		Dallas	00000		Unknown	XXX
1119	Stripped Threads		20180404	Pipe Replaced	4419 Moler		Dallas	00000		Unknown	XXX
1120	Stripped Threads		20180404	Pipe Replaced	4427 Moler		Dallas	00000		Unknown	XXX
1121	Stripped Threads		20180404	Pipe Replaced	4550 western oaks dr		Dallas	00000		Unknown	XXX
1122	Stripped Threads		20180421	Pipe Replaced	3827 Shelley		Dallas	00000		Unknown	XXX

	L	M	N	O	P	Q	R	S	T	U	V
1123	Stripped Threads		20180421	Pipe Replaced	4627 silver lake dr		Dallas	00000		Unknown	XXX
1124	Stripped Threads		20180421	Pipe Replaced	4628 timber wood dr		Dallas	00000		Unknown	XXX
1125	Stripped Threads		20180421	Pipe Replaced	4641 silver lake		Dallas	00000		Unknown	XXX
1126	Stripped Threads		20180421	Pipe Replaced	4660 siver lake dr		Dallas	00000		Unknown	XXX
1127	Stripped Threads		20180424	Pipe Replaced	4133 Shelley Blvd		Dallas	00000		Unknown	XXX
1128	Stripped Threads		20180424	Pipe Replaced	4667 silver lake dr		Dallas	00000		Unknown	XXX
1129	Stripped Threads		20180424	Pipe Replaced	4668 timber wood dr		Dallas	00000		Unknown	XXX
1130	Stripped Threads		20180425	Pipe Replaced	5504 GOODMAN ST		Dallas	00000		Unknown	XXX
1131	Stripped Threads		20180612	Pipe Replaced	3906 Mount Royal st		Dallas	00000		Unknown	XXX
1132	Excessive Strain		20180416	Split Sleeve	4504 Cedar Path Dr		Dallas	00000		XXX	XXX
1133	Ground Movement		20180421	Encapsulation	Colorado Blvd & N Winnetka Ave		Dallas	00000		XXX	XXX
1134	Ground Movement		20180425	Encapsulation	Colorado Blvd & Clinton Ave		Dallas	00000		XXX	XXX
1135	Packing		20180409	Encapsulation	3306 Irwindell		Dallas	00000		XXX	XXX
1136	Packing		20180419	Encapsulation	604 Schooldell Dr		Dallas	00000		XXX	XXX
1137	Stripped Threads		20180425	Split Sleeve	2313 Topeka Ave.		Dallas	00000		XXX	XXX
1138	Corrosion		20180416	Component Replaced	3810 Shelly		Dallas	00000		XXX	XXX
1139	Stripped Threads		20180409	Pipe Replaced	3903 Dawes Dr.		Dallas	00000		XXX	XXX
1140	Corrosion		20180324	Pipe Replaced	8225 GOLDFIELD DR		Dallas	00000		XXX	XXX
1141	Corrosion		20180326	Pipe Replaced	400 blk bagley @ spruce		Dallas	00000		XXX	XXX
1142	Other Third Party Excavators		20180324	Pipe Replaced	403 N WINDOMERE AVE		Dallas	00000		XXX	XXX
1143	Weld (Steel)		20180326	Split Sleeve	5607 Martinez Trail		Dallas	00000		XXX	XXX
1144	Stripped Threads		20180325	Encapsulation	2010 Ivanhoe		Dallas	00000		Dresser	XXX
1145	Stripped Threads		20180328	Pipe Replaced	4107 Meredith Ave		Dallas	00000		Dresser	XXX
1146	Ground Movement		20180331	Pipe Replaced	4681 Timberwood		Dallas	00000		XXX	XXX
1147	Ground Movement		20180325	Pipe Replaced	4617 Timber Wood Dr.		Dallas	00000		XXX	XXX
1148	Stripped Threads		20180517	Pipe Replaced	2000 Blk. W Commerce		Dallas	00000		XXX	XXX
1149	Weld (Steel)		20180413	Pipe Replaced	4678 Timber Wood Dr		Dallas	00000		XXX	XXX
1150	Gasket/O-Ring		20180420	Pipe Replaced	211 n bagley		Dallas	00000		Dresser	XXX
1151	Gasket/O-Ring		20180424	Tighten	115 n justin		Dallas	00000		Dresser	XXX
1152	Stripped Threads		20180326	Pipe Replaced	4637 Timber Wood Dr		Dallas	00000		Unknown	XXX
1153	Stripped Threads		20180404	Pipe Replaced	4641 Timberwood Dr.		Dallas	00000		Dresser	XXX
1154	Stripped Threads		20180412	Pipe Replaced	2930 Reservoir		Dallas	00000		Unknown	XXX
1155	Stripped Threads		20180420	Pipe Replaced	4618 Timber Wood Dr		Dallas	00000		Unknown	XXX
1156	Stripped Threads		20180423	Pipe Replaced	4030 Shelley Blvd		Dallas	00000		Unknown	XXX
1157	Stripped Threads		20180424	Pipe Replaced	4606 Larkhill Dr		Dallas	00000		Unknown	XXX
1158	Stripped Threads		20180424	Pipe Replaced	4657 Silver Lake		Dallas	00000		Unknown	XXX
1159	Stripped Threads		20180424	Pipe Replaced	4658 Timber Wood Dr		Dallas	00000		Unknown	XXX
1160	Stripped Threads		20180424	Pipe Replaced	4661 Silver Lake		Dallas	00000		Unknown	XXX
1161	Stripped Threads		20180425	Pipe Replaced	4642 Timber Wood Dr		Dallas	00000		Unknown	XXX
1162	Backfill		20180420	Component Replaced	718 n bagley		Dallas	00000		XXX	XXX
1163	Stripped Threads		20180412	Pipe Replaced	6126 Keeneland Pkwy		Dallas	00000		XXX	XXX
1164	Stripped Threads		20180325	Pipe Replaced	3830 Dawes Dr		Dallas	00000		XXX	XXX
1165	Stripped Threads		20180406	Pipe Replaced	3914 Dawes Dr.		Dallas	00000		XXX	XXX
1166	Stripped Threads		20180411	Pipe Replaced	4529 Lynnacre Cir		Dallas	00000		XXX	XXX
1167	Stripped Threads		20180412	Pipe Replaced	4553 Lynnacre Cir		Dallas	00000		XXX	XXX
1168	Packing		20180402	Greasing	2450 Knoxville St		Dallas	00000		XXX	XXX
1169	Corrosion		20180325	Clamp Installed	2619 Ingersoll		Dallas	00000		XXX	XXX
1170	Fusion Defect (Plastic)		20180406	Pipe Replaced	Moss Farm Ln @ Abrams Rd		Dallas	00000		XXX	XXX
1171	Stripped Threads		20180325	Abandoned	2550 HUDSPETH AVE		Dallas	00000		XXX	XXX
1172	Equipment Malfunction		20180325	Pipe Replaced	6215 DENHAM DR		Dallas	00000		Unknown	XXX
1173	Stripped Threads		20180326	Tighten	2210 saint germain		Dallas	00000		Unknown	XXX

	L	M	N	O	P	Q	R	S	T	U	V
1174	Gouge		20180326	Abandoned	1308 Singleton Blvd		Dallas	00000		XXX	XXX
1175	Stripped Threads		20180325	Pipe Replaced	2540 Western Park Dr		Dallas	00000		XXX	XXX
1176	Gasket/O-Ring		20180327	Component Replaced	2011 N montclair		Dallas	00000		XXX	XXX
1177	Stripped Threads		20180325	Component Replaced	2439 Jim St		Dallas	00000		XXX	XXX
1178	Corrosion		20180426	Clamp Installed	1200 Ft. Worth Ave		Dallas	00000		XXX	XXX
1179	Corrosion		20180507	Pipe Replaced	5862 BEAU PURPLE DR		Dallas	00000		XXX	XXX
1180	Corrosion		20180517	Pipe Replaced	2102 Ivahoe		Dallas	00000		XXX	XXX
1181	Gasket/O-Ring		20180327	Pipe Replaced	4406 Bridle Wood Dr		Dallas	00000		Unknown	XXX
1182	Gasket/O-Ring		20180423	Pipe Replaced	306 N DWIGHT AVE		Dallas	00000		Dresser	XXX
1183	Gasket/O-Ring		20180423	Pipe Replaced	415 N DWIGHT AVE		Dallas	00000		Dresser	XXX
1184	Stripped Threads		20180425	Pipe Replaced	1631 N. Montclair Ave.		Dallas	00000		Unknown	XXX
1185	Ground Movement		20180327	Pipe Replaced	2540 wood Valley Place		Dallas	00000		XXX	XXX
1186	Stripped Threads		20180416	Tighten	2639 Iroquois		Dallas	00000		XXX	XXX
1187	Dent		20180412	Doped/Caulked	3419 singleton		Dallas	00000		XXX	XXX
1188	Ground Movement		20180424	Encapsulation	921 Kessler Pkwy		Dallas	00000		XXX	XXX
1189	Packing		20180406	Encapsulation	1024 Knott Pl		Dallas	00000		XXX	XXX
1190	Packing		20180428	Encapsulation	1534 Junior Dr		Dallas	00000		XXX	XXX
1191	Corrosion		20180426	Pipe Replaced	1227 S. Westmoreland		Dallas	00000		XXX	XXX
1192	Gasket/O-Ring		20180406	Pipe Replaced	5402 Bernal Dr		Dallas	00000		XXX	XXX
1193	Gasket/O-Ring		20180427	Greasing	4507 Bridle Wood Dr		Dallas	00000		XXX	XXX
1194	Gasket/O-Ring		20180328	Pipe Replaced	414 TIAWAH DR		Dallas	00000		XXX	XXX
1195	Packing		20180326	Encapsulation	5338 Merrimac Ave		Dallas	00000		XXX	XXX
1196	Packing		20180327	Encapsulation	5343 Morningside Ave		Dallas	00000		XXX	XXX
1197	Gasket/O-Ring		20180326	Pipe Replaced	6819 Prosper St.		Dallas	00000		Unknown	XXX
1198	Stripped Threads		20180426	Split Sleeve	4000 BLK FLOYD		Dallas	00000		Dresser	XXX
1199	Stripped Threads		20180430	Pipe Replaced	727 N. HAMPTON RD		Dallas	00000		XXX	XXX
1200	Gasket/O-Ring		20180330	Component Replaced	6620 mattney dr		Dallas	00000		XXX	XXX
1201	Gasket/O-Ring		20180524	Pipe Replaced	EL PASTEL DR.		Dallas	00000		XXX	XXX
1202	Other Third Party Excavators		20180327	Pipe Replaced	3759 Panalero Ln		Dallas	00000		XXX	XXX
1203	Stripped Threads		20180327	Tighten	1600 BLK W BROOKLYN AVE		Dallas	00000		XXX	XXX
1204	Gasket/O-Ring		20180515	Pipe Replaced	3434 W Illinois Ave		Dallas	00000		Dresser	XXX
1205	Packing		20180328	Encapsulation	1200 N PLYMOUTH RD		Dallas	00000		XXX	XXX
1206	Stripped Threads		20180418	Split Sleeve	3932 Shelley		Dallas	00000		XXX	XXX
1207	Stripped Threads		20180427	Pipe Replaced	1736 FORT WORTH AVE		Dallas	00000		Unknown	XXX
1208	Corrosion		20180426	Split Sleeve	3510 Texas Dr		Dallas	00000		XXX	XXX
1209	Stripped Threads		20180426	Tighten	W MAIN ST & PITTMAN ST		Dallas	00000		XXX	XXX
1210	Packing		20180430	Encapsulation	1156 N WINNETKA AVE		Dallas	00000		XXX	XXX
1211	Packing		20180628	Encapsulation	3303 Alaska		Dallas	00000		XXX	XXX
1212	Stripped Threads		20180428	Abandoned	2302 Kathleen Ave		Dallas	00000		XXX	XXX
1213	Gasket/O-Ring		20180416	Greasing	3734 Texas		Dallas	00000		XXX	XXX
1214	Corrosion		20180329	Pipe Replaced	4102 texas Dr		Dallas	00000		XXX	XXX
1215	Gouge		20180411	Tighten	2752 YELLOW JASMINE LN		Dallas	00000		XXX	XXX
1216	Ground Movement		20180328	Pipe Replaced	4104 Texas Dr		Dallas	00000		XXX	XXX
1217	Packing		20180328	Encapsulation	4928 East Side Ave		Dallas	00000		XXX	XXX
1218	Packing		20180404	Encapsulation	5930 Lewis		Dallas	00000		XXX	XXX
1219	Stripped Threads		20180329	Pipe Replaced	8840 BARCLAY ST		Dallas	00000		XXX	XXX
1220	Stripped Threads		20180328	Split Sleeve	4102 Texas Dr		Dallas	00000		Dresser	XXX
1221	Stripped Threads		20180328	Split Sleeve	931 JONELLE		Dallas	00000		Unknown	XXX
1222	Stripped Threads		20180329	Pipe Replaced	1307 S Montreal		Dallas	00000		XXX	XXX
1223	Packing		20180329	Encapsulation	2510 N HENDERSON AVE		Dallas	00000		XXX	XXX
1224	Packing		20180329	Encapsulation	5236 ash ln @ henderson		Dallas	00000		XXX	XXX

	L	M	N	O	P	Q	R	S	T	U	V
1225	Packing		20180403	Encapsulation	209 Winslett		Dallas	00000		XXX	XXX
1226	Packing		20180404	Encapsulation	400 S. Fitzhugh		Dallas	00000		XXX	XXX
1227	Stripped Threads		20180502	Pipe Replaced	5850 La Vista		Dallas	00000		XXX	XXX
1228	Stripped Threads		20180404	Pipe Replaced	2036 SHORTAL ST		Dallas	00000		Unknown	XXX
1229	Stripped Threads		20180402	Pipe Replaced	1306 S Montreal		Dallas	00000		XXX	XXX
1230	Stripped Threads		20180521	Pipe Replaced	4304 FIREBRICK LN.		Dallas	00000		XXX	XXX
1231	Packing		20180329	Encapsulation	1241 Hollywood		Dallas	00000		XXX	XXX
1232	Packing		20180428	Encapsulation	1203 S Montreal		Dallas	00000		XXX	XXX
1233	Packing		20180428	Encapsulation	214 Munger		Dallas	00000		XXX	XXX
1234	Packing		20180428	Encapsulation	3942 East Side Ave.		Dallas	00000		XXX	XXX
1235	Packing		20180501	Encapsulation	4933 Alton		Dallas	00000		XXX	XXX
1236	Packing		20180502	Encapsulation	5403 MERCEDES AVE		Dallas	00000		XXX	XXX
1237	Stripped Threads		20180404	Pipe Replaced	9234 ROLLING ROCK LN		Dallas	00000		XXX	XXX
1238	Corrosion		20180329	Pipe Replaced	343 W MONTANA AVE		Dallas	00000		XXX	XXX
1239	Corrosion		20180330	Abandoned	5928 Richmond Ave		Dallas	00000		XXX	XXX
1240	Other Third Party Excavators		20180329	Pipe Replaced	1011 S AKARD ST		Dallas	00000		XXX	XXX
1241	Other Third Party Excavators		20180329	Pipe Replaced	2640 MORGAN DR		Dallas	00000		XXX	XXX
1242	Other Third Party Excavators		20180329	Pipe Replaced	9850 whitehurst		Dallas	00000		XXX	XXX
1243	Stripped Threads		20180330	Pipe Replaced	5938 Oram		Dallas	00000		XXX	XXX
1244	Stripped Threads		20180330	Pipe Replaced	714 s Acres Dr.		Dallas	00000		XXX	XXX
1245	Gasket/O-Ring		20180428	Pipe Replaced	1715 W Clarendon Dr		Dallas	00000		Dresser	XXX
1246	Gasket/O-Ring		20180428	Pipe Replaced	6425 La Grange Cir		Dallas	00000		Unknown	XXX
1247	Gasket/O-Ring		20180430	Pipe Replaced	5915 oram		Dallas	00000		Dresser	XXX
1248	Gasket/O-Ring		20180501	Encapsulation	5829 PROSPECT AVE		Dallas	00000		XXX	XXX
1249	Gasket/O-Ring		20180502	Pipe Replaced	5908 LA VISTA CT.		Dallas	00000		XXX	XXX
1250	Packing		20180329	Encapsulation	3306 Irwindell		Dallas	00000		XXX	XXX
1251	Packing		20180329	Encapsulation	Westmoreland and Irwindell		Dallas	00000		XXX	XXX
1252	Packing		20180429	Encapsulation	6656 LAKEWOOD		Dallas	00000		XXX	XXX
1253	Packing		20180430	Encapsulation	713 henderson		Dallas	00000		XXX	XXX
1254	Stripped Threads		20180430	Tighten	5918 Prospect Ave		Dallas	00000		XXX	XXX
1255	Other Third Party Excavators		20180330	Component Replaced	3535 DEER MEADOR LN.		Dallas	00000		XXX	XXX
1256	Other Third Party Excavators		20180330	Abandoned	5930 ROSS AVE		Dallas	00000		XXX	XXX
1257	Stripped Threads		20180401	Abandoned	2623 JIM ST		Dallas	00000		XXX	XXX
1258	Packing		20180330	Encapsulation	3600 GARRISON ST		Dallas	00000		XXX	XXX
1259	Packing		20180509	Greasing	3927 N WESTMORELAND RD		Dallas	00000		XXX	XXX
1260	Stripped Threads		20180405	Pipe Replaced	5216 maple springs blvd		Dallas	00000		XXX	XXX
1261	Packing		20180412	Encapsulation	2403 marfa		Dallas	00000		XXX	XXX
1262	Other Third Party Excavators		20180331	Abandoned	9025 COTTONVALLEY RD		Dallas	00000		XXX	XXX
1263	Stripped Threads		20180331	Abandoned	7615 caillet st		Dallas	00000		XXX	XXX
1264	Gasket/O-Ring		20180331	Pipe Replaced	6707 VADA DR		Dallas	00000		Unknown	XXX
1265	Stripped Threads		20180501	Pipe Replaced	917 THELMA ST		Dallas	00000		Unknown	XXX
1266	Stripped Threads		20180407	Pipe Replaced	6711 VADA DR		Dallas	00000		XXX	XXX

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
1	Compression Material	Coupling Installation Date	Pipe Manufacturer	Pipe Type	Pipe Material	Pipe Size	Facility Type	Fitting Type	Joint Type	Report Modified Date
2	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
3	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
4	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
5	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
6	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
7	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
8	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
9	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
10	Steel	19710101	Other	Medium Density Polyethylene	PE 3408	1.00	Service	XXX	XXX	7/13/2018
11	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
12	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
13	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
14	XXX		0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
15	XXX		0 Other	Medium Density Polyethylene	PE 2306	0.75	Service	XXX	XXX	7/13/2018
16	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
17	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
18	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
19	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
20	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
21	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
22	XXX		0 XXX	Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
23	XXX		0 XXX	Coated Steel	XXX	2.00	Service	XXX	XXX	7/13/2018
24	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
25	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
26	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
27	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
28	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
29	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
30	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
31	XXX		0 XXX	Coated Steel	XXX	2.00	Service	XXX	XXX	7/13/2018
32	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
33	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
34	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
35	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	Plugs/Caps	XXX	7/13/2018
36	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Threadolets/Weldolets/Sockolets	XXX	7/13/2018
37	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Threadolets/Weldolets/Sockolets	XXX	7/13/2018
38	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Threadolets/Weldolets/Sockolets	XXX	7/13/2018
39	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
40	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
41	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
42	XXX		0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
43	XXX		0 XXX	Coated Steel	XXX	2.00	Service	XXX	XXX	7/13/2018
44	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
45	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
46	XXX		0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
47	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
48	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
49	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
50	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
51	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
52	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX		7/13/2018
53	XXX		0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
54	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
55	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
56	Steel	19710101	XXX	Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
57	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
58	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
59	XXX		0 XXX	Coated Steel	XXX	8.00	Main	Split Sleeve	XXX	7/13/2018
60	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Union	XXX	7/13/2018
61	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
62	XXX		0 XXX	Coated Steel	XXX	6.00	Main	XXX	XXX	7/13/2018
63	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
64	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
65	XXX		0 Other	Medium Density Polyethylene	Other	1.00	Service	XXX	XXX	7/13/2018
66	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
67	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
68	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
69	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
70	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
71	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
72	Steel	19710101	XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
73	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
74	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
75	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
76	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
77	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
78	XXX		0 XXX	Coated Steel	XXX	0.75	Service	Transition Fitting	Threaded	7/13/2018
79	XXX		0 XXX	Coated Steel	XXX	8.00	Main	Split Sleeve	XXX	7/13/2018
80	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
81	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
82	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
83	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
84	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
85	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
86	XXX		0 XXX	Coated Steel	XXX	2.00	Main	Other	Mechanical Joint	7/13/2018
87	XXX		0 XXX	Bare Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
88	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
89	XXX		0 Other	Medium Density Polyethylene	PE 2406	1.00	Service	XXX	XXX	7/13/2018
90	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
91	XXX		0 XXX	Coated Steel	XXX	3.00	Service	XXX	XXX	7/13/2018
92	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
93	XXX		0 XXX	Bare Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
94	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
95	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
96	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
97	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
98	Steel	19800101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
99	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
100	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
101	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
102	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
103	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
104	XXX		0 XXX	Coated Steel	XXX	3.00	Main	Threadolets/Weldolets/Sockolets	XXX	7/13/2018
105	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
106	XXX		0 XXX	Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
107	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
108	XXX		0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
109	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
110	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
111	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
112	XXX		0 XXX	Coated Steel	XXX	6.00	Main	XXX	XXX	7/13/2018
113	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
114	Plastic	19800101	Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
115	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
116	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
117	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
118	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
119	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
120	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
121	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Service Tee Cap	XXX	7/13/2018
122	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Other	XXX	7/13/2018
123	XXX		0 XXX	Bare Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
124	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
125	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
126	XXX		0 XXX	Bare Steel	XXX	1.00	Service	Plugs/Caps	XXX	7/13/2018
127	XXX		0 XXX	Bare Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
128	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
129	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
130	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
131	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
132	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
133	XXX		0 Other	Medium Density Polyethylene	PE 3408	1.00	Service	XXX	XXX	7/13/2018
134	XXX		0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
135	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
136	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
137	XXX		0 XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
138	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
139	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
140	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
141	XXX		0 Driscopipe	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
142	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
143	Steel	19710101	XXX	Coated Steel	XXX	0.50	Service	XXX	XXX	7/13/2018
144	Steel	19710101	XXX	Bare Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
145	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
146	Steel	19800101	XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
147	XXX		0 Other	Medium Density Polyethylene	PE 3408	1.00	Service	Saddle Fitting	XXX	7/13/2018
148	XXX		0 XXX	Coated Steel	XXX	2.00	Service	Threadolets/Weldolets/Sockolets	XXX	7/13/2018
149	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
150	XXX		0 XXX	Coated Steel	XXX	2.00	Service	Elbow	XXX	7/13/2018
151	XXX		0 XXX	Coated Steel	XXX	2.00	Service	Elbow	XXX	7/13/2018
152	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
153	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
154	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
155	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
156	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
157	XXX		0 XXX	Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
158	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
159	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
160	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
161	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
162	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
163	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
164	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
165	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
166	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
167	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
168	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
169	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
170	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
171	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
172	Steel	19710101	XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
173	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
174	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
175	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
176	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
177	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
178	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
179	XXX		0 Other	Medium Density Polyethylene	PE 3406	0.75	Service	Transition Fitting	XXX	7/13/2018
180	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
181	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
182	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Other	XXX	7/13/2018
183	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Saddle Fitting	XXX	7/13/2018
184	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Service Tee Cap	XXX	7/13/2018
185	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
186	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Saddle Fitting	XXX	7/13/2018
187	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
188	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
189	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
190	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
191	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
192	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
193	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
194	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
195	XXX		0 XXX	Bare Steel	XXX	1.00	Service	Plugs/Caps	XXX	7/13/2018
196	XXX		0 XXX	Coated Steel	XXX	3.00	Main	Threadolets/Weldolets/Sockolets	XXX	7/13/2018
197	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
198	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
199	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
200	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
201	XXX		0 Other	Medium Density Polyethylene	PE 3408	1.00	Service	XXX	XXX	7/13/2018
202	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
203	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
204	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
205	XXX		0 XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
206	XXX		0 XXX	Coated Steel	XXX	2.00	Service	XXX	XXX	7/13/2018
207	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
208	Steel	19710101	XXX	Bare Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
209	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
210	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
211	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
212	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
213	XXX		0 XXX	Coated Steel	XXX	3.00	Main	Elbow	XXX	7/13/2018
214	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
215	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
216	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
217	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
218	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
219	XXX		0 XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
220	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
221	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
222	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
223	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
224	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
225	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
226	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
227	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
228	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
229	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
230	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
231	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
232	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
233	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
234	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
235	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
236	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
237	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
238	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
239	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
240	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
241	XXX		0 XXX	Coated Steel	XXX	6.00	Main	XXX	XXX	7/13/2018
242	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
243	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
244	Steel	19800101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
245	XXX		0 XXX	Coated Steel	XXX	3.00	Main	Other	XXX	7/13/2018
246	XXX		0 XXX	Coated Steel	XXX	0.75	Service	Other	XXX	7/13/2018
247	XXX		0 XXX	Bare Steel	XXX	0.75	Service	Elbow	XXX	7/13/2018
248	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Tee	XXX	7/13/2018
249	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
250	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
251	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
252	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
253	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
254	XXX		0 XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
255	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
256	Steel	19800101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
257	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
258	XXX	0 XXX	XXX	Bare Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
259	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Other	XXX	7/13/2018
260	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Saddle Fitting	XXX	7/13/2018
261	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Saddle Fitting	XXX	7/13/2018
262	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Insulator	XXX	7/13/2018
263	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Saddle Fitting	XXX	7/13/2018
264	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Saddle Fitting	XXX	7/13/2018
265	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Saddle Fitting	XXX	7/13/2018
266	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
267	XXX	0 XXX	XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
268	XXX	0 Other	XXX	Medium Density Polyethylene	Other	1.00	Service	Elbow	XXX	7/13/2018
269	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
270	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
271	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
272	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
273	XXX	0 XXX	XXX	Coated Steel	XXX	2.00	Main	XXX	Field Fillet Weld (Steel)	7/13/2018
274	XXX	0 XXX	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
275	XXX	0 Other	XXX	Medium Density Polyethylene	PE 2306	2.00	Service	XXX	XXX	7/13/2018
276	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
277	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
278	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
279	XXX	0 XXX	XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
280	XXX	0 XXX	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
281	XXX	0 XXX	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
282	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Threadolets/Weldolets/Sockolets	XXX	7/13/2018
283	XXX	0 XXX	XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
284	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
285	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
286	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
287	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
288	XXX	0 XXX	XXX	Coated Steel	XXX	2.00	Service	XXX	XXX	7/13/2018
289	Steel	19710101	XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
290	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
291	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
292	Steel	19710101	XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
293	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
294	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
295	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
296	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Other	XXX	7/13/2018
297	XXX	0 XXX	XXX	Bare Steel	XXX	1.00	Service	Plugs/Caps	XXX	7/13/2018
298	XXX	0 XXX	XXX	Bare Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
299	XXX	0 XXX	XXX	Bare Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
300	XXX	0 XXX	XXX	Bare Steel	XXX	1.00	Service	Plugs/Caps	XXX	7/13/2018
301	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
302	XXX	0 XXX	XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
303	XXX	0 XXX	XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
304	XXX	0 XXX	XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
305	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
306	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
307	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
308	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
309	XXX	0 XXX		Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
310	XXX	0 XXX		Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
311	XXX	0 Other		Medium Density Polyethylene	PE 3408	0.50	Service	XXX	XXX	7/13/2018
312	XXX	0 XXX		Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
313	XXX	0 XXX		Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
314	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
315	XXX	0 XXX		Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
316	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
317	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
318	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
319	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
320	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
321	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
322	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
323	XXX	0 XXX		Coated Steel	XXX	1.00	Service	Other	XXX	7/13/2018
324	XXX	0 Other		Medium Density Polyethylene	PE 2306	0.75	Service	Other	XXX	7/13/2018
325	XXX	0 XXX		Coated Steel	XXX	3.00	Main	Other	XXX	7/13/2018
326	XXX	0 XXX		Coated Steel	XXX	0.50	Service	Threadolets/Weldolets/Sockolets	XXX	7/13/2018
327	XXX	0 XXX		Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
328	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
329	XXX	0 XXX		Bare Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
330	XXX	0 XXX		Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
331	XXX	0 Other		Medium Density Polyethylene	Other	0.75	Service	XXX	XXX	7/13/2018
332	XXX	0 XXX		Coated Steel	XXX	6.00	Main	XXX	XXX	7/13/2018
333	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
334	Steel	19710101	XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
335	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
336	XXX	0 XXX		Coated Steel	XXX	1.00	Service	Union	Threaded	7/13/2018
337	XXX	0 XXX		Coated Steel	XXX	1.00	Service	Other	XXX	7/13/2018
338	XXX	0 XXX		Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
339	XXX	0 XXX		Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
340	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
341	XXX	0 XXX		Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
342	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
343	XXX	0 XXX		Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
344	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
345	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
346	XXX	0 XXX		Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
347	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
348	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
349	Steel	19800101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
350	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
351	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
352	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
353	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
354	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
355	XXX	0 Other		Medium Density Polyethylene	PE 2306	0.75	Service	Elbow	XXX	7/13/2018
356	XXX	0 XXX		Coated Steel	XXX	2.00	Main	Threadolets/Weldolets/Sockolets	XXX	7/13/2018
357	XXX	0 XXX		Coated Steel	XXX	1.00	Service	Other	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
358	XXX		0 XXX	Coated Steel	XXX	0.75	Service	Insulator	XXX	7/13/2018
359	XXX		0 XXX	Coated Steel	XXX	2.00	Main	Other	XXX	7/13/2018
360	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Insulator	XXX	7/13/2018
361	XXX		0 XXX	Bare Steel	XXX	1.00	Service	Plugs/Caps	XXX	7/13/2018
362	XXX		0 XXX	Bare Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
363	XXX		0 XXX	Bare Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
364	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
365	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
366	Steel	19710101	XXX	Bare Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
367	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
368	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
369	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	Plugs/Caps	XXX	7/13/2018
370	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	Mechanical Joint	7/13/2018
371	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
372	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
373	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
374	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
375	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
376	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
377	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
378	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
379	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
380	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
381	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
382	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
383	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
384	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
385	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
386	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
387	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
388	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
389	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Threadolets/Weldolets/Sockolets	XXX	7/13/2018
390	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Insulator	XXX	7/13/2018
391	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
392	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
393	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
394	XXX		0 XXX	Bare Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
395	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
396	XXX		0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
397	XXX		0 Nipak	Medium Density Polyethylene	PE 2406	2.00	Main	XXX	XXX	7/13/2018
398	XXX		0 Driscopipe	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
399	Steel	19800101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
400	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
401	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
402	Steel	19800101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
403	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
404	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Threadolets/Weldolets/Sockolets	XXX	7/13/2018
405	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
406	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
407	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
408	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
409	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
410	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
411	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
412	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
413	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
414	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
415	Steel	19800101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
416	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
417	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
418	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
419	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
420	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
421	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
422	XXX		0 XXX	Coated Steel	XXX	3.00	Main	Nipple	XXX	7/13/2018
423	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
424	XXX		0 XXX	Bare Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
425	XXX		0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
426	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
427	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
428	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
429	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
430	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
431	XXX		0 XXX	Bare Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
432	XXX		0 XXX	Bare Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
433	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
434	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
435	XXX		0 XXX	Coated Steel	XXX	0.50	Service	XXX	XXX	7/13/2018
436	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
437	XXX		0 XXX	Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
438	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
439	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
440	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
441	Plastic	19800101	XXX	Bare Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
442	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
443	XXX		0 XXX	Bare Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
444	XXX		0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
445	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
446	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
447	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
448	XXX		0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
449	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
450	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
451	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
452	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
453	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
454	Plastic	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
455	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
456	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
457	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
458	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
459	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
460	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Other	XXX	7/13/2018
461	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
462	XXX		0 XXX	Bare Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
463	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
464	XXX		0 XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
465	XXX		0 Other	Medium Density Polyethylene	PE 3408	0.75	Service	XXX	XXX	7/13/2018
466	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.50	Service	XXX	XXX	7/13/2018
467	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
468	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
469	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
470	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
471	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
472	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
473	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
474	Steel	19800101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
475	Steel	19800101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
476	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
477	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
478	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
479	XXX		0 XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
480	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
481	XXX		0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
482	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
483	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
484	Steel	19710101	XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
485	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
486	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
487	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
488	XXX		0 XXX	Coated Steel	XXX	2.00	Main	Plugs/Caps	XXX	7/13/2018
489	XXX		0 XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
490	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
491	XXX		0 XXX	Bare Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
492	XXX		0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
493	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
494	XXX		0 XXX	Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
495	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
496	XXX		0 XXX	Bare Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
497	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
498	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
499	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
500	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
501	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
502	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
503	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
504	XXX		0 Other	Medium Density Polyethylene	PE 3408	1.00	Service	XXX	XXX	7/13/2018
505	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
506	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
507	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
508	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
509	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
510	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
511	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
512	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
513	Steel	19710101	XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
514	Steel	19710101	XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
515	Steel	19800101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
516	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
517	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
518	XXX	0 XXX		Bare Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
519	XXX	0 Other		Medium Density Polyethylene	PE 2306	2.00	Service	Nipple	XXX	7/13/2018
520	XXX	0 XXX		Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
521	XXX	0 XXX		Coated Steel	XXX	1.25	Service	Plugs/Caps	XXX	7/13/2018
522	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
523	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
524	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
525	XXX	0 XXX		Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
526	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
527	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
528	Steel	19710101	XXX	Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
529	XXX	0 XXX		Bare Steel	XXX	1.00	Service	Plugs/Caps	XXX	7/13/2018
530	XXX	0 XXX		Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
531	XXX	0 XXX		Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
532	XXX	0 XXX		Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
533	XXX	0 XXX		Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
534	XXX	0 XXX		Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
535	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
536	XXX	0 XXX		Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
537	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
538	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
539	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
540	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
541	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
542	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
543	XXX	0 XXX		Coated Steel	XXX	0.75	Service	Saddle Fitting	XXX	7/13/2018
544	XXX	0 XXX		Coated Steel	XXX	3.00	Main	Split Sleeve	XXX	7/13/2018
545	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
546	XXX	0 XXX		Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
547	XXX	0 XXX		Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
548	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
549	XXX	0 XXX		Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
550	XXX	0 XXX		Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
551	XXX	0 Other		Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
552	XXX	0 XXX		Coated Steel	XXX	0.75	Service	Transition Fitting	XXX	7/13/2018
553	XXX	0 XXX		Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
554	XXX	0 XXX		Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
555	XXX	0 XXX		Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
556	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
557	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
558	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
559	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
560	Steel	19800101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
561	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
562	Steel	19800101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
563	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
564	XXX	0 XXX		Coated Steel	XXX	2.00	Main	Welded Service Tee	XXX	7/13/2018
565	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
566	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
567	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
568	XXX	0 XXX		Coated Steel	XXX	6.00	Main	XXX	XXX	7/13/2018
569	XXX	0 XXX		Bare Steel	XXX	2.00	Service	XXX	XXX	7/13/2018
570	XXX	0 XXX		Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
571	XXX	0 XXX		Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
572	XXX	0 XXX		Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
573	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
574	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
575	Steel	19800101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
576	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
577	XXX	0 XXX		Bare Steel	XXX	1.00	Service	Other	XXX	7/13/2018
578	XXX	0 XXX		Coated Steel	XXX	1.00	Service	Plugs/Caps	XXX	7/13/2018
579	XXX	0 XXX		Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
580	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
581	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
582	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
583	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
584	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
585	Plastic	19710101	Other	Medium Density Polyethylene	PE 2306	0.75	Service	XXX	XXX	7/13/2018
586	XXX	0 XXX		Coated Steel	XXX	2.00	Main	Mechanical Service Tee	XXX	7/13/2018
587	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
588	XXX	0 XXX		Coated Steel	XXX	6.00	Main	XXX	XXX	7/13/2018
589	XXX	0 XXX		Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
590	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
591	Steel	19710101	XXX	Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
592	XXX	0 XXX		Bare Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
593	XXX	0 XXX		Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
594	XXX	0 XXX		Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
595	XXX	0 XXX		Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
596	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
597	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
598	XXX	0 XXX		Coated Steel	XXX	1.00	Service	Other	XXX	7/13/2018
599	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
600	XXX	0 XXX		Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
601	XXX	0 XXX		Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
602	XXX	0 XXX		Bare Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
603	XXX	0 XXX		Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
604	XXX	0 Other		Medium Density Polyethylene	PE 2406	1.25	Service	XXX	XXX	7/13/2018
605	XXX	0 PolyPipe		Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
606	XXX	0 XXX		Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
607	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
608	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
609	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
610	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
611	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
612	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
613	XXX		0 XXX	Coated Steel	XXX	6.00	Main	XXX	Field Butt Weld (Steel)	7/13/2018
614	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
615	XXX		0 XXX	Bare Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
616	XXX		0 XXX	Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
617	XXX		0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
618	Steel		19710101 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
619	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
620	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
621	Steel		19710101 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
622	Steel		19710101 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
623	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Union	XXX	7/13/2018
624	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
625	Steel		19800101 Other	Medium Density Polyethylene	PE 3406	0.75	Service	XXX	XXX	7/13/2018
626	XXX		0 XXX	Coated Steel	XXX	0.75	Service	Nipple	XXX	7/13/2018
627	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.50	Service	XXX	XXX	7/13/2018
628	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Union	XXX	7/13/2018
629	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
630	XXX		0 XXX	Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
631	Steel		19710101 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
632	Steel		19710101 Other	Medium Density Polyethylene	Other	2.00	Service	XXX	XXX	7/13/2018
633	Steel		19710101 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
634	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
635	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
636	Steel		19710101 Other	Medium Density Polyethylene	PE 3406	0.75	Service	XXX	XXX	7/13/2018
637	Plastic		19710101 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
638	Steel		19710101 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
639	Steel		19800101 XXX	Coated Steel	XXX	2.00	Service	XXX	XXX	7/13/2018
640	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Union	XXX	7/13/2018
641	XXX		0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
642	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
643	XXX		0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
644	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
645	XXX		0 Other	Medium Density Polyethylene	PE 2406	2.00	Service	XXX	XXX	7/13/2018
646	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
647	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
648	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
649	XXX		0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
650	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
651	XXX		0 XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
652	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
653	XXX		0 Other	Medium Density Polyethylene	PE 2306	2.00	Main	XXX	XXX	7/13/2018
654	Steel		19710101 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
655	Steel		19710101 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
656	Steel		19800101 Other	Medium Density Polyethylene	PE 2306	0.75	Service	XXX	XXX	7/13/2018
657	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
658	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
659	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
660	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
661	Steel		19710101 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
662	Steel		19710101 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
663	Steel		19710101 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
664	Steel	19800101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
665	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
666	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
667	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
668	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
669	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
670	XXX	0	XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
671	XXX	0	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
672	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
673	XXX	0	XXX	Coated Steel	XXX	1.00	Main	Other	XXX	7/13/2018
674	XXX	0	XXX	Coated Steel	XXX	1.25	Service	Union	XXX	7/13/2018
675	XXX	0	XXX	Coated Steel	XXX	3.00	Main	Nipple	XXX	7/13/2018
676	XXX	0	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
677	XXX	0	Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
678	XXX	0	Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
679	XXX	0	XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
680	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
681	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
682	XXX	0	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
683	XXX	0	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
684	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
685	Steel	19800101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
686	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
687	XXX	0	XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
688	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
689	XXX	0	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
690	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
691	XXX	0	XXX	Coated Steel	XXX	1.00	Service	Union	XXX	7/13/2018
692	XXX	0	XXX	Coated Steel	XXX	0.50	Service	XXX	XXX	7/13/2018
693	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
694	XXX	0	XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
695	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
696	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
697	XXX	0	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
698	XXX	0	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
699	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
700	XXX	0	XXX	Coated Steel	XXX	3.00	Main	Other	XXX	7/13/2018
701	XXX	0	Other	Medium Density Polyethylene	PE 3408	1.00	Service	XXX	XXX	7/13/2018
702	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
703	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
704	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
705	Steel	19710101	Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
706	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
707	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
708	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
709	XXX	0	Other	Medium Density Polyethylene	PE 2406	1.25	Service	XXX	XXX	7/13/2018
710	XXX	0	XXX	Coated Steel	XXX	0.75	Service	Elbow	XXX	7/13/2018
711	XXX	0	XXX	Coated Steel	XXX	1.00	Service	Other	XXX	7/13/2018
712	XXX	0	XXX	Coated Steel	XXX	4.00	Main	Nipple	XXX	7/13/2018
713	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
714	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
715	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
716	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
717	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
718	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
719	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
720	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
721	XXX		0 XXX	Bare Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
722	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
723	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
724	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
725	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
726	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
727	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
728	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
729	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
730	XXX		0 XXX	Bare Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
731	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
732	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
733	XXX		0 Other	Medium Density Polyethylene	PE 3408	1.00	Service	XXX	XXX	7/13/2018
734	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
735	XXX		0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
736	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
737	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
738	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
739	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
740	Steel	19710101	XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
741	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	Field Butt Weld (Steel)	7/13/2018
742	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
743	XXX		0 XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
744	XXX		0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
745	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
746	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
747	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
748	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
749	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
750	XXX		0 XXX	Cast Iron	XXX	4.00	Main	XXX	Bell & Spigot	7/13/2018
751	XXX		0 PolyPipe	Medium Density Polyethylene	PE 2406	1.25	Service	XXX	XXX	7/13/2018
752	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
753	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
754	XXX		0 Other	Medium Density Polyethylene	PE 2306	0.75	Service	XXX	XXX	7/13/2018
755	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
756	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
757	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
758	XXX		0 Other	Medium Density Polyethylene	PE 2306	0.75	Service	XXX	XXX	7/13/2018
759	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
760	XXX		0 PolyPipe	Medium Density Polyethylene	PE 2406	8.00	Main	XXX	XXX	7/13/2018
761	XXX		0 XXX	Cast Iron	XXX	8.00	Main	XXX	XXX	7/13/2018
762	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
763	XXX		0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
764	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
765	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
766	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
767	XXX	0	XXX	Bare Steel	XXX	0.75	Service	Meter Swivel	XXX	7/13/2018
768	XXX	0	Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
769	XXX	0	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
770	XXX	0	XXX	Bare Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
771	XXX	0	XXX	Coated Steel	XXX	1.25	Main	XXX	XXX	7/13/2018
772	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
773	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
774	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
775	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
776	XXX	0	Other	Medium Density Polyethylene	PE 2306	1.25	Service	XXX	XXX	7/13/2018
777	XXX	0	XXX	Bare Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
778	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
779	XXX	0	XXX	Bare Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
780	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
781	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
782	XXX	0	XXX	Coated Steel	XXX	2.00	Service	Threadolets/Weldolets/Sockolets	XXX	7/13/2018
783	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
784	XXX	0	XXX	Bare Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
785	XXX	0	Driscopipe	Medium Density Polyethylene	PE 2406	4.00	Main	XXX	XXX	7/13/2018
786	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
787	XXX	0	XXX	Bare Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
788	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
789	XXX	0	XXX	Coated Steel	XXX	1.25	Service	Anodeless Meter Riser	XXX	7/13/2018
790	XXX	0	XXX	Cast Iron	XXX	4.00	Main	XXX	Mechanical Joint	7/13/2018
791	XXX	0	Other	Medium Density Polyethylene	PE 3408	0.75	Service	XXX	XXX	7/13/2018
792	XXX	0	XXX	Bare Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
793	XXX	0	XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
794	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
795	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
796	XXX	0	XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
797	XXX	0	Other	Medium Density Polyethylene	PE 3408	0.75	Service	Tee	XXX	7/13/2018
798	XXX	0	XXX	Coated Steel	XXX	0.75	Service	Nipple	XXX	7/13/2018
799	XXX	0	XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
800	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
801	XXX	0	XXX	Cast Iron	XXX	4.00	Main	Saddle Fitting	Mechanical Joint	7/13/2018
802	XXX	0	Other	Medium Density Polyethylene	PE 2406	0.50	Service	XXX	XXX	7/13/2018
803	XXX	0	XXX	Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
804	XXX	0	XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
805	XXX	0	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
806	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
807	XXX	0	Other	Medium Density Polyethylene	PE 3408	1.25	Service	XXX	XXX	7/13/2018
808	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
809	XXX	0	XXX	Aldyl Polyethylene	XXX	2.00	Main	XXX	XXX	7/13/2018
810	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
811	XXX	0	XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
812	XXX	0	Other	Medium Density Polyethylene	PE 2306	6.00	Main	XXX	Butt Fusion (Plastic)	7/13/2018
813	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
814	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
815	XXX	0	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
816	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
817	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
818	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
819	XXX	0 XXX	0 XXX	Cast Iron	XXX	4.00	Main	XXX	Mechanical Joint	7/13/2018
820	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
821	XXX	0 XXX	0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
822	XXX	0 XXX	0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
823	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
824	XXX	0 XXX	0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
825	XXX	0 XXX	0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
826	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
827	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
828	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
829	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
830	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
831	XXX	0 XXX	0 XXX	Coated Steel	XXX	2.00	Main	Other	XXX	7/13/2018
832	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
833	Steel	19710101	XXX	Coated Steel	XXX	0.50	Service	XXX	XXX	7/13/2018
834	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
835	Steel	19710101	XXX	Coated Steel	XXX	0.50	Service	XXX	XXX	7/13/2018
836	XXX	0 XXX	0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
837	XXX	0 XXX	0 XXX	Bare Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
838	XXX	0 Other	0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
839	Plastic	19710101	Other	Medium Density Polyethylene	PE 2306	2.00	Main	XXX	XXX	7/13/2018
840	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
841	Plastic	19710101	Other	Medium Density Polyethylene	PE 2306	1.25	Service	XXX	XXX	7/13/2018
842	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
843	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.00	Service	Union	XXX	7/13/2018
844	XXX	0 XXX	0 XXX	Bare Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
845	XXX	0 XXX	0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
846	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
847	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.25	Service	Elbow	XXX	7/13/2018
848	XXX	0 XXX	0 XXX	Cast Iron	XXX	4.00	Main	XXX	XXX	7/13/2018
849	XXX	0 Other	0 Other	Medium Density Polyethylene	PE 2306	2.00	Main	XXX	XXX	7/13/2018
850	XXX	0 Other	0 Other	Medium Density Polyethylene	PE 3408	2.00	Service	XXX	XXX	7/13/2018
851	XXX	0 Other	0 Other	Medium Density Polyethylene	PE 2406	2.00	Main	XXX	XXX	7/13/2018
852	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
853	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
854	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
855	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.25	Service	Elbow	Threaded	7/13/2018
856	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
857	XXX	0 XXX	0 XXX	Cast Iron	XXX	4.00	Main	XXX	XXX	7/13/2018
858	XXX	0 Other	0 Other	Medium Density Polyethylene	PE 2406	1.25	Service	XXX	XXX	7/13/2018
859	XXX	0 Other	0 Other	Medium Density Polyethylene	Other	1.25	Service	XXX	XXX	7/13/2018
860	XXX	0 Other	0 Other	Medium Density Polyethylene	PE 3408	8.00	Main	XXX	XXX	7/13/2018
861	XXX	0 XXX	0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
862	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
863	Steel	19710101	Other	Medium Density Polyethylene	PE 2406	2.00	Main	XXX	XXX	7/13/2018
864	XXX	0 XXX	0 XXX	Coated Steel	XXX	1.00	Service	Other	XXX	7/13/2018
865	XXX	0 XXX	0 XXX	Cast Iron	XXX	4.00	Main	XXX	Mechanical Joint	7/13/2018
866	XXX	0 XXX	0 XXX	Bare Steel	XXX	1.00	Service	Plugs/Caps	XXX	7/13/2018
867	XXX	0 XXX	0 XXX	Cast Iron	XXX	6.00	Main	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
868	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.50	Service	XXX	XXX	7/13/2018
869	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
870	XXX		0 Other	Medium Density Polyethylene	PE 3408	2.00	Main	XXX	XXX	7/13/2018
871	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
872	XXX		0 XXX	Cast Iron	XXX	4.00	Main	Other	XXX	7/13/2018
873	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
874	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
875	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
876	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
877	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
878	XXX		0 XXX	Cast Iron	XXX	6.00	Main	XXX	Mechanical Joint	7/13/2018
879	XXX		0 XXX	Cast Iron	XXX	4.00	Main	XXX	Bell & Spigot	7/13/2018
880	XXX		0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
881	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
882	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
883	Steel	19710101	Other	Medium Density Polyethylene	PE 3408	0.75	Service	XXX	XXX	7/13/2018
884	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
885	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
886	XXX		0 XXX	Coated Steel	XXX	6.00	Main	XXX	XXX	7/13/2018
887	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Welded Service Tee	XXX	7/13/2018
888	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Union	XXX	7/13/2018
889	XXX		0 XXX	Cast Iron	XXX	8.00	Main	Bell Joint Clamp	XXX	7/13/2018
890	XXX		0 XXX	Bare Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
891	XXX		0 XXX	Cast Iron	XXX	4.00	Main	Bell Joint Clamp	XXX	7/13/2018
892	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
893	XXX		0 Other	Medium Density Polyethylene	PE 2406	2.00	Service	XXX	XXX	7/13/2018
894	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
895	XXX		0 Other	Medium Density Polyethylene	PE 3408	1.00	Service	XXX	XXX	7/13/2018
896	XXX		0 XXX	Cast Iron	XXX	4.00	Main	XXX	Bell & Spigot	7/13/2018
897	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
898	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
899	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
900	XXX		0 XXX	Cast Iron	XXX	4.00	Main	XXX	Mechanical Joint	7/13/2018
901	XXX		0 XXX	Bare Steel	XXX	6.00	Main	XXX	XXX	7/13/2018
902	Plastic	19710101	Other	Medium Density Polyethylene	Other	0.50	Service	XXX	XXX	7/13/2018
903	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
904	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
905	Steel	19710101	Other	Medium Density Polyethylene	PE 3408	1.00	Service	XXX	XXX	7/13/2018
906	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
907	XXX		0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
908	XXX		0 Other	Medium Density Polyethylene	PE 3408	0.75	Service	XXX	XXX	7/13/2018
909	XXX		0 XXX	Cast Iron	XXX	1.25	Main	XXX	XXX	7/13/2018
910	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
911	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
912	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
913	Steel	19710101	XXX	Coated Steel	XXX	1.25	Main	XXX	XXX	7/13/2018
914	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
915	XXX		0 XXX	Coated Steel	XXX	0.75	Service	Nipple	XXX	7/13/2018
916	XXX		0 XXX	Coated Steel	XXX	6.00	Main	XXX	XXX	7/13/2018
917	XXX		0 XXX	Coated Steel	XXX	12.0	Main	XXX	XXX	7/13/2018
918	XXX		0 XXX	Cast Iron	XXX	4.00	Main	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
919	XXX		0 XXX	Bare Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
920	XXX		0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
921	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
922	XXX		0 XXX	Cast Iron	XXX	4.00	Main	XXX	Mechanical Joint	7/13/2018
923	XXX		0 XXX	Cast Iron	XXX	4.00	Main	XXX	Mechanical Joint	7/13/2018
924	XXX		0 XXX	Bare Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
925	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
926	XXX		0 Nipak	Medium Density Polyethylene	PE 2406	2.00	Main	XXX	XXX	7/13/2018
927	XXX		0 XXX	Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
928	XXX		0 XXX	Cast Iron	XXX	6.00	Main	Mechanical Service Tee	XXX	7/13/2018
929	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
930	XXX		0 XXX	Cast Iron	XXX	4.00	Main	XXX	Mechanical Joint	7/13/2018
931	XXX		0 Nipak	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
932	XXX		0 Driscopipe	Medium Density Polyethylene	PE 2406	2.00	Main	XXX	XXX	7/13/2018
933	XXX		0 Other	Medium Density Polyethylene	PE 2406	1.25	Service	XXX	XXX	7/13/2018
934	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
935	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
936	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
937	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
938	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
939	XXX		0 Other	Medium Density Polyethylene	PE 2306	3.00	Main	Service Tee Cap	XXX	7/13/2018
940	XXX		0 XXX	Cast Iron	XXX	4.00	Main	XXX	Bell & Spigot	7/13/2018
941	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
942	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
943	XXX		0 XXX	Bare Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
944	XXX		0 Other	Medium Density Polyethylene	PE 2406	1.25	Service	XXX	XXX	7/13/2018
945	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
946	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
947	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
948	XXX		0 Other	Medium Density Polyethylene	PE 2406	1.25	Service	XXX	XXX	7/13/2018
949	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
950	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
951	Steel	19710101	XXX	Coated Steel	XXX	4.00	Service	XXX	XXX	7/13/2018
952	XXX		0 Other	Medium Density Polyethylene	PE 3408	1.00	Service	Nipple	XXX	7/13/2018
953	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
954	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
955	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
956	XXX		0 XXX	Bare Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
957	XXX		0 XXX	Coated Steel	XXX	1.50	Service	XXX	XXX	7/13/2018
958	XXX		0 Other	Medium Density Polyethylene	Other	4.00	Main	XXX	XXX	7/13/2018
959	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
960	XXX		0 XXX	Bare Steel	XXX	1.25	Service	Nipple	XXX	7/13/2018
961	XXX		0 XXX	Cast Iron	XXX	8.00	Main	XXX	XXX	7/13/2018
962	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
963	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
964	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
965	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Elbow	XXX	7/13/2018
966	XXX		0 XXX	Coated Steel	XXX	4.00	Main	XXX	XXX	7/13/2018
967	XXX		0 XXX	Bare Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
968	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
969	XXX		0 XXX	Coated Steel	XXX	6.00	Main	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
970	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
971	XXX		0 Other	Medium Density Polyethylene	PE 2306	0.75	Service	XXX	XXX	7/13/2018
972	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
973	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
974	XXX		0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
975	XXX		0 Other	Medium Density Polyethylene	PE 2406	1.50	Service	XXX	XXX	7/13/2018
976	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
977	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
978	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
979	XXX		0 XXX	Coated Steel	XXX	1.25	Service	Elbow	XXX	7/13/2018
980	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
981	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
982	XXX		0 XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
983	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
984	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
985	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
986	Steel	19710101	XXX	Coated Steel	XXX	2.00	Service	XXX	XXX	7/13/2018
987	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
988	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
989	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
990	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
991	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
992	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	Other	XXX	7/13/2018
993	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
994	XXX		0 XXX	Cast Iron	XXX	6.00	Main	XXX	Bell & Spigot	7/13/2018
995	XXX		0 XXX	Bare Steel	XXX	6.00	Main	XXX	XXX	7/13/2018
996	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
997	XXX		0 Nipak	Medium Density Polyethylene	PE 2306	0.75	Service	XXX	XXX	7/13/2018
998	XXX		0 XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
999	XXX		0 XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
1000	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1001	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1002	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1003	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
1004	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1005	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
1006	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
1007	XXX		0 XXX	Coated Steel	XXX	2.00	Main	Other	XXX	7/13/2018
1008	XXX		0 XXX	Coated Steel	XXX	1.00	Service	Saddle Fitting	XXX	7/13/2018
1009	XXX		0 XXX	Cast Iron	XXX	4.00	Main	XXX	Bell & Spigot	7/13/2018
1010	XXX		0 XXX	Cast Iron	XXX	4.00	Main	XXX	Bell & Spigot	7/13/2018
1011	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
1012	XXX		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
1013	XXX		0 XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1014	XXX		0 Other	Medium Density Polyethylene	PE 2306	1.00	Service	XXX	XXX	7/13/2018
1015	XXX		0 XXX	Coated Steel	XXX	8.00	Main	XXX	XXX	7/13/2018
1016	XXX		0 XXX	Coated Steel	XXX	16.0	Main	XXX	XXX	7/13/2018
1017	XXX		0 XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1018	Steel	19710101	XXX	Coated Steel	XXX	1.50	Main	XXX	XXX	7/13/2018
1019	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1020	Steel	19710101	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
1021	Steel	19800101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1022	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1023	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
1024	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1025	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1026	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1027	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
1028	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1029	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1030	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1031	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1032	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
1033	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1034	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1035	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1036	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1037	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1038	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1039	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1040	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1041	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
1042	XXX	0 XXX	XXX	Cast Iron	XXX	6.00	Main	Bell Joint Clamp	XXX	7/13/2018
1043	XXX	0 XXX	XXX	Coated Steel	XXX	1.25	Service	Elbow	XXX	7/13/2018
1044	XXX	0 XXX	XXX	Cast Iron	XXX	6.00	Main	Bell Joint Clamp	XXX	7/13/2018
1045	XXX	0 XXX	XXX	Coated Steel	XXX	1.25	Service	Elbow	XXX	7/13/2018
1046	XXX	0 XXX	XXX	Cast Iron	XXX	6.00	Main	Leak Clamp	Bell & Spigot	7/13/2018
1047	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	Nipple	XXX	7/13/2018
1048	XXX	0 XXX	XXX	Cast Iron	XXX	8.00	Main	XXX	Bell & Spigot	7/13/2018
1049	XXX	0 XXX	XXX	Cast Iron	XXX	4.00	Main	XXX	Bell & Spigot	7/13/2018
1050	XXX	0 XXX	XXX	Bare Steel	XXX	2.00	Main	XXX	Threaded	7/13/2018
1051	XXX	0 XXX	XXX	Cast Iron	XXX	6.00	Main	XXX	Mechanical Joint	7/13/2018
1052	XXX	0 XXX	XXX	Coated Steel	XXX	2.00	Main	XXX	Threaded	7/13/2018
1053	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1054	XXX	0 Other	XXX	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
1055	XXX	0 XXX	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
1056	XXX	0 Other	XXX	Medium Density Polyethylene	PE 2406	2.00	Service	XXX	XXX	7/13/2018
1057	XXX	0 Other	XXX	Medium Density Polyethylene	PE 2306	0.75	Service	XXX	XXX	7/13/2018
1058	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1059	XXX	0 Other	XXX	Medium Density Polyethylene	PE 2306	1.00	Service	XXX	XXX	7/13/2018
1060	XXX	0 XXX	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
1061	XXX	0 XXX	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
1062	XXX	0 XXX	XXX	Bare Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
1063	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1064	XXX	0 XXX	XXX	Coated Steel	XXX	0.50	Service	XXX	XXX	7/13/2018
1065	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1066	XXX	0 XXX	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1067	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1068	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1069	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1070	Steel	19710101	XXX	Coated Steel	XXX	1.25	Service	XXX	XXX	7/13/2018
1071	XXX	0 XXX	XXX	Cast Iron	XXX	4.00	Main	XXX	Bell & Spigot	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
1072	xxx		0 xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1073	xxx		0 xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1074	xxx		0 xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1075	xxx		0 xxx	Cast Iron	xxx	4.00	Main	xxx	xxx	7/13/2018
1076	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1077	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1078	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1079	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1080	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1081	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1082	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1083	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1084	xxx		0 xxx	Coated Steel	xxx	1.00	Service	Union	xxx	7/13/2018
1085	xxx		0 xxx	Coated Steel	xxx	2.00	Main	Nipple	xxx	7/13/2018
1086	xxx		0 xxx	Coated Steel	xxx	0.75	Service	Other	xxx	7/13/2018
1087	xxx		0 xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1088	xxx		0 xxx	Cast Iron	xxx	6.00	Main	xxx	Bell & Spigot	7/13/2018
1089	xxx		0 xxx	Cast Iron	xxx	6.00	Main	Other	Mechanical Joint	7/13/2018
1090	xxx		0 xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1091	xxx		0 xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1092	xxx		0 xxx	Cast Iron	xxx	6.00	Main	xxx	Bell & Spigot	7/13/2018
1093	xxx		0 xxx	Cast Iron	xxx	6.00	Main	xxx	Bell & Spigot	7/13/2018
1094	xxx		0 xxx	Cast Iron	xxx	6.00	Main	xxx	Bell & Spigot	7/13/2018
1095	xxx		0 xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1096	xxx		0 xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1097	xxx		0 xxx	Cast Iron	xxx	6.00	Main	xxx	Bell & Spigot	7/13/2018
1098	xxx		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	xxx	xxx	7/13/2018
1099	xxx		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	xxx	xxx	7/13/2018
1100	xxx		0 xxx	Bare Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1101	xxx		0 xxx	Coated Steel	xxx	2.00	Main	xxx	xxx	7/13/2018
1102	xxx		0 xxx	Coated Steel	xxx	2.00	Main	xxx	xxx	7/13/2018
1103	xxx		0 xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1104	xxx		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	xxx	xxx	7/13/2018
1105	xxx		0 xxx	Coated Steel	xxx	0.75	Service	xxx	xxx	7/13/2018
1106	xxx		0 xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1107	Steel	19710101	xxx	Coated Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1108	xxx		0 xxx	Cast Iron	xxx	6.00	Main	xxx	Bell & Spigot	7/13/2018
1109	xxx		0 xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1110	xxx		0 xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1111	xxx		0 xxx	Coated Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1112	xxx		0 xxx	Coated Steel	xxx	2.00	Main	xxx	xxx	7/13/2018
1113	xxx		0 xxx	Coated Steel	xxx	0.75	Service	xxx	xxx	7/13/2018
1114	Steel	19710101	xxx	Coated Steel	xxx	2.00	Main	xxx	xxx	7/13/2018
1115	Steel	19710101	xxx	Coated Steel	xxx	3.00	Main	xxx	xxx	7/13/2018
1116	Steel	19710101	xxx	Coated Steel	xxx	2.00	Main	xxx	xxx	7/13/2018
1117	Steel	19710101	xxx	Coated Steel	xxx	0.75	Service	xxx	xxx	7/13/2018
1118	Steel	19710101	xxx	Coated Steel	xxx	0.75	Service	xxx	xxx	7/13/2018
1119	Plastic	19710101	Other	Medium Density Polyethylene	PE 2406	0.75	Service	xxx	xxx	7/13/2018
1120	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1121	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1122	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
1123	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1124	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1125	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1126	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1127	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1128	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1129	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1130	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1131	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1132	XXX	0 XXX	XXX	Coated Steel	XXX	2.00	Main	Union	XXX	7/13/2018
1133	XXX	0 XXX	XXX	Cast Iron	XXX	8.00	Main	XXX	Bell & Spigot	7/13/2018
1134	XXX	0 XXX	XXX	Cast Iron	XXX	6.00	Main	XXX	Bell & Spigot	7/13/2018
1135	XXX	0 XXX	XXX	Cast Iron	XXX	4.00	Main	XXX	Bell & Spigot	7/13/2018
1136	XXX	0 XXX	XXX	Cast Iron	XXX	8.00	Main	XXX	Bell & Spigot	7/13/2018
1137	XXX	0 XXX	XXX	Coated Steel	XXX	2.00	Main	XXX	Threaded	7/13/2018
1138	XXX	0 XXX	XXX	Coated Steel	XXX	0.50	Service	XXX	XXX	7/13/2018
1139	XXX	0 Other	XXX	Medium Density Polyethylene	PE 2306	1.00	Service	XXX	XXX	7/13/2018
1140	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1141	XXX	0 XXX	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1142	XXX	0 PolyPipe	XXX	Medium Density Polyethylene	PE 2406	0.75	Service	XXX	XXX	7/13/2018
1143	XXX	0 XXX	XXX	Coated Steel	XXX	6.00	Main	XXX	XXX	7/13/2018
1144	Steel	19710101	XXX	Bare Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1145	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1146	XXX	0 XXX	XXX	Bare Steel	XXX	1.00	Service	Insulator	XXX	7/13/2018
1147	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1148	XXX	0 XXX	XXX	Bare Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1149	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1150	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1151	Steel	19710101	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1152	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1153	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1154	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1155	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1156	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1157	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1158	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1159	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1160	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1161	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1162	XXX	0 Other	XXX	Medium Density Polyethylene	PE 2306	0.75	Service	Elbow	XXX	7/13/2018
1163	XXX	0 XXX	XXX	Coated Steel	XXX	0.75	Service	Elbow	XXX	7/13/2018
1164	XXX	0 Other	XXX	Medium Density Polyethylene	Other	0.75	Service	XXX	XXX	7/13/2018
1165	XXX	0 XXX	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
1166	XXX	0 XXX	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
1167	XXX	0 XXX	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1168	XXX	0 XXX	XXX	Coated Steel	XXX	3.00	Main	XXX	XXX	7/13/2018
1169	XXX	0 XXX	XXX	Coated Steel	XXX	2.00	Main	XXX	XXX	7/13/2018
1170	XXX	0 Plexco	XXX	Medium Density Polyethylene	PE 2306	4.00	Main	XXX	XXX	7/13/2018
1171	XXX	0 XXX	XXX	Coated Steel	XXX	0.75	Service	XXX	XXX	7/13/2018
1172	Steel	19710101	XXX	Coated Steel	XXX	1.00	Service	XXX	XXX	7/13/2018
1173	Steel	19710101	XXX	Coated Steel	XXX	2.00	Service	XXX	XXX	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF	
1174	xxx		0	Other	Medium Density Polyethylene	PE 2406	1.25	Service	Other	xxx	7/13/2018
1175	xxx		0	xxx	Coated Steel	xxx	1.00	Service	Other	xxx	7/13/2018
1176	xxx		0	Other	Medium Density Polyethylene	PE 2406	0.75	Service	xxx	xxx	7/13/2018
1177	xxx		0	Other	Medium Density Polyethylene	PE 2406	1.00	Service	xxx	xxx	7/13/2018
1178	xxx		0	xxx	Coated Steel	xxx	2.00	Main	xxx	xxx	7/13/2018
1179	xxx		0	xxx	Coated Steel	xxx	6.00	Main	xxx	xxx	7/13/2018
1180	xxx		0	xxx	Coated Steel	xxx	2.00	Main	xxx	xxx	7/13/2018
1181	Steel		19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1182	Steel		19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1183	Steel		19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1184	Steel		19710101	xxx	Coated Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1185	xxx		0	xxx	Coated Steel	xxx	1.00	Service	Saddle Fitting	xxx	7/13/2018
1186	xxx		0	xxx	Coated Steel	xxx	3.00	Main	Nipple	xxx	7/13/2018
1187	xxx		0	xxx	Coated Steel	xxx	12.0	Main	xxx	Field Butt Weld (Steel)	7/13/2018
1188	xxx		0	xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1189	xxx		0	xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1190	xxx		0	xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1191	xxx		0	xxx	Bare Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1192	xxx		0	xxx	Coated Steel	xxx	4.00	Main	xxx	xxx	7/13/2018
1193	xxx		0	xxx	Coated Steel	xxx	4.00	Main	xxx	xxx	7/13/2018
1194	xxx		0	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1195	xxx		0	xxx	Cast Iron	xxx	4.00	Main	xxx	Mechanical Joint	7/13/2018
1196	xxx		0	xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1197	Steel		19710101	xxx	Coated Steel	xxx	0.75	Service	xxx	xxx	7/13/2018
1198	Steel		19710101	xxx	Bare Steel	xxx	16.0	Main	xxx	xxx	7/13/2018
1199	xxx		0	Other	Medium Density Polyethylene	PE 2406	0.75	Service	Other Meter Riser	xxx	7/13/2018
1200	xxx		0	Other	Medium Density Polyethylene	PE 2306	0.75	Service	xxx	xxx	7/13/2018
1201	xxx		0	xxx	Coated Steel	xxx	2.00	Main	xxx	xxx	7/13/2018
1202	xxx		0	Other	Medium Density Polyethylene	PE 3408	0.75	Service	xxx	xxx	7/13/2018
1203	xxx		0	xxx	Coated Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1204	Steel		19710101	xxx	Coated Steel	xxx	2.00	Service	xxx	xxx	7/13/2018
1205	xxx		0	xxx	Cast Iron	xxx	6.00	Main	xxx	Mechanical Joint	7/13/2018
1206	xxx		0	xxx	Coated Steel	xxx	2.00	Main	xxx	xxx	7/13/2018
1207	Steel		19710101	xxx	Coated Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1208	xxx		0	xxx	Coated Steel	xxx	4.00	Main	Leak Clamp	xxx	7/13/2018
1209	xxx		0	xxx	Coated Steel	xxx	2.00	Main	Nipple	xxx	7/13/2018
1210	xxx		0	xxx	Cast Iron	xxx	8.00	Main	xxx	Mechanical Joint	7/13/2018
1211	xxx		0	xxx	Cast Iron	xxx	4.00	Main	xxx	Mechanical Joint	7/13/2018
1212	xxx		0	xxx	Bare Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1213	xxx		0	xxx	Coated Steel	xxx	4.00	Main	xxx	xxx	7/13/2018
1214	xxx		0	xxx	Coated Steel	xxx	2.00	Service	xxx	xxx	7/13/2018
1215	xxx		0	Other	Medium Density Polyethylene	PE 3408	0.75	Service	xxx	xxx	7/13/2018
1216	xxx		0	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1217	xxx		0	xxx	Cast Iron	xxx	4.00	Main	xxx	xxx	7/13/2018
1218	xxx		0	xxx	Cast Iron	xxx	4.00	Main	xxx	xxx	7/13/2018
1219	xxx		0	xxx	Coated Steel	xxx	0.75	Service	xxx	xxx	7/13/2018
1220	Steel		19710101	xxx	Coated Steel	xxx	2.00	Main	xxx	xxx	7/13/2018
1221	Steel		19710101	xxx	Coated Steel	xxx	3.00	Main	xxx	xxx	7/13/2018
1222	xxx		0	xxx	Coated Steel	xxx	1.25	Service	Elbow	xxx	7/13/2018
1223	xxx		0	xxx	Cast Iron	xxx	8.00	Main	xxx	Bell & Spigot	7/13/2018
1224	xxx		0	xxx	Cast Iron	xxx	6.00	Main	xxx	Bell & Spigot	7/13/2018

	W	X	Y	Z	AA	AB	AC	AD	AE	AF
1225	xxx		0 xxx	Cast Iron	xxx	6.00	Main	xxx	Bell & Spigot	7/13/2018
1226	xxx		0 xxx	Cast Iron	xxx	8.00	Main	xxx	Bell & Spigot	7/13/2018
1227	xxx		0 xxx	Coated Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1228	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1229	xxx		0 xxx	Coated Steel	xxx	1.25	Service	Elbow	xxx	7/13/2018
1230	xxx		0 Other	Medium Density Polyethylene	PE 2306	0.75	Service	Nipple	xxx	7/13/2018
1231	xxx		0 xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1232	xxx		0 xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1233	xxx		0 xxx	Cast Iron	xxx	6.00	Main	Bell Joint Clamp	Bell & Spigot	7/13/2018
1234	xxx		0 xxx	Cast Iron	xxx	6.00	Main	xxx	Bell & Spigot	7/13/2018
1235	xxx		0 xxx	Cast Iron	xxx	6.00	Main	xxx	Bell & Spigot	7/13/2018
1236	xxx		0 xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1237	xxx		0 Other	Medium Density Polyethylene	PE 2306	0.75	Service	xxx	xxx	7/13/2018
1238	xxx		0 xxx	Coated Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1239	xxx		0 xxx	Coated Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1240	xxx		0 Driscopipe	Medium Density Polyethylene	PE 2406	2.00	Main	xxx	xxx	7/13/2018
1241	xxx		0 Other	Medium Density Polyethylene	Other	0.75	Service	xxx	xxx	7/13/2018
1242	xxx		0 Other	Medium Density Polyethylene	PE 2306	4.00	Main	xxx	xxx	7/13/2018
1243	xxx		0 xxx	Coated Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1244	xxx		0 xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1245	Steel	19710101	xxx	Bare Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1246	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1247	Steel	19710101	xxx	Coated Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1248	xxx		0 xxx	Cast Iron	xxx	4.00	Main	Leak Clamp	xxx	7/13/2018
1249	xxx		0 xxx	Coated Steel	xxx	2.00	Service	Insulator	xxx	7/13/2018
1250	xxx		0 xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1251	xxx		0 xxx	Cast Iron	xxx	4.00	Main	xxx	Bell & Spigot	7/13/2018
1252	xxx		0 xxx	Cast Iron	xxx	6.00	Main	xxx	Bell & Spigot	7/13/2018
1253	xxx		0 xxx	Cast Iron	xxx	6.00	Main	xxx	Bell & Spigot	7/13/2018
1254	xxx		0 Other	Medium Density Polyethylene	PE 2306	1.00	Service	xxx	xxx	7/13/2018
1255	xxx		0 xxx	Bare Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1256	xxx		0 Other	Medium Density Polyethylene	PE 3408	0.75	Service	xxx	xxx	7/13/2018
1257	xxx		0 xxx	Coated Steel	xxx	0.75	Service	Nipple	xxx	7/13/2018
1258	xxx		0 xxx	Cast Iron	xxx	8.00	Main	xxx	Mechanical Joint	7/13/2018
1259	xxx		0 xxx	Coated Steel	xxx	6.00	Main	xxx	xxx	7/13/2018
1260	xxx		0 xxx	Coated Steel	xxx	1.25	Service	xxx	xxx	7/13/2018
1261	xxx		0 xxx	Cast Iron	xxx	6.00	Main	xxx	Bell & Spigot	7/13/2018
1262	xxx		0 Other	Medium Density Polyethylene	PE 2406	0.75	Service	xxx	xxx	7/13/2018
1263	xxx		0 Other	Medium Density Polyethylene	PE 2406	1.25	Service	xxx	xxx	7/13/2018
1264	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1265	Steel	19710101	xxx	Coated Steel	xxx	1.00	Service	xxx	xxx	7/13/2018
1266	xxx		0 xxx	Coated Steel	xxx	1.00	Service	Nipple	xxx	7/13/2018