

DCA21FA174

POWERPLANTS

Specialist's Factual Report - Attachment 2
Camp Systems EHM Fleet Status Report, June 30, 2021, pgs. 20-21

October 5, 2022

Engine Status For N810TA

Owner	TRANS AIR	Phone		Operator	TRANS AIR	Phone	
Address	P.O. BOX 29239 HONOLULU, HI 96820	Fax		Address	P.O. BOX 29239 HONOLULU, HI 96820	Fax	
Serial/Reg No	21116/N810TA	Model		Manufacturer	PRATT & WHITNEY	InServiceDate	N/A
						Last Actuals:	
						10	HRS as of 30-Oct-2019
						10	AFL as of 30-Oct-2019

ENGINE

1 **PCE-647548** **Overall Engine Status** **Normal**

Current Trend Status

Fault Status

0 Fault Codes Detected in Latest Upload

ENGINE

2 **PCE-657227** **Overall Engine Status** **Normal**

Current Trend Status

Fault Status

0 Fault Codes Detected in Latest Upload

Cruise Trend For N810TA

Engine	ESN	Baseline Date	Last Upload Date	Last Trend Date	Last Review Date	EHM Analyst	Previous Status	Current Trend Status
1	PCE-647548	30-Oct-2019	30-Jun-2021	29-Jun-2021	30-Jun-2021	COLIN DOYLE	✔ Trend Normal	✔ Trend Normal



Engine	ESN	Baseline Date	Last Upload Date	Last Trend Date	Last Review Date	EHM Analyst	Previous Status	Current Trend Status
2	PCE-657227	30-Oct-2019	30-Jun-2021	29-Jun-2021	30-Jun-2021	COLIN DOYLE	✔ Trend Normal	✔ Trend Normal



CAMP Systems (TM) 2016-17
 This report is for information purposes only. CAMP makes no representations or warranties with respect to the information contained herein. It is the sole responsibility of the operator of an aircraft to determine the airworthiness of an engine and dispatchability of an aircraft, in each case in accordance with the requirements of the manufacturer and regulatory authorities.