

#### Bridge Factors Factual Report Attachment 23 – Texts from Mr. Kevin Hanson of Structural Technologies on his mobile device dated March 10, 2018

Miami, FL

**HWY18MH009** 

(8 pages)



3/10/18 6:04 AM

They havent got it in place yet


Almost?


Send me a picture

What time the guys coming?

3/10/18 6:12 AM

Chestor is on the way with equipment and Charles should be there














4 days until someone tags it and 2 weeks before someone falls

Off


3/10/18 9:05 AM

How did it go

Still waiting

Still not in place?



















3/10/18 10:58 AM

What size bar needs to be coupled 1 3/8?

Yes

Chestur has in truck

3/10/18 11:05 AM

Ok

3/10/18 1:32 PM

Everything went







Ok

3/10/18 1:32 PM

Everything went ok

3/10/18 2:00 PM

We are just getting started

3/10/18 3:00 PM

No oil

What kind does it take?

Let me conf 😸







Let me confirm

3/10/18 3:09 PM


Aw32


3/10/18 6:30 PM

We're done

Thank You kev

3/10/18 7:08 PM






















It cracked like hell



















It cracked like hell

3/12/18 8:01 AM

