

October 22, 2014

NTSB Information Request

DCA14MP002 – Harlem, NY

New York City Department of Environmental Protection should provide answers to the following:

1. The construction year of the combined sewer main (32 inch x 48 inch) between 116<sup>th</sup> Street and 117<sup>th</sup> Street, on Park Avenue, Harlem.

**RESPONSE:**

This information was included in the transmittal submitted on April 7, 2014, in response to "Item 5. Records regarding the installation of the main sewer." DEP provided "Map: Inflow and Infiltration Analysis Existing Sewer System – Dated: 3/17/86," which shows the year of installation for this sewer as **1873**.

2. The installation year of the 12 inch cast iron water main between 116<sup>th</sup> Street and 117<sup>th</sup> Street on Park Avenue (incident pipes on March 12, 2014)

**RESPONSE:**

This information was included in the transmittal submitted on April 7, 2014, in response to "Item 8. Records regarding the installation of the water main." DEP provided "Index Card Detailing Location of Water Main records for Park Ave, " which shows the year of construction as **1887**.

3. Provide the detailed construction records to these two utilities. If the records are not available, explain why.

**RESPONSE:**

This information was included in the transmittal submitted on April 7, 2014, in response to "Item 5. Records regarding the installation of the main sewer, "and "Item 8. Records regarding the installation of the water main." DEP does not have additional responsive documents.