



History Details For Locomotive - BNSF 9199 May 18, 2021 to May 19, 2021

BNSF 9199 | HP Actual/Available 4300 4300 | FLY 0.00

Shopping and Servicing Details Field Repairs

Location	Arrival Reason	Work Level Description	Comments	Arrived	Released				
<a href="#">History</a> <a href="#">Work Plan History</a>	M368	Preventive Heavy		5/13/21 09:26:49	5/19/21 05:56:46				
>	200001972232	NSP BNSF 9199 Locomotive Outshop Supervisor	REG	0/70	Deferred				
>	200001972186	SHDF TASK BP08-003 Gear Case Inspection and s	REG	47/102	Completed				
>	200001972905	SHDF Complete BP01-142, exhaust insp/retorque	REG	81/105	Completed				
>	200001972235	NSP BNSF 9199 Wheel Sheet Maintenance Wheel	REG	2/2	Completed				
>	Op No. 0010	Description Initial Wheel Sheet	REG	Start Date 05/19/2021	Tasks 1/1	Track & Spot 008E-8E	Duration 00 H 00 M	Status Completed	Mz
>	Op No. 0020	Description Final Wheel Sheet	REG	Start Date 05/19/2021	Tasks 1/1	Track & Spot 008E-8E	Duration 00 H 00 M	Status Completed	Mz
>	200001972239	NSP BNSF 9199 General Maintenance General Ma	REG	266/266	Completed				
>	200001979913	SHDF #7 P/A C/O IWL BP01-001 Power Assembly C	REG	86/165	Completed				
>	200001996407	SHDF FRONT Coupler Height	REG	1/1	Completed				
>	200001998854	SHDF OOT - BNSF 9199 General Maintenance Gene	REG	1/1	Completed				
>	200001972931	SHDF Complete Roll Check after all wheel chan	REG	27/27	Completed				
>	200001972228	LVL 9 BNSF 9199 AFM Insp AFM Inspection	REG	2/2	Completed				
>	Op No. 0010	Description AFM Calibration	REG	Start Date 05/18/2021	Tasks 2/2	Track & Spot 008E-8E	Duration 00 H 00 M	Status Completed	Mz
>	200001972906	SHDF Complete BP08-002 All wheel change. BP08	REG	76/125	Completed				
>	200001972524	SHDF BNSF 9199 L6R6 Out of tolerance Wheel Wo	REG	1/1	Completed				
>	200001972522	SHDF BNSF 9199 L4R4 Out of tolerance Wheel Wo	REG	1/1	Completed				
>	200001972523	SHDF BNSF 9199 L5R5 Out of tolerance Wheel Wo	REG	1/1	Completed				
>	200001972521	SHDF BNSF 9199 L2R2 Out of tolerance Wheel Wo	REG	1/1	Completed				
>	200001972930	SHDF Complete BP07-245 cool level invalid sta	REG	29/42	Completed				
>	200001972993	SHDF Complete BP11-022, quality outbound insp	REG	10/10	Completed				
>	200001972229	LVL I BNSF 9199 Hand Brake Insp Hand Bra	REG	1/1	Completed				
>	Op No. 0010	Description Perform Hand Brake Inspection	REG	Start Date 05/13/2021	Tasks 1/1	Track & Spot 007W-7W	Duration 01 H 00 M	Status Completed	Mz
>	200001972234	NSP BNSF 9199 FRQ Inspection FRQ with ERI	REG	9/9	Completed				
>	Op No. 0010	Description Federal Inspection tems	REG	Start Date 05/13/2021	Tasks 7/7	Track & Spot 007W-7W	Duration 03 H 00 M	Status Completed	Mz
>	Op No. 0020	Description Level 1 Air Test	REG	Start Date 05/16/2021	Tasks 1/1	Track & Spot 0006-06	Duration 01 H 30 M	Status Completed	Mz
>	Op No. 0030	Description Event Recorder Test	REG	Start Date 05/14/2021	Tasks 1/1	Track & Spot 0006-06	Duration 01 H 00 M	Status Completed	Mz
>	200001973003	SHDF Complete BP07-032 for radar TS BP07-032	REG	35/35	Completed				
>	200001972225	LVL A reported the unit is tripping a PIR mis	REG	1/1	Completed				
>	200001972226	LVL 2 Engine Protection Shut down...DIC...meo	REG	1/1	Completed				
>	200001972227	LVL 8 Cycled the breakers for the 3rd time to	REG	1/1	Completed				
>	200001972963	SHDF Complete BP01-020 for LWSD BP01-020 EUI	REG	79/156	Completed				
>	200001973000	SHDF Complete BP01-019 for LOPS BP01-019 Low	REG	61/125	Completed				
>	200001972751	SHDF IUNSC Defects	REG	28/28	Completed				



History Details For Locomotive - BNSF 9199 May 18, 2021 to May 19, 2021

BNSF 9199 | HP Actual/Available 4300 4300 | FLY 0.00

Shopping and Servicing Details Field Repairs

Location	Arrival Reason	Work Level Description	Comments	Arrived	Released			
<a href="#">History</a> <a href="#">Work Plan History</a>	NORTH (NORTHTOWN, MN)(02438665)	M368	Preventive Heavy					
>	200001972232	NSP	BNSF 9199 Locomotive Outshop Supervisor	REG	0/70	Deferred		
>	200001972186	SHDF	TASK BP08-003 Gear Case Inspection and s	REG	47/102	Completed		
>	200001972905	SHDF	Complete BP01-142, exhaust insp/retorque	REG	81/105	Completed		
>	200001972235	NSP	BNSF 9199 Wheel Sheet Maintenance Wheel	REG	2/2	Completed		
>	200001972239	NSP	BNSF 9199 General Maintenance General Ma	REG	266/266	Completed		
	Op No.	Description	Start Date	Tasks	Track & Spot	Duration	Status	Mz
>	0010	Electrical Inbound REG	05/13/2021	49/49	0006-06	00 H 00 M	Completed	
>	0020	PTC M368 Inspection REG	05/14/2021	16/16	0006-06	04 H 00 M	Completed	
>	0030	Mach Inbound REG	05/18/2021	21/21	008E-8E	00 H 00 M	Completed	
>	0040	Safety Precautions REG	05/13/2021	4/4	007W-7W	01 H 00 M	Completed	
>	0050	MFI REG	05/13/2021	18/18	007W-7W	01 H 00 M	Completed	
>	0060	Mach. Bottoms REG	05/13/2021	25/25	0006-06	00 H 00 M	ReadyToStart	
>	0070	Mach. Tops REG	05/13/2021	39/39	007W-7W	16 H 01 M	Completed	
>	0080	Elec. Bottoms REG	05/13/2021	5/5	0006-06	04 H 27 M	Completed	
>	0090	Elec. Tops REG	05/13/2021	17/17	0006-06	05 H 24 M	Completed	
>	0100	SMW REG	05/13/2021	29/29	0006-06	10 H 10 M	Completed	
>	0110	Performance Based Task REG	05/14/2021	9/9	0006-06	01 H 12 M	Completed	
>	0120	Inhouse Sheet REG	05/13/2021	6/6	0006-06	01 H 00 M	Completed	
>	0130	Outbound REG	05/18/2021	28/28	008E-8E	01 H 00 M	Completed	
>	200001979913	SHDF	#7 P/A C/O IWL BP01-001 Power Assembly C	REG	86/165	Completed		
>	200001996407	SHDF	FRONT Coupler Height	REG	1/1	Completed		
>	200001998854	SHDF	OOT - BNSF 9199 General Maintenance Gene	REG	1/1	Completed		
>	200001972931	SHDF	Complete Roll Check after all wheel chan	REG	27/27	Completed		
>	200001972228	LVL 9	BNSF 9199 AFM Insp AFM Inspection	REG	2/2	Completed		
>	200001972906	SHDF	Complete BP08-002 All wheel change. BP08	REG	76/125	Completed		
>	200001972524	SHDF	BNSF 9199 L6R6 Out of tolerance Wheel Wo	REG	1/1	Completed		
>	200001972522	SHDF	BNSF 9199 L4R4 Out of tolerance Wheel Wo	REG	1/1	Completed		
>	200001972523	SHDF	BNSF 9199 L5R5 Out of tolerance Wheel Wo	REG	1/1	Completed		
>	200001972521	SHDF	BNSF 9199 L2R2 Out of tolerance Wheel Wo	REG	1/1	Completed		
>	200001972930	SHDF	Complete BP07-245 cool level invalid sta	REG	29/42	Completed		
>	200001972993	SHDF	Complete BP11-022, quality outbound insp	REG	10/10	Completed		
>	200001972229	LVL I	BNSF 9199 Hand Brake Insp Hand Bra	REG	1/1	Completed		
>	200001972234	NSP	BNSF 9199 FRQ Inspection FRQ with ERI	REG	9/9	Completed		
>	200001973003	SHDF	Complete BP07-032 for radar TS BP07-032	REG	35/35	Completed		
>	200001972225	LVL A	reported the unit is tripping a PIR mis	REG	1/1	Completed		
>	200001972226	LVL 2	Engine Protection Shut down...DIC...meo	REG	1/1	Completed		
>	200001972227	LVL 8	Cycled the breakers for the 3rd time to	REG	1/1	Completed		
>	200001972963	SHDF	Complete BP01-020 for LWSD BP01-020 EUI	REG	79/156	Completed		
>	200001973000	SHDF	Complete BP01-019 for LOPS BP01-019 Low	REG	61/125	Completed		

## Loco Defects for BNSF 9199

### From 10/30/2021 12:00:00 AM thru 11/24/2021 12:00:00 AM

Note: Blanks in Rprs column indicates an open defect  
 Actn: 1=Replaced 2=Repaired 3=Adjusted 4=No defect found 5=Duplicate 6=Reduced

Defect Date	Lvl	DEFJ C	Loco Init	Loco No	City	Defect	Defective Item	Rprs	Actn	Rpr City	Rpr Date
11/23/2021	8	F016	BNSF	9199	DEAJCT		No Output		2	ALLIANCE	11/27/2021
11/19/2021	1	F026	BNSF	9199	FTWORTH		PAST DUE FRQ		2	ALLIANCE	11/22/2021
11/19/2021	9	F003	BNSF	9199	FTWORTH		PAST DUE AFM		2	ALLIANCE	11/22/2021
11/14/2021	8	F001	BNSF	9199	MONTROSE		High Pressure		2	ALLIANCE	11/22/2021
11/6/2021	9		BNSF	9199	FTWORTH		26 Camera Failure (Overall		2	ALLIANCE	11/8/2021
11/3/2021	9	F004	BNSF	9199	DENVER		Needs Replacement		2	ALLIANCE	11/8/2021
11/1/2021	2	F018	BNSF	9199	DENVER		DWS - Dead Wont Start		2	ALLIANCE	11/8/2021