



Investigative Photographs

**Boise, Idaho
HWY18FH015**

(6 pages)

Photograph 1. Damage sustained to the right side of the 2019 Volvo truck tractor.




Photograph 2. The right front of the 2019 Volvo truck tractor



Photograph 3. The right side of the 2019 Volvo truck tractor.



Photograph 4. The rear of the 2019 Volvo truck-tractor, and the rear of the semitrailer refrigeration unit.



Photograph 5. The remnants of the 2019 Volvo center console.



Photograph 6. The Electronic Control Modules from the center console.



Photograph 7. The transmission Electronic Control Module



Photograph 8 The left side of the 2015 Great Dane semitrailer that was in combination with the 2019 Volvo truck tractor.



Photograph 9. The right side of the 2008 Jeep Wrangler.

