



Highway Factors Photographs

Boise, Idaho

HWY18FH015

(14 pages)



Highway Photo 1 –View of Eastbound I-84 with wreckage behind the tow truck in the number 2 lane where the impact occurred. **Highway photos 1-8 are provided courtesy of the Idaho Highway Patrol**



Highway Photo 2 – Eastbound view of produce from both semi-trailers spilled in the impact lane.



Highway Photo 3 – Additional view of cargo spilled in the impact lane with a view of the damage to the striking semi-trailer.



Highway Photo 4 – View of extensive crushing damage to the red Jeep Wrangler



Highway Photo 5 – Right side view showing the extensive rear and front crushing damage to the Jeep.



Highway Photo 6 – Closer view of the frontal damage to the Jeep



Highway Photo 7 – View of extensive frontal crush to the 2019 Volvo truck tractor



Highway Photo 8 – View of the truck tractor and Jeep after they were pulled apart by tow trucks.



Highway Photo 9 – View of tire friction marks and scrape marks in the number 2 lane. Also note the damage to the bottom of the overhead sign. Photos were taken from the Cloverdale Road overpass.



Highway Photo 10 – Additional view of tire marks and scrapes in the impact lane.



Highway Photo 11 – View of tire marks and pavement scrapes leading to a burned area on the concrete impact lane.



Highway Photo 12 – Additional view looking west in the I-84 eastbound lanes from the Cloverdale overpass. Tire marks and scrapes begin west of the shadow on the pavement formed by the sunlight on the overhead highway sign.



Highway Photo 13 – Eastbound view of I-84 looking east from the Cloverdale overpass. The two, “Left Three Lanes Closed” signs are visible on the shoulders of the highway.