

Bristol and Shalimar Atmospheric Corrosion Reports – 3 cycles

MRU	Installation	Premise	Survey Date	Hs	Street	City	Customer	Atmos Corr	Need Paint	No Issue	Tech	Repair Date
07JA098A	7001565796	700417405	12/9/2023	185	BRISTOL BLVD	Jackson				X	Tech 1	
07JA098A	7001565796	700417405	5/11/2023	185	BRISTOL BLVD	Jackson				X	Tech 2	
07JA098A	7001565796	700417405	6/15/2020	185	BRISTOL BLVD	Jackson				X	Tech 2	
07JA098A	7001565796	700417405	11/13/2017	185	BRISTOL BLVD	Jackson				X	Tech 3	

MRU	Installation	Premise	Survey Date	Hs	Street	City	Customer	Atmos Corr	Need Paint	No Issue	Tech	Repair Date
08JA109H	7001487102	700417045	12/10/2023	1146	SHALIMAR DR	Jackson	Sfr3 Llc			X	Tech 4	
08JA109H	7001487102	700417045	5/15/2023	1146	SHALIMAR DR	Jackson	Sfr3 Llc			X	Tech 5	
08JA109H	7001487102	700417045	6/15/2020	1146	SHALIMAR DR	Jackson	Sfr3 Llc			X	Tech 5	
08JA109H	7001487102	700417045	11/13/2017	1146	SHALIMAR DR	Jackson	Sfr3 Llc			X	Tech 6	