

Specialist's Report – Attachment 6
Young Eagles KRAS Runway 30 Procedure

OPERATIONAL FACTORS

CEN21FA199




Photo 1: Runway 30 flight path (recovered in wreckage on N587CD on April 25, 2021).