

Specialist's Report – Attachment 7
Cirrus SR22 Normal and Emergency Checklists

OPERATIONAL FACTORS

CEN21FA199




Photo 1: Cirrus SR22 Normal Checklists (recovered in N587CD wreckage).




Photo 2: Cirrus SR-22 Emergency checklists (recovered in N587CD wreckage).