

**STATE OF NEW YORK
DEPARTMENT OF PUBLIC SERVICE
16 NYCRR PART 753 CITATION**

Date of Violation: 1/15/2008

Date Issued: 5/21/2008

Company Cited: Consolidated Edison of New York

Address: 30 Flatbush Avenue

City: Brooklyn

State: NY

Zip Code: 11217-

Violation Location: 327 Pennsylvania Avenue

Town: Canarsie

County: Kings (Brooklyn)

Other Party(ies): KeySpan Energy

Damaged Facilities: 1" Service

Method Of Excavation: Backhoe

Description of Project: Electric

Nature of Project:

Private ☐Municipal ☐State ☐Utility ☐

Origin of Investigation:

Directly Reported By:

Emergency Notification ☐Operator ☒Excavator ☐Random ☐Complaint ☐

Effect/Public Health

Safety & Welfare:

Code Section Violated: 3.1(d)

Requirement: Failure to renotify if start date is delayed over ten days.

Remarks: Failure to renotify if start date is delayed over ten days.

Regional ID #

Office ID:

3053

One-Call #

Pictures Taken

☐

Yes

X

No

Booklet Provided:

X

Yes

No

Investigative Report

☐

Yes

X

No

Other Evidence:

DPS
Investigator:

Steve Blaney

Print

Signature

Issued
to:

Print

Signature

Signature acknowledges receipt only and does not constitute an admission to the alleged violation(s).

No response to this citation is required. If you wish to respond, write to the Gas Water Division, New York State Department of Public Service, Three Empire State Plaza, Albany, N.Y. 12223-1350. If the Public Service Commission proposes to determine any penalties for this alleged violation(s), you will be notified by separate letter and provided an opportunity to respond.

Original: Company Cited

Copies: (1) Other Party, (2) Dept. of Public Service Files

**STATE OF NEW YORK
DEPARTMENT OF PUBLIC SERVICE
16 NYCRR PART 753 CITATION**

Date of Violation(s): 6/27/2008Date Issued: 8/25/2008Company Cited: Consolidated Edison Company of New York (CenY), Attn : Pedro CorredorAddress: 118-29 Queens BoulevardCity: Forest Hills, New York CityState: NY Zip Code: 11375Violation Location: 14 Bird LnCity: RyeCounty: WestchesterOther Party(s): Hymon Williams LLC, 502 Broadway, Patterson, NJ - 07501Damaged Facilities: 1 inch plastic service tee to 16 Bird LnMethod of Excavation: Missile (directional drill)Description of Project: Install telephone cableNature of Project: Private ☐ Municipal ☐ State ☐ Utility ☒

Origin of Investigation:	Directly Reported by:		Emergency Notification		<input checked="" type="checkbox"/>
	Operator <input type="checkbox"/>	Excavator <input type="checkbox"/>	Random <input type="checkbox"/>	Complaint	<input type="checkbox"/>

Effect/Public Health	<u>Release of natural gas to atmosphere, evacuation of building and an unscheduled</u>
Safety & Welfare:	<u>interruption of natural gas service to 20 customers</u>

Code Section(s) Violated:	4.6(a)	Requirement:	<u>Accurately locate and mark out operators under-ground facilities within 15 feet of work area.</u>
	&		
	4.6(b)(1)		<u>Provide markings at sufficient intervals.</u>

Remarks: Violation of 753-4.6(a) for failure to mark the service line to 16 Bird Lane.

Violation of 753-4.6(b)(1) for failure to have marks at sufficient intervals as necessary to clearly indicate the direction of run of the gas main, which was in a cul-de-sac. Marks were about 30 feet apart and were not adequate to depict curvature of the main.

Regional ID #	NYC-08-018		
Office ID #	<u>3268 + 3269</u>		
One-Call #	<u>06168-139-081-00</u>		
Pictures Taken	<input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Booklet provided	<input type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Investigative Report	<input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Other Evidence	<u>CenY's damage report</u>		

Suresh Thomas
Print

DPS Investigator: [Signature]
Signature

Issued to: _____
Print

Signature

Signature acknowledges receipt only and does not constitute an admission to the alleged violation(s).

No response to this citation is required. If you wish to respond, write to the Gas & Water Division, New York State Department of Public Service, Three Empire State Plaza, Albany, N.Y. 12223-1350. If the Public Service Commission proposes to determine any penalties for this alleged violation(s), you will be notified by separate letter and provided an opportunity to respond.

Original: Company Cited

Copies: (1) Other Party, (2) Dept. of Public Service Files

**STATE OF NEW YORK
DEPARTMENT OF PUBLIC SERVICE
16 NYCRR PART 753 CITATION**

Date of Violation(s): 8/4/2009

Date Issued: 8/18/2009

Company Cited: Consolidated Edison of New York - Attn: Pete Corredor

Address: 118-29 Queens Boulevard

City: Forest Hills

State: N.Y. Zip Code: 11375

Violation Location: North West corner of Van Buren Street.

City: Staten Island, N.Y.

County: Richmond

Other Party(s): KSE - NYC (Attn: Daniel Hanrahan - 200 Gulf Ave., Staten Island, NY 10303)

Damaged Facilities: 6" High Pressure Medium Density Polyethylene (PE) natural gas main

Method of Excavation: Earth-auger adapted to a Con Edison truck

Description of Project: Excavating to install an electric pole

Nature of Project: Private ☐ Municipal ☐ State ☐ Utility ☒

Origin of Investigation:	Directly Reported by:		Emergency Notification	
	Operator <input checked="" type="checkbox"/>	Excavator <input type="checkbox"/>	Random <input type="checkbox"/>	Complaint <input type="checkbox"/>

Effect/Public Health: Release of natural gas and an unscheduled service interruption.


Safety & Welfare:

Code Section(s) Violated:	753.3.6(b)	Requirement:	"Failed to verify the location of the gas main by means of hand digging within the tolerance zone"
	753.3.6(c)		

Remarks: On 8/04/09, Consolidated Edison damaged a National Grid 6-inch high pressure plastic gas main at approximately 10:00 AM while augering to install an electric pole. During the investigation conducted by National Grid, it was determined that Con Edison failed to verify the location of the gas main by means of hand excavation within the Tolerance Zone.

Regional ID #	NYC-09-011			
Office ID #	3683			
One-Call #	92010439	and	92150155	
Pictures Taken	<input checked="" type="checkbox"/>	Yes	<input type="checkbox"/>	No
Booklet provided	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No
Investigative Report	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No
Other Evidence				

Alma Platero

DPS Investigator: 

Issued to: _____

Signature

Signature acknowledges receipt only and does not constitute an admission to the alleged violation(s).

No response to this citation is required. If you wish to respond, write to the Gas & Water Division, New York State Department of Public Service, Three Empire State Plaza, Albany, N.Y. 12223-1350. If the Public Service Commission proposes to determine any penalties for this alleged violation(s), you will be notified by separate letter and provided an opportunity to respond.

Original: Company Cited

Copies: (1) Other Party, (2) Dept. of Public Service Files

**STATE OF NEW YORK
DEPARTMENT OF PUBLIC SERVICE
16 NYCRR PART 753 CITATION**

Date of Violation(s): 7/15/2010

Date Issued: 7/20/2010

Company Cited: Consolidated Edison Company of New York (CENY), Attn : Pedro Corredor

Address: 118-29 Queens Boulevard

City: Forest Hills, New York City

State: NY Zip Code: 11375

Violation Location: Intersection of Ridgeway Ave & Richbell Road

City: White Plains

County: Westchester

Other Party(s): J. Fletcher Creamer & Son

Damaged Facilities: 6 inch medium pressure plastic gas main

Method of Excavation: Backhoe

Description of Project: Water main rehab

Nature of Project:

Private ☐Municipal ☒State ☐Utility ☐

Origin of Investigation:

Directly Reported by:

Emergency Notification ☒Operator ☐Excavator ☐Random ☐Complaint ☐

Effect/Public Health: Release of natural gas to the atmosphere and an unscheduled interruption of

Safety & Welfare: 35 gas services.

Code Section(s) Violated: 4.6

Requirement:

Accurately locate and mark out operator's
underground facilities within 15 feet of work area.

Remarks: As a result of inaccurate maps, Con Edison failed to accurately locate its 6-inch plastic gas main resulting in a damage and a release of gas and an unscheduled service interruption.

Regional ID #

NYC-10-006

Office ID #

4026

One-Call #

06210-161-082-01& 06210-161-083-01

Pictures Taken

☒

Yes

No

Booklet provided

☐

Yes

☒

No

Investigative Report

☒

Yes

No

Other Evidence

Damage report by Consolidated
Edison Company of New York

DPS

Suresh Thomas

Print

Investigator:

Signature

Issued

Print

to:

Signature

Signature acknowledges receipt only and does not
constitute an admission to the alleged violation(s).

No response to this citation is required. If you wish to respond, write to the Gas & Water Division, New York State Department of Public Service, Three Empire State Plaza, Albany, N.Y. 12223-1350. If the Public Service Commission proposes to determine any penalties for this alleged violation(s), you will be notified by separate letter and provided an opportunity to respond.

Original: Company Cited

Copies: (1) Other Party, (2) Dept. of Public Service Files

**STATE OF NEW YORK
DEPARTMENT OF PUBLIC SERVICE
16 NYCRR PART 753 CITATION**

Date of Violation: 6/10/2011

Date Issued: 10/6/2011

Company Cited: Con Edison

Address: 118-29 Queens Blvd - G3

City: Forest Hills

State: NY

Zip Code: 11375-

Violation Location: 2147 E. 73rd St.

Town: Canarsie

County: Kings (Brooklyn)

Other Party(ies): KeySpan Energy of New York City

Damaged Facilities: 1" Service

Method Of Excavation: Backhoe

Description of Project: Electric

Nature of Project: Private ☐ Municipal ☐ State ☐ Utility ☐

Origin of Investigation:

Directly Reported By:

Emergency Notification ☐Operator ☒Excavator ☐Random ☐Complaint ☐

Effect/Public Health

Safety & Welfare:

Code Section Violated: 3.1(a)(1) Requirement: Failure to provide notice of intent to excavate to the one-call notification system

Remarks: Failure to provide notice of intent to excavate to the one-call notification system

Regional ID #

Office ID: 4457

One-Call #

Pictures Taken

Booklet Provided:

Investigative Report

Other Evidence:

	Yes	X	No
X	Yes		No
	Yes	X	No

DPS
Investigator:

Charles Puglisi

Print

Signature

Issued
to:

Print

Signature

Signature acknowledges receipt only and does not constitute an admission to the alleged violation(s).

No response to this citation is required. If you wish to respond, write to the Gas Water Division, New York State Department of Public Service, Three Empire State Plaza, Albany, N.Y. 12223-1350. If the Public Service Commission proposes to determine any penalties for this alleged violation(s), you will be notified by separate letter and provided an opportunity to respond.

Original: Company Cited

Copies: (1) Other Party, (2) Dept. of Public Service Files

**STATE OF NEW YORK
DEPARTMENT OF PUBLIC SERVICE
16 NYCRR PART 753 CITATION**

Date of Violation(s): 11/18/2011

Date Issued: 12/15/2011

Company Cited: Consolidated Edison Company of New York (CECONY), Attn: Pedro Corredor

Address: 118-29 Queens Boulevard

City: Forest Hills, New York City

State: NY Zip Code: 11375

Violation Location: 1434 Pleasantville Road

City: Briarcliff Manor

County: Westchester

Other Party(s): Consolidated Edison Company of New York - Electric operations

Damaged Facilities: 4-inch plastic high pressure gas main

Method of Excavation: Auger

Description of Project: Installing utility pole

Nature of Project:

Private ☐Municipal ☐State ☐Utility ☒

Origin of Investigation:

Directly Reported by:

Emergency Notification ☒Operator ☐Excavator ☐Random ☐Complaint ☐Effect/Public Health: Unscheduled release of natural gas to atmosphere and interruption of gas service toSafety & Welfare: 5 customers.Code Section(s) Violated: 4.6Requirement: Accurately locate and mark out underground facilities within 15 feet of work area.Remarks: CECONY's damage report indicates that the marks were inaccurate and outside the tolerance zone.The mark outs were approximately 3 feet outside of the tolerance zone.

Regional ID #	NYC-11-021			
Office ID #				
One-Call #	1181-134-002-00			
Pictures Taken	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No
Booklet provided	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	No
Investigative Report	<input checked="" type="checkbox"/>	Yes	<input type="checkbox"/>	No
Other Evidence	CECONY'S Damage Report			

Arpit Mehta

DPS Investigator: [Signature]

Issued to: [Signature]

Signature acknowledges receipt only and does not constitute an admission to the alleged violation(s).

No response to this citation is required. If you wish to respond, write to the Gas & Water Division, New York State Department of Public Service, Three Empire State Plaza, Albany, N.Y. 12223-1350. If the Public Service Commission proposes to determine any penalties for this alleged violation(s), you will be notified by separate letter and provided an opportunity to respond.

Original: Company Cited

Copies: (1) Other Party, (2) Dept. of Public Service Files

**STATE OF NEW YORK
DEPARTMENT OF PUBLIC SERVICE
16 NYCRR PART 753 CITATION**

Date of Violation(s): 8/7/2012

Date Issued: 1/18/2013

Company Cited: Consolidated Edison Company of New York

Attn: Pedro Corredor

Address: 118-29 Queens Boulevard

City: Forest Hills, New York City

State: NY Zip Code: 11375

Violation Location: Intersection of Barnes Avenue & E 216th Street

City: Bronx

County: Bronx

Other Party(s): Thirau LLC, 127 Costello Road, Newington, CT 06111

Facilities: 6-inch LP HDPE gas main

Method of Excavation: Core Bore Machine

Description of Project: Utility Pole Replacement

Nature of Project: Private ☐ Municipal ☐ State ☐ Utility ☒

Origin of Investigation: Directly Reported by: ☐ Emergency Notification ☒
Operator ☐ Excavator ☐ Random ☐ Complaint ☐

Effect/Public Health: Unscheduled release of natural gas to atmosphere from 6" LP HDPE gas main.


Safety & Welfare: Evacuation of approximately 300 people from nearby school and service outages.

Code Section(s) Violated: 753-4.6(a) Requirement: Locate and accurately mark operator's underground facilities in or within 15 feet of work area

Remarks: Contractor requested a markout stating, "mark a 30 foot radius around pole #13757". The operator failed to markout all underground facilities in and within 15 feet of the requested work area.

Regional ID #	NYC-12-011		
Office ID #	4868		
One-Call #	122140324		
Pictures Taken	<input checked="" type="checkbox"/>	Yes	No
Booklet provided	<input type="checkbox"/>	Yes	No
Investigative Report	<input checked="" type="checkbox"/>	Yes	No
Other Evidence	CECONY Map Plates		

Marc Stubel
Print

DPS Investigator: 
Signature

Issued to: _____
Print

Signature

Signature acknowledges receipt only and does not constitute an admission to the alleged violation(s).

No response to this citation is required. If you wish to respond, write to the Gas & Water Division, New York State Department of Public Service, Three Empire State Plaza, Albany, N.Y. 12223-1350. If the Public Service Commission proposes to determine any penalties for this alleged violation(s), you will be notified by separate letter and provided an opportunity to respond.

Original: Company Cited

Copies: (1) Other Party, (2) Dept. of Public Service Files

Copies: (1) Other Party, (2) Dept. of Public Service Files