

Carburetor Icing Probability Graph – CEN23FA077

Airplane: Cessna 150H

Accident Date: 1/11/2022

Accident Location: Auburn, NE

Accident Time: 1924 CST

Weather: METAR KAFK 120115Z AUTO 01012KT 10SM
SCT120 00/M02 A2990

Celsius to Fahrenheit Conversion:

Temperature, 0° C = 32° F

Dew Point, -2° C = 28.4° F

Source: Federal Aviation Administration

Special Airworthiness Information Bulletin CE-09-35

Carburetor Icing Prevention

