National Transportation Safety Board

Office of Highway Safety Washington, DC 20594



HWY22MH009

ERRATA

Group Chair's Factual Report

TABLE OF CONTENTS

A.	Crash	3
	Group	
C.	Summary	3
D	Frrata	3

A. CRASH

Location: Clarendon Hills, Illinois

Date: May 11th, 2022 Time: 8:16 a.m. CDT

B. GROUP

Group Chair Eric Gregson

National Transportation Safety Board

Washington, D.C.

C. SUMMARY

Please refer to the Crash Information and Summary Report, in the docket for this investigation.

D. ERRATA - TECHNICAL RECONSTRUCTION GROUP CHAIR REPORT

 On page 3, last paragraph, first sentence should read: "Upon arrival of NTSB investigators, the lead cab car, identified as #8473, was still attached to the other five passenger rail cars and locomotive and was stopped approximately 1,106 feet east of the collision location."

Submitted by:

Eric Gregson Technical Reconstructionist