



Vehicle Photos

**Culver City, CA
HWY18FH004**

(3 pages)



Vehicle Photo 1: This is a view of the design imprint on the upper cowling of the passenger vehicle, that was transferred from the rear of the Fire Truck.



Vehicle Photo 2: This is a view of the damage sustained to the hood of the passenger vehicle.



Vehicle Photo 3: This is a view of the contact between the steering wheel and dash.



Vehicle Photo 4: This is a view of the damaged brake master cylinder for the passenger vehicle.