




**Photo 1 – View of accident airplane (photo courtesy of the pilot)**



**Photo 2 - View of aileron damage (photo courtesy of the pilot)**