



Photo 1 – View of left side of airplane (photo courtesy of the pilot)



Photo 2 - View of elevator damage (photo courtesy of the pilot)