



**Photo 1 – Rear view of fuselage and wing damage (photo courtesy of local law enforcement)**



**Photo 2 – Front view of fuselage and wing damage (photo courtesy of local law enforcement)**