

Winslow Griesser

PD San Juan Maritime and Divers Unit
Capt. Jose Delgado #3-592
Diver Rafael Quijano #878
Diver Catalino Ortiz #699
Diver Jonathan Morales #2023
Safety Wilfredo Quiñones #880
Boat Raptor (R-06)

Date: 08/10/2022
Time In: 4:16 pm approx.
Time out: 5:00 pm approx

Prepared by: SA [REDACTED]
CGIS RAO SAN JUAN [REDACTED]



Starboard Side

- #1 Mark with a measurement of approx... 1'
- #2 (2) different marks with a measurement of approx... 2'
- #3 (2) different marks with a measurement of approx... 3' and the other 2'
- #4 Mark with a measurement of approx... 9"
- #5 Mark near thruster side with a measurement of approx... 1'
- #6 Multiple marks that start at the front of the Starboard side

No other damage on Hull Starboard side, stern or propellers where found on CGC WINSLOW GRIESSER during Divers inspection on 08/10/2022.

Winslow Griesser

PD San Juan Maritime and Divers Unit
Capt. Jose Delgado #3-592
Diver Rafael Quijano #878
Diver Catalino Ortiz #699
Diver Jonathan Morales #2023
Safety Wilfredo Quiñones #880
Boat Raptor (R-06)

Date: 08/10/2022
Time In: 4:16 pm approx.
Time out: 5:00 pm approx

Prepared by: SA [REDACTED]
CGIS RAO SAN JUAN [REDACTED]



Port Side

- #1 Front
- #2 Mark starts at 8ft level with a measurement of approx... 3' 4"
- #3 Mark starts at 5ft level across 4ft level with a measurement of approx... 5' 5"

No other damage on Hull Port side, stern or propellers where found on CGC WINSLOW GRIESSER during Divers inspection on 08/10/2022.