



Photo 1 – View of Substantial Damage to Vertical Fin. (FAA)



Photo 2 – View of Fuselage Buckling aft of Cockpit (FAA)