

Photo 1 – View of Wreckage as Found (FAA)




Photo 2 – View of Left Wing, Tail Section and Engine (FAA)