




**Photo 1 – Airplane at accident site (Photo provided by FAA)**





**Photo 2 – Damage to right lower wing (Photo provided by FAA)**





**Photo 3 – Damage to right elevator (Photo provided by FAA)**