



Photo 1 – Aerial photo of the accident site



Photo 2 – Rear of burned wreckage



Photo 3 – Left side of burned wreckage



Photo 4 – Right side of burned wreckage



Photo 5 – Engine and one attached propeller blade



Photo 6 – Broken propeller blades and ground scars