



Photo 1 – Accident site and main wreckage from the rear



Photo 2 – Main wreckage from the front with powerlines in the background



Photo 3 – Power lines and a piece of right wing leading edge