

Photo 1 – Left Wing Damage (Courtesy of the owner)



Photo 2 – Left Wing Damage (Courtesy of the owner)




Photo 3 - Left Wing Tip (Courtesy of the owner)