



**Photo 1 – Aerial view of accident site**



**Photo 2 – Accident site, main wreckage**



**Photo 3 – Accident site, main wreckage**




**Photo 4 - Accident site, main wreckage**




**Photo 5 – Forward cabin floor and pilot seats**



**Photo 6 – Top of cabin structure with Vision 1000**




**Photo 7 – Rotor mast**



**Photo 8 – Rear bulkhead and rear cabin area**



**Photo 9 – Damaged main rotor blades**



**Photo 10 - Engine**



**Photo 11 – Pre accident photo of the helicopter**



**Photo 12 - Pre accident photo of the rear seats**



**Photo 13 – Pre accident photo of the front right pilot seat**



**Photo 14 – Pre accident photo of the front left pilot seat**