



Photo 1 – Debris Field



Photo 2 – Debris Field



Photo 3 – Debris Field



Photo 4 – Wreckage path



Photo 5 – Right Engine



Photo 6 – Left Engine



Photo 7 – Outer casing of the E-GPWS



Photo 8 – Cockpit Voice Recorder



Photo 9 – Interior of the Aircraft Recording System (AreS)