

CEN24LA130

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front of airplane (Courtesy of FAA)



Photograph 2 - Left side of airplane (Courtesy of FAA)



Photograph 3 - Left wing separation (Courtesy of FAA)



Photograph 4 - Left wing separation (Courtesy of FAA)