



Photo 1 – Engine Damage – Courtesy of FAA (Federal Aviation Administration)



Photo 2 – Side view of fuselage – Courtesy of FAA