



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA19FA265



Photo 1 – View of Airplane from Top (Left Wing in to the Right)



Photo 2 – View of Airplane from Right Wing



Photo 3 –View of Airplane from Below (Left Wing on Left)



Photo 4 – View of Airplane from the Left Wing



Photo 5 – Close-Up View of Tail and Fuselage Wreckage