



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA20CA223



Photo 1 – View of Inverted Airplane (Photo Courtesy of Local Police)



Photo 2 – View of Up-ripped Airplane from Left Side (Photo Courtesy of FAA)



Photo 3 – View of Up-righted Airplane from Rear (Photo Courtesy of FAA)



Photo 4 – View of Up-righted Airplane from Front (Photo Courtesy of FAA)



Photo 5 – View of Empennage (Photo Courtesy of FAA)



Photo 6 – View of Empennage from Front (Photo Courtesy of FAA)