



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA20CA250



Photo 1 – View of Airplane from Front (Photo Courtesy of FAA)



Photo 2 – View of Airplane from Left Wing (Photo Courtesy of FAA)



Photo 3 – View of Airplane from Right Wing (Photo Courtesy of FAA)




Photo 4 – View of Firewall Damage (Photo Courtesy of FAA)



Photo 5 – Close-Up View of Nose Area Damage (Photo Courtesy of FAA)