



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA20CA298



Photo 1 – View of Airplane from the Tail (Photo Courtesy of FAA)



Photo 2 – View of Airplane from Right Wing (Photo Courtesy of FAA)



Photo 3 – View of Airplane from Left Wing (Photo Courtesy of FAA)



Photo 4 – View of Airplane from Front (Photo Courtesy of FAA)



Photo 5 – View of Beginning of Impact Scar (Photo Courtesy of FAA)



Photo 6 – View of Propeller and Wheel Fairing (Photo Courtesy of FAA)