



**NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Eastern Region

**Photo Array**

**ERA20FA031**



**Photo 1 – View of Main Airplane Wreckage**





**Photo 2 – View of Main Airplane Wreckage**





**Photo 3 – View of Left Wing and Tree Debris**





**Photo 4 – Distant View of Main Wreckage**





**Photo 5 – View of Tree Damage with Airplane Debris**





**Photo 6 – Tree Limb Damage from Above**





**Photo 7 – Right Wing Damage**