



**NATIONAL TRANSPORTATION SAFETY BOARD**  
Office of Aviation Safety

**INVESTIGATIVE PHOTOGRAPHS**

**A. ACCIDENT      ERA21FA135**

Location:            Mayfield, KY  
Date:                February 22, 2021  
Aircraft:            Vans RV-7  
Registration:        N383DB

NTSB IIC:           Peter Wentz

**Photographs provided by the NTSB IIC.**



Photograph 1 – Accident site.



Photograph 2 – Accident airplane, view of the left wing, tail, and rudder.



Photograph 3 – Accident airplane, aft view of the left wing, tail section, and rudder.



Photograph 4 – Accident airplane, aft view of the right tail section, rudder, and right wing.



Photograph 5 – Accident airplane, cockpit area and instrument panel.