



Photo 1 – View of Airplane as Found (FAA)



Photo 2 – View of Damage to Right Wing, Wingtip, and Aileron Hinge Mount (FAA)




Photo 3 – Overhead View of ADS-B Ground Track over Google Earth (NTSB)




Photo 4 – ADS-B Ground Track over Google Earth (NTSB)




Photo 5 – Touchdown Point Illustration Interpolated from ADS-B and Video Time Stamps over Google Earth (NTSB)