

# MEMORANDUM FOR RECORD

## National Transportation Safety Board Office of Aviation Safety - Eastern Region

NTSB Case Number: ERA22LA190

Subject: Viewing of Essex County Airport (CDW) surveillance videos:

Video 1 - Shows the airplane landing approximately  $\frac{3}{4}$  down runway 22

Video 2- Shows the airplanes touchdown and then skidding off runway 22 into a ditch

A review of the airport surveillance videos shows the airplane approaching runway 22 at CDW. The airplane is seen landing approximately  $\frac{3}{4}$  of the way down the runway. Airport surveillance also shows the airplanes landing roll, exiting the runway 22 and coming to a stop in a ditch.