



Photo 1 – Aerial View of Main Wreckage and Wreckage Path Facing Opposite Direction of Travel (SCPD)



Photo 2 – View of Main Wreckage Facing Opposite Direction of Travel (Lycoming)



Photo 3 – View of Left Wing as Found (Lycoming)



Photo 4 – View of Engine as Found (Lycoming)