

ERA24LA085

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Damage Overview Left Side (Courtesy of FAA)



Photograph 2 - Airplane Damage Overview Right Side (Courtesy of FAA)



Photograph 3 - Airplane and Utility Pole (Courtesy of FAA)



Photograph 4 - Taxiway Overview (Courtesy of FAA)