

From: [Glen Carter](#)
To: [Lyons Sara](#)
Subject: RE: Document Request - Farmersville, TX (PLD21FR002)
Date: Tuesday, October 19, 2021 11:12:31 AM

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Sara,

The photos were taken with a cell phone. Those pictures are taken and then emailed or text to Marshall Cross at the end of the day. So they weren't sent before the incident.

Glen

From: Lyons Sara <[REDACTED]>
Sent: Tuesday, October 19, 2021 10:06 AM
To: Glen Carter <[REDACTED]>
Subject: RE: Document Request - Farmersville, TX (PLD21FR002)

Glen,

Can you confirm whether the photos of the pig were taken with a cell phone or with a camera? I am wondering if the time was accurately set on the device (6/28/2021 at 3:27PM and 3:28PM). Were these photos emailed prior to the accident?

Thanks,
-Sara

From: Glen Carter <[REDACTED]>
Sent: Thursday, July 22, 2021 2:44 PM
To: Lyons Sara <[REDACTED]>
Subject: RE: Document Request - Farmersville, TX (PLD21FR002)
Importance: High

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Sara,

I have attached the documentation requested except for the JSAs. Marco is on paid leave and his truck was issued to another crew due to a truck shortage. Somehow during the transition his JSA book has been misplaced. It contains all of the JSAs that were conducted for the month of June. We are actively searching for it and when we find it I will send those over to you as well. I am now requiring all of our people to genius scan their JSAs immediately after they do them and send them to me where we don't have a repeat of lost documents. If there is anything else that you need please let me know.

Have a great day,

Glen

Glen Carter

Bobcat Contracting
1721 HCR 3106 - PO Box 663
Hillsboro, TX 76645



www.bobcatcontracting.com

From: Lyons Sara <[REDACTED]>
Sent: Thursday, July 22, 2021 8:06 AM
To: Glen Carter <[REDACTED]>
Subject: RE: Document Request - Farmersville, TX (PLD21FR002)

Good morning, Glen,

Can you specify which Atmos procedures were being followed by your staff on the day of the accident? I can either use a specific reference or the actual document.

Also, I did receive the information for the Human Performance Group (thank you), but I haven't seen a response to these Operations Group questions:

Documentation related to the work performed on the site of the accident for ten days prior to the accident and extending through the day after the accident, including:

1. Safety Briefing JSAs
2. Employee notes, including photos if available
3. Timeline of employees onsite, indicating the names of those individuals who were on the site, their title, and responsibilities
4. Scope of work for contract activities performed on the day of the accident

Can you give me an estimate of when these documents will be provided? If any of these records don't exist, a response stating that there are no such records will close the request.

Thanks,

-Sara

From: Glen Carter <[REDACTED]>
Sent: Friday, July 2, 2021 10:40 AM
To: Lyons Sara <[REDACTED]>
Subject: Re: Document Request - Farmersville, TX (PLD21FR002)

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Sara,

Bobcat Contracting was following ATMOS procedures related to sending and receiving pigs. The rest of the requested documents are being put together at our home office.

Thank you,

Glen

Sent from my iPad

On Jun 30, 2021, at 11:18 PM, Lyons Sara <[REDACTED]> wrote:

Glen,

I wanted to thank you again for your help with our investigation so far. We really appreciate your staff's willingness to help and to participate in interviews. As we continue through this on-scene portion of our investigation, we need some documentation to support the team's activities, which I've identified in the table below.

I will send you a link to the Accellion workspace for this investigation soon. When you log-in, you will see a folder for each Party and subfolders for each group. Please add the requested documents to your folder under the relevant group (as identified below).

There is some information that cannot be shared with the other Parties in this request (e.g., employee drug and alcohol records). Only for those records that cannot be shared with the other Parties, please provide them on a thumb drive if possible.

Thanks,

-Sara

Requesting Group	Description





[This photograph was timestamped 6/28/2021 at 3:28 PM]





[This photograph was timestamped 6/28/2021 at 3:27 PM]



[This photograph was timestamped 6/28/2021 at 3:28 PM]





JOB: 01-ATM-02637 Line D17 Piggig- D17-9 to Rockwall

Date	Notes	_fkEmpListID	EmpName	_fkEQListID	_fkEmpRank	PerDiemLinesQ	TStart	TEnd	HoursInvoiced	
Monday, June 21, 2021		1913	Marco Rodriguez		FOR	Yes	06:30:00	20:00:00	13.50	
		2715	Ethan Knight		GL	Yes	06:30:00	18:30:00	12.00	
		2771	Adolfo Ruiz		SKLDLAB	Yes	15:00:00	18:30:00	3.50	
				Service Truck		Yes	15:00:00	20:00:00	5.00	
				Service Truck			06:30:00	18:30:00	3.50	
				Service Truck			06:30:00	18:30:00	12.00	
				Service Truck			06:30:00	20:00:00	13.50	
				320 Excavator			07:00:00	17:00:00	10.00	
				Haul Truck - 50 Ton		No	07:00:00	17:00:00	10.00	
		1. Drove to ATMOS station in Heath, unloaded trackhoe, & helped FESCO rig up separator and did leak checks. Drove to 1A. launcher in Farmersville, & set up FESCO's flare. Preloaded bullet nose pig for the next day, and rebuilt mandrel.								
		1B. Worked on setting up google sheets & tracking spots for the pig run.								
		Drop off 210								
	Tuesday, June 22, 2021		1913	Marco Rodriguez		FOR	Yes	03:00:00	15:00:00	12.00
			2715	Ethan Knight		GL	Yes	03:00:00	15:00:00	12.00
		2771	Adolfo Ruiz		SKLDLAB	Yes	03:00:00	15:00:00	12.00	
				Service Truck		Yes	03:00:00	15:30:00	12.50	
				Service Truck			03:00:00	15:00:00	12.00	
				Service Truck			03:00:00	15:00:00	12.00	
				Service Truck			03:00:00	15:00:00	12.00	
				Geo Phone			03:00:00	15:00:00	1.00	
				Geo Phone			03:00:00	15:00:00	1.00	
				Geo Phone			03:00:00	15:00:00	1.00	
				320 Excavator			07:00:00	17:00:00	10.00	
				Light Tower			04:00:00	10:00:00	6.00	
				28 Caterpillar Loader			07:00:00	17:00:00	10.00	
		1. Drove to launcher, launched bullet nose pig and tracked pig. Got to receiver, pulled pig and washed it. Then drove to 1A. receiver and preloaded mandrel for the next day.								
Wednesday, June 23, 2021		1913	Marco Rodriguez		FOR	Yes	03:00:00	16:00:00	13.00	
		2715	Ethan Knight		GL	Yes	03:00:00	16:00:00	13.00	
		2771	Adolfo Ruiz		SKLDLAB	Yes	03:00:00	16:00:00	13.00	
				Service Truck		Yes	03:00:00	12:00:00	9.00	
				Service Truck			03:00:00	16:00:00	13.00	
				Service Truck			03:00:00	16:00:00	13.00	
				Service Truck			03:00:00	16:00:00	13.00	
				Geo Phone			03:00:00	16:00:00	1.00	
				Geo Phone			03:00:00	16:00:00	1.00	
				Geo Phone			03:00:00	16:00:00	1.00	
				320 Excavator			07:00:00	17:00:00	10.00	
				Light Tower			04:00:00	10:00:00	6.00	
				28 Caterpillar Loader			07:00:00	17:00:00	10.00	
		1. Drove to launcher, launched mandrel and tracked. Got to receiver, pulled mandrel and washed it. Went to ATMOS 1A. office in McKinney to look at and pick up pig parts inventory. Then drove to launcher, rebuilt mandrel and preloaded 1B. for the next day.								
Thursday, June 24, 2021		1913	Marco Rodriguez		FOR	Yes	03:00:00	16:00:00	11.50	
		2715	Ethan Knight		GL	Yes	03:00:00	16:00:00	13.00	
		2771	Adolfo Ruiz		SKLDLAB	Yes	03:00:00	16:00:00	11.50	
				Service Truck		Yes	03:00:00	12:00:00	9.00	
				Service Truck			03:00:00	16:00:00	13.00	
				Service Truck			03:00:00	16:00:00	13.00	
				Service Truck			03:00:00	16:00:00	13.00	
				Geo Phone			03:00:00	16:00:00	1.00	
				Geo Phone			03:00:00	16:00:00	1.00	
				Geo Phone			03:00:00	16:00:00	1.00	
				320 Excavator			07:00:00	17:00:00	10.00	
				Light Tower			04:00:00	10:00:00	6.00	
				28 Caterpillar Loader			07:00:00	17:00:00	10.00	
		1. Drove to launcher, launched mandrel and tracked. Got to receiver, pulled mandrel and washed it. Then drove to 1A. receiver, rebuilt mandrel and preloaded for the next day.								
Friday, June 25, 2021		1913	Marco Rodriguez		FOR	No	03:00:00	12:00:00	0.00	
		2715	Ethan Knight		GL	No	03:00:00	15:00:00	0.00	
		2771	Adolfo Ruiz		SKLDLAB	No	03:00:00	12:00:00	0.00	
				Service Truck		Yes	03:00:00	12:00:00	9.00	
				320 Excavator			07:00:00	17:00:00	8.00	
				Service Truck			03:00:00	12:00:00	12.00	
				Service Truck			03:00:00	12:00:00	9.00	
				Service Truck			03:00:00	12:00:00	9.00	
				Geo Phone		No	03:00:00	12:00:00	1.00	
				Geo Phone		No	03:00:00	12:00:00	1.00	
				Geo Phone		No	03:00:00	12:00:00	1.00	
				Light Tower			04:00:00	10:00:00	6.00	
				28 Caterpillar Loader			07:00:00	17:00:00	8.00	
		1. Drove to launcher, launched mandrel and tracked. Got to receiver, pulled mandrel, washed and then rebuilt mandrel for								

Date	Activity	Time	Person	Code	Yes/No	Start	End	Rate
Sunday, June 27, 2021	1A. another run later that day.	1913	Marco Rodriguez	FOR	No	15:00:00	19:00:00	0.00
		2771	Adolfo Ruiz	GL	No	15:00:00	19:00:00	0.00
			Service Truck		Yes	12:00:00	18:00:00	6.00
			320 Excavator			07:00:00	17:00:00	4.00
			Service Truck		Yes	15:00:00	19:00:00	4.00
			Service Truck		Yes	15:00:00	19:00:00	4.00
			Service Truck		Yes	15:00:00	19:00:00	4.00
Monday, June 28, 2021	Rebuilt mandrel, drove to launcher in Farmersville & preload mandrel for next day.	1913	Marco Rodriguez	FOR	No	03:00:00	15:30:00	12.50
		2715	Ethan Knight	GL	No	03:00:00	15:30:00	12.50
		2771	Adolfo Ruiz	SKDLAB	No	03:00:00	15:30:00	12.50
			28 Caterpillar Loader			03:00:00	15:00:00	11.00
			320 Excavator			03:00:00	15:00:00	11.00
			Service Truck			03:00:00	15:30:00	12.50
			Service Truck			03:00:00	15:30:00	12.50
			Service Truck			03:00:00	15:30:00	12.50
			Geo Phone			03:00:00	15:30:00	1.00
			Geo Phone			03:00:00	15:30:00	1.00
			Geo Phone			03:00:00	15:30:00	1.00
			Light Tower			03:00:00	15:30:00	6.00
		1. Drive to jobsite, launch mandrel pig, track, receive and unload and clean. Drive to McKinney service center and pick up						
	1A. gauge plate, drive to location.							

Timeline of Bobcat Contracting Employees on site Farmersville June 28, 2021

Marco Rodriguez, Adolfo Ruiz and Ethan Knight arrived onsite at the D17 worksite in Farmersville at 2:29pm on June 28, 2021. The incident occurred at approximately 3:30pm.

Marco Rodriguez- Foreman. His responsibilities include leading the safety briefing with his team before start of work, oversee the entire pig loading operation for Bobcat Contracting and operate the excavator to push the pig into the launcher. He can also perform any task related to launching/receiving pigs. And those under him can work under his span of control and direct supervision.

Adolfo Ruiz- Skilled labor. His responsibilities include any work done to the pig (rebuild, install transmitter, etc), operating valves or doors with direct ATMOS supervision and direction, spotting for the operator of the excavator, strapping/un-strapping pig to excavator, loading/unloading pig, preparing push pole and bonding cable, loading and pushing the pig in manually, unloading the pig.

Ethan Knight- General labor. His responsibilities include performing any general labor task that he is OQ trained for and assisting the skilled labor and foreman with tasks throughout the launching/receiving operation.

Timeline of events is as follows:

Timeline of the Major Activities at the Site on the Day of the Accident

(Times in parenthesis indicate the longest estimated duration of that task)

1. Atmos and Bobcat (A&B) on Location at 2:29
2. Sat in truck during heavy periods of rain
- 2B – Atmos verifies valve closures
3. Rain lightened up, set up umbrella and FESCO arrives at 3:18
4. Transmitter in Pig – Bobcat (7 minutes); also occurring at this time:
 4. FESCO begin process of flaring (10 minutes) (3:19)¹
 5. Atmos verifies Line is Flat
 6. Procedure to open Barrel door (3 min) – Bobcat
(Steps 7-9 took an estimated 3 minutes to complete)
 7. Bobcat enters excavator
 8. Strapping pig to excavator – Bobcat
 9. Moving pig into position in trap – Bobcat
 10. Push pig in barrel [Manually – Bobcat and FESCO (B&F)]
 11. Excavator tracks back – Bobcat
 12. Push pole picked up, bonding strap attached – (B&F)

¹¹ Details of the flaring process is discussed after the timeline.

Timeline of Bobcat Contracting Employees on site Farmersville June 28, 2021

13. Manually pushing pig into nominal with poll (B&F)
14. Excavator tracking back to push pole (B&F)
15. Excavator pushes pig into nominal, 4 crew step back from pole; bonding cable held onto push pole (B&F)
16. Atmos verifies setting of front caps
17. Excavator tracks back as crew holds push pole – (B&F)
18. Crew starts to remove push pole (B&F)
19. Ignition
20. 911 call at 3:35:50 pm