

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: RRD23MR005
---	---------------------------------------

For Use In All Modal Investigations

OFFICE Railroad, Pipeline Hazardous Materials	DATE OF ACCIDENT 2/3/2023	ACCIDENT LOCATION (City & State) East Palestine Ohio
--	------------------------------	---

EVIDENCE OBTAINED BY: Paul Stancil

<input checked="" type="checkbox"/> EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION Tank cars OCPX80235, OCPX80179, and GATX95098, tank car staging area, East Palestine, Ohio	DATE 2/8/23
<input type="checkbox"/> EVIDENCE RECEIVED FROM:		GROUP Hazmat
EVIDENCE CONTROL NUMBER RRD23MR005 - HAZ - 001		

DESCRIPTION (BIN ITEM - HAS BEEN SEPARATED)
 1. OCPX 80235: plastic bag containing metallic debris taken from PRD inside of top fittings housing.
 2. OCPX 80179: plastic bag containing metallic debris taken from top fittings protective housing
 3. GATX 95098: plastic bag containing metallic debris taken from top fittings protective housing.

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Robert	LAST NAME: Wood	
ADDRESS: [REDACTED]		
PHONE: [REDACTED]	EMAIL: [REDACTED]	
RETURNED <input type="checkbox"/>	DATE:	CONTACT:

CHAIN OF CUSTODY

RELEASED BY: Tank cars OCPX80235, OCPX80179, and GATX95098	RELEASED TO: Paul Stancil, RPH-20	DATE: 2/8/2023
PURPOSE: Evidence collected from tank car during on-scene investigation.		
RELEASED BY: Paul Stancil, RPH-20	RELEASED TO: Adrienne Lamm, RE-30	DATE: 2/15/2023
PURPOSE: Laboratory examination.		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: RRD23MR005
---	---------------------------------------

For Use In All Modal Investigations

OFFICE Railroad, Pipeline Hazardous Materials	DATE OF ACCIDENT 2/3/2023	ACCIDENT LOCATION (City & State) East Palestine Ohio
--	------------------------------	---

EVIDENCE OBTAINED BY: Paul Stancil

<input checked="" type="checkbox"/> EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION Tank car GATX95098, staging area, East Palestine, Ohio	DATE 2/22/23
<input type="checkbox"/> EVIDENCE RECEIVED FROM:		GROUP Hazmat
EVIDENCE CONTROL NUMBER RRD23MR005 - HAZ - 002		

DESCRIPTION (BIN ITEM - HAS BEEN SEPARATED
Plastic bag containing manway/pressure plate gasket. Gasket material is believed to be Durlon 9000 filled PTFE gasket material. Trinity Industries tank car drawing F-020-T16043 (Fittings Arrangement) calls for Durlon 9000 21 1/4 ID x 22 1/4 OD x 1/8 thick. See HAZ- 006 for related exam request.

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Robert	LAST NAME: Wood	
ADDRESS: [REDACTED]		
PHONE: [REDACTED]	EMAIL: [REDACTED]	
RETURNED <input type="checkbox"/>	DATE:	CONTACT:

CHAIN OF CUSTODY

RELEASED BY: Tank car GATX95098	RELEASED TO: Paul Stancil, RPH-20	DATE: 2/22/23
PURPOSE: Evidence collected from tank car during on-scene investigation.		
RELEASED BY: Paul Stancil, RPH-20	RELEASED TO: Michael Budinski, RE-30	DATE: 2/28/23
PURPOSE: Laboratory examination.		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: RRD23MR005
---	---------------------------------------

For Use In All Modal Investigations

OFFICE Railroad, Pipeline Hazardous Materials	DATE OF ACCIDENT 2/3/2023	ACCIDENT LOCATION (City & State) East Palestine Ohio
--	------------------------------	---

EVIDENCE OBTAINED BY: Paul Stancil

<input checked="" type="checkbox"/> EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION Tank car OCPX80235, TrinityRail Car Repair, 2850 Peden Rd., Saginaw, TX	DATE 3/15/2023
<input type="checkbox"/> EVIDENCE RECEIVED FROM:		GROUP Hazmat
EVIDENCE CONTROL NUMBER RRD23MR005 - HAZ - 003		

DESCRIPTION (BIN ITEM - HAS BEEN SEPARATED
OCPX80235: plastic bag containing metallic debris taken from pressure relief device throat inside of top fittings protective housing. Material was sampled during bench testing conducted at TrinityRail, Saginaw, TX on 3/15/2023.

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Robert	LAST NAME: Wood	
ADDRESS: [REDACTED]		
PHONE: [REDACTED]	EMAIL: [REDACTED]	
RETURNED <input type="checkbox"/>	DATE:	CONTACT:

CHAIN OF CUSTODY

RELEASED BY: Tank car OCPX80235	RELEASED TO: BOL # 1381HME-NTSB-1, evidence seals DOT-068989 and 068990	DATE: 2/23/23
PURPOSE: Five VCM tank car pressure plate assemblies shipped from East Palestine OH to TrinityRail Saginaw, TX for examination.		
RELEASED BY: DOT-068989 and 068990	RELEASED TO: Paul Stancil, RPH-20	DATE: 3/15/2023
PURPOSE: Separate PRD from pressure plate. Valve examination at TrinityRail, Saginaw, Texas.		
RELEASED BY: Paul Stancil, RPH-20	RELEASED TO: Trinity - 5372464; 5372465; 5372466; 5372467	DATE: 3/16/2023
PURPOSE: Secure bagged evidence in shipping container and apply evidence seals.		
RELEASED BY: Trinity - 5372464; 5372465; 5372466; 5372467	RELEASED TO: BOL# F0013864, FedEx Freight	DATE: 3/17/2023
PURPOSE: Ship from TrinityRail Saginaw, TX to NTSB headquarters, Washington, D.C.		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: RRD23MR005
---	---------------------------------------

For Use In All Modal Investigations

OFFICE Railroad, Pipeline Hazardous Materials	DATE OF ACCIDENT 2/3/2023	ACCIDENT LOCATION (City & State) East Palestine Ohio
--	------------------------------	---

EVIDENCE OBTAINED BY: Paul Stancil

<input checked="" type="checkbox"/> EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION Tank car GATX95098, TrinityRail Car Repair, 2850 Peden Rd., Saginaw, TX	DATE 3/15/2023
<input type="checkbox"/> EVIDENCE RECEIVED FROM:		GROUP Hazmat
EVIDENCE CONTROL NUMBER RRD23MR005 - HAZ - 004		

DESCRIPTION (BIN ITEM - HAS BEEN SEPARATED
GATX95098: plastic bag containing metallic debris taken from top fittings protective housing next to pressure relief device. Material was sampled during bench testing that occurred at TrinityRail, Saginaw, TX on 3/16/2023.

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Robert	LAST NAME: Wood	
ADDRESS: [REDACTED]		
PHONE: [REDACTED]	EMAIL: [REDACTED]	
RETURNED <input type="checkbox"/>	DATE:	CONTACT:

CHAIN OF CUSTODY

RELEASED BY: Tank car OCPX80235	RELEASED TO: BOL # 1381HME-NTSB-1, evidence seals DOT-068989 and 068990	DATE: 2/23/23
PURPOSE: Five VCM tank car pressure plate assemblies shipped from East Palestine OH to TrinityRail Saginaw, TX for examination.		
RELEASED BY: DOT-068989 and 068990	RELEASED TO: Paul Stancil, RPH-20	DATE: 3/15/2023
PURPOSE: Separate PRD from pressure plate. Valve examination at TrinityRail, Saginaw, Texas.		
RELEASED BY: Paul Stancil, RPH-20	RELEASED TO: Trinity - 5372464; 5372465; 5372466; 5372467	DATE: 3/16/2023
PURPOSE: Secure bagged evidence in shipping container and apply evidence seals.		
RELEASED BY: Trinity - 5372464; 5372465; 5372466; 5372467	RELEASED TO: BOL# F0013864, FedEx Freight	DATE: 3/17/2023
PURPOSE: Ship from TrinityRail Saginaw, TX to NTSB headquarters, Washington, D.C.		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: RRD23MR005
---	---------------------------------------

For Use In All Modal Investigations

OFFICE Railroad, Pipeline Hazardous Materials	DATE OF ACCIDENT 2/3/2023	ACCIDENT LOCATION (City & State) East Palestine Ohio
--	------------------------------	---

EVIDENCE OBTAINED BY: Paul Stancil

<input checked="" type="checkbox"/> EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION Tank car OCPX80235, TrinityRail Car Repair, 2850 Peden Rd., Saginaw, TX	DATE 3/15/2023
<input type="checkbox"/> EVIDENCE RECEIVED FROM:		GROUP Hazmat
EVIDENCE CONTROL NUMBER RRD23MR005 - HAZ - 005		

DESCRIPTION (BIN ITEM - HAS BEEN SEPARATED
OCPX80235: plastic bag containing three glass vials of debris taken from seal retainer cup in pressure relief device during bench testing that occurred on 3/15/2023. Two vials may contain a metallic fragment, one vial contains soot-like material.

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Robert	LAST NAME: Wood	
ADDRESS: [REDACTED]		
PHONE: [REDACTED]	EMAIL: [REDACTED]	
RETURNED <input type="checkbox"/>	DATE:	CONTACT:

CHAIN OF CUSTODY

RELEASED BY: Tank car OCPX80235	RELEASED TO: BOL # 1381HME-NTSB-1, evidence seals DOT-068989 and 068990	DATE: 2/23/23
PURPOSE: Five VCM tank car pressure plate assemblies shipped from East Palestine OH to TrinityRail Saginaw, TX for examination.		
RELEASED BY: DOT-068989 and 068990	RELEASED TO: Paul Stancil, RPH-20	DATE: 3/15/2023
PURPOSE: Separate PRD from pressure plate. Valve examination at TrinityRail, Saginaw, Texas.		
RELEASED BY: Paul Stancil, RPH-20	RELEASED TO: Trinity - 5372464; 5372465; 5372466; 5372467	DATE: 3/16/2023
PURPOSE: Secure bagged evidence in shipping container and apply evidence seals.		
RELEASED BY: Trinity - 5372464; 5372465; 5372466; 5372467	RELEASED TO: BOL# F0013864, FedEx Freight	DATE: 3/17/2023
PURPOSE: Ship from TrinityRail Saginaw, TX to NTSB headquarters, Washington, D.C.		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: RRD23MR005
---	---------------------------------------

For Use In All Modal Investigations

OFFICE Railroad, Pipeline Hazardous Materials	DATE OF ACCIDENT 2/3/2023	ACCIDENT LOCATION (City & State) East Palestine Ohio
--	------------------------------	---

EVIDENCE OBTAINED BY: Paul Stancil

<input checked="" type="checkbox"/> EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION Tank car OCPX80235, TrinityRail Car Repair, 2850 Peden Rd., Saginaw, TX	DATE 3/15/2023
<input type="checkbox"/> EVIDENCE RECEIVED FROM:		GROUP Hazmat
EVIDENCE CONTROL NUMBER RRD23MR005 - HAZ - 006		

DESCRIPTION (BIN ITEM - HAS BEEN SEPARATED
 OCPX80235: plastic bag containing pressure relief device gasket. Gasket material is believed to be Durlon 9000 filled PTFE gasket material. Gasket was removed from pressure plate assembly during bench testing that occurred on 3/15/2023 at TrinityRail, Saginaw, TX.

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Robert	LAST NAME: Wood	
ADDRESS: [REDACTED]		
PHONE: [REDACTED]	EMAIL: [REDACTED]	
RETURNED <input type="checkbox"/>	DATE:	CONTACT:

CHAIN OF CUSTODY

RELEASED BY: Tank car OCPX80235	RELEASED TO: BOL # 1381HME-NTSB-1, evidence seals DOT-068989 and 068990	DATE: 2/23/23
PURPOSE: Five VCM tank car pressure plate assemblies shipped from East Palestine OH to TrinityRail Saginaw, TX for examination.		
RELEASED BY: DOT-068989 and 068990	RELEASED TO: Paul Stancil, RPH-20	DATE: 3/15/2023
PURPOSE: Separate PRD from pressure plate. Valve examination at TrinityRail, Saginaw, Texas.		
RELEASED BY: Paul Stancil, RPH-20	RELEASED TO: Trinity - 5372464; 5372465; 5372466; 5372467	DATE: 3/16/2023
PURPOSE: Secure bagged evidence in shipping container and apply evidence seals.		
RELEASED BY: Trinity - 5372464; 5372465; 5372466; 5372467	RELEASED TO: BOL# F0013864, FedEx Freight	DATE: 3/17/2023
PURPOSE: Ship from TrinityRail Saginaw, TX to NTSB headquarters, Washington, D.C.		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: RRD23MR005
---	---------------------------------------

For Use In All Modal Investigations

OFFICE Railroad, Pipeline Hazardous Materials	DATE OF ACCIDENT 2/3/2023	ACCIDENT LOCATION (City & State) East Palestine Ohio
--	------------------------------	---

EVIDENCE OBTAINED BY: Paul Stancil

<input checked="" type="checkbox"/> EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION Tank car OCPX80370 and GATX95098, TrinityRail Car Repair, 2850 Peden Rd., Saginaw, TX	DATE 3/15/2023
<input type="checkbox"/> EVIDENCE RECEIVED FROM:		GROUP Hazmat
EVIDENCE CONTROL NUMBER RRD23MR005 - HAZ - 007		

DESCRIPTION (BIN ITEM - HAS BEEN SEPARATED
OCPX80370 and GATX95098: plastic bin containing two disassembled pressure relief device removed from tank car pressure plate. Approximate weight is 140 pounds.

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Robert	LAST NAME: Wood	
ADDRESS: [REDACTED]		
PHONE: [REDACTED]	EMAIL: [REDACTED]	
RETURNED <input type="checkbox"/>	DATE:	CONTACT:

CHAIN OF CUSTODY

RELEASED BY: Tank car OCPX80370 and GATX95098	RELEASED TO: BOL # 1381HME-NTSB-1, evidence seals DOT-068989 and 068990	DATE: 2/23/23
PURPOSE: Five VCM tank car pressure plate assemblies shipped from East Palestine OH to TrinityRail Saginaw, TX for examination.		
RELEASED BY: DOT-068989 and 068990	RELEASED TO: Paul Stancil, RPH-20	DATE: 3/15/2023
PURPOSE: Separate PRD from pressure plate. Valve examination at TrinityRail, Saginaw, Texas.		
RELEASED BY: Paul Stancil, RPH-20	RELEASED TO: Trinity - 5372474; 5372468; 5372469; 5372470	DATE: 3/16/23
PURPOSE: Secure two PRDs in shipping container.		
RELEASED BY: Trinity - 5372474; 5372468; 5372469; 5372470	RELEASED TO: BOL# F0013864, FedEx Freight	DATE: 3/17/2023
PURPOSE: Ship from TrinityRail Saginaw, TX to NTSB headquarters, Washington, D.C.		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: RRD23MR005
---	---------------------------------------

For Use In All Modal Investigations

OFFICE Railroad, Pipeline Hazardous Materials	DATE OF ACCIDENT 2/3/2023	ACCIDENT LOCATION (City & State) East Palestine Ohio
--	------------------------------	---

EVIDENCE OBTAINED BY: Paul Stancil

<input checked="" type="checkbox"/> EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION Tank car TILX402025, TrinityRail Car Repair, 2850 Peden Rd., Saginaw, TX	DATE 3/15/2023
<input type="checkbox"/> EVIDENCE RECEIVED FROM:		GROUP Hazmat
EVIDENCE CONTROL NUMBER RRD23MR005 - HAZ - 008		

DESCRIPTION (BIN ITEM - HAS BEEN SEPARATED
TILX402025: plastic bin containing disassembled pressure relief device removed from tank car pressure plate. Approximate weight is 70 pounds.

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Robert	LAST NAME: Wood	
ADDRESS: [REDACTED]		
PHONE: [REDACTED]	EMAIL: [REDACTED]	
RETURNED <input type="checkbox"/>	DATE:	CONTACT:

CHAIN OF CUSTODY

RELEASED BY: Tank car TILX402025	RELEASED TO: BOL # 1381HME-NTSB-1, evidence seals DOT-068989 and 068990	DATE: 2/23/23
PURPOSE: Five VCM tank car pressure plate assemblies shipped from East Palestine OH to TrinityRail Saginaw, TX for examination.		
RELEASED BY: DOT-068989 and 068990	RELEASED TO: Paul Stancil, RPH-20	DATE: 3/15/2023
PURPOSE: Separate PRD from pressure plate. Valve examination at TrinityRail, Saginaw, Texas.		
RELEASED BY: Paul Stancil, RPH-20	RELEASED TO: Trinity - 5372464; 5372465; 5372466; 5372467	DATE: 3/16/23
PURPOSE: Secure PRD in shipping container.		
RELEASED BY: Trinity - 5372464; 5372465; 5372466; 5372467	RELEASED TO: BOL# F0013864, FedEx Freight	DATE: 3/17/2023
PURPOSE: Ship from TrinityRail Saginaw, TX to NTSB headquarters, Washington, D.C.		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: RRD23MR005
---	---------------------------------------

For Use In All Modal Investigations

OFFICE Railroad, Pipeline Hazardous Materials	DATE OF ACCIDENT 2/3/2023	ACCIDENT LOCATION (City & State) East Palestine Ohio
--	------------------------------	---

EVIDENCE OBTAINED BY: Paul Stancil

<input checked="" type="checkbox"/> EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION Tank car OCPX80235, TrinityRail Car Repair, 2850 Peden Rd., Saginaw, TX	DATE 3/15/2023
<input type="checkbox"/> EVIDENCE RECEIVED FROM:		GROUP Hazmat
EVIDENCE CONTROL NUMBER RRD23MR005 - HAZ - 009		

DESCRIPTION (BIN ITEM - HAS BEEN SEPARATED
OCPX80235: plastic bin containing disassembled pressure relief device removed from tank car pressure plate. Approximate weight is 70 pounds.

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Robert	LAST NAME: Wood
ADDRESS: [REDACTED]	
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED <input type="checkbox"/>	DATE:
CONTACT:	

CHAIN OF CUSTODY

RELEASED BY: Tank car OCPX80235	RELEASED TO: BOL # 1381HME-NTSB-1, evidence seals DOT-068989 and 068990	DATE: 2/23/23
PURPOSE: Five VCM tank car pressure plate assemblies shipped from East Palestine OH to TrinityRail Saginaw, TX for examination.		
RELEASED BY: DOT-068989 and 068990	RELEASED TO: Paul Stancil, RPH-20	DATE: 3/15/2023
PURPOSE: Separate PRD from pressure plate. Valve examination at TrinityRail, Saginaw, Texas.		
RELEASED BY: Paul Stancil, RPH-20	RELEASED TO: Trinity - 468003; 468004; 468005, 468006	DATE: 3/16/2023
PURPOSE: Secure PRD in shipping container.		
RELEASED BY: Trinity - 468003; 468004; 468005, 468006	RELEASED TO: BOL# F0013864, FedEx Freight	DATE: 3/17/2023
PURPOSE: Ship from TrinityRail Saginaw, TX to NTSB headquarters, Washington, D.C.		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: RRD23MR005
---	---------------------------------------

For Use In All Modal Investigations

OFFICE Railroad, Pipeline Hazardous Materials	DATE OF ACCIDENT 2/3/2023	ACCIDENT LOCATION (City & State) East Palestine Ohio
--	------------------------------	---

EVIDENCE OBTAINED BY: Paul Stancil

<input checked="" type="checkbox"/> EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION Tank car OCPX80179, TrinityRail Car Repair, 2850 Peden Rd., Saginaw, TX	DATE 3/15/2023
<input type="checkbox"/> EVIDENCE RECEIVED FROM:		GROUP Hazmat
EVIDENCE CONTROL NUMBER HMD23MR005 - HAZ - 010		

DESCRIPTION (BIN ITEM - HAS BEEN SEPARATED
OCPX80179: plastic bin containing disassembled pressure relief device removed from tank car pressure plate. Approximate weight is 70 pounds.

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Robert	LAST NAME: Wood	
ADDRESS: [REDACTED]		
PHONE: [REDACTED]	EMAIL: [REDACTED]	
RETURNED <input type="checkbox"/>	DATE:	CONTACT:

CHAIN OF CUSTODY

RELEASED BY: Tank car OCPX80179	RELEASED TO: BOL # 1381HME-NTSB-1, evidence seals DOT-068989 and 068990	DATE: 2/23/23
PURPOSE: Five VCM tank car pressure plate assemblies shipped from East Palestine OH to TrinityRail Saginaw, TX for examination.		
RELEASED BY: DOT-068989 and 068990	RELEASED TO: Paul Stancil, RPH-20	DATE: 3/15/2023
PURPOSE: Separate PRD from pressure plate. Valve examination at TrinityRail, Saginaw, Texas.		
RELEASED BY: Paul Stancil, RPH-20	RELEASED TO: Trinity - 4687999; 4688000; 4688001; 4688002	DATE: 3/16/23
PURPOSE: Secure PRD in shipping container.		
RELEASED BY: Trinity - 4687999; 4688000; 4688001; 4688002	RELEASED TO: BOL# F0013864, FedEx Freight	DATE: 3/17/2023
PURPOSE: Ship from TrinityRail Saginaw, TX to NTSB headquarters, Washington, D.C.		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

