

YEAR 2010 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Sept 27	375.91		3635.4	TTS mont 1635.4
	Eng 0-360	A4A SM	L-21906-30A	installed in PA-22/20
	N9975D	SM 22-6766		this date JAW STC iBIRM as per
				light plane drawings associated with STC instructions note: STC
	RM45	incorporated on	AIC N9975D, comp ✓	#164/80 #2 74/80
	#3 64/80	#4 64/80	oil screen ✓ OK, fuel screens ✓ OK, mag timing	✓ OK AP 87-20-01 P/W, multi ✓ OK AD 91-14-22 PCW JAW AD 2004-10
				in accordance with MSB 475C See AP note Log this etc. Engine
				fuel pump repairs as per STC SA02241AK Trimmer Aviation fuel modification
				(pressure vented fuel caps), Aeroshell 500 installed, lubed controls
				Engine time comp OK. I credit this engine has been inspected
				JAW a 100hr inspection this date, airworthy for return to
	Service	[REDACTED]	[REDACTED]	APP

DATE July 7 SERIAL NO. _____

NAME Dick Thompson CITY _____

MODEL P 180 AIRCRAFT SERIAL NO. 28-3678 TOTAL HOURS 3016

REGISTRATION NO. 95549V ENGINE FOR FWD. L-21706-36A

RECEIVED: AM PM L OR AFT

PROMISED: AM PM PHONE WHEN READY YES # _____ WRITTEN BY _____

OPER. NO. _____ SERVICE DESCRIPTION _____

OPER. NO.	DESCRIPTION	CHANGE OIL	CHANGE OIL FILTER CART.	INSPECTIONS:	25-50-75 HOUR	100 HOUR ANNUAL	WASH	POLISH	SIGNATURE	LICENSE NUMBER
	ACT. MAINT. - DEF. 60M - COOLER REMOVE TO SHIP CHASS. - CHANGE L AND LITE									
	ENG. REMOVE - TEAR DOWN - & REINSTALL DUE TO HI OIL CONSUMPTION & CHAIN RE-MAKE FOR REWORK -									
	W/ RD 8/1-14-33 50 475 P CARBURETOR GEAR KIT & PUMP DRIVE SHAFT - NITRATE & CARBURIZED GEAR									

Just Bear the Endorsement Mechanic, and his Rating member MUST be Shown.

FRY'S AIRCRAFT

7-20-93 TACH TIME 3048.4
 ran-up a/c, drained oil, r & r filter w/ new, cut
 open filter & checked for metal-NO contamination
 added 8 qt aeroshell 100w straight mineral oil
 washed engine-ran-up checked for oil leaks- ok
 7-20-93

No. _____
 SIGNATURE _____
 LICENSE NUMBER _____

MATERIAL USED

QUAN.	PART NUMBER AND DESCRIPTION	PRICE EACH
4	VALVE CYL. ASSY, NEW	
3	VALVE TAPPETS, NEW	
4	ROCKER ARMS, NEW	
2	ROCKER PIN PLUGS, NEW	
8	ROCKER PIN PLUGS, NEW	
8	NEW TAPPET RODS	
4	CYL. HOLES DOWN HOLES	
4	STANDARD TUBE HOSES	
4	INTAKE HOSES	
2	OIL PUMP CHAMBER, NEW	
1	OIL PUMP HOUSING, NEW	
1	OIL PUMP DRIVE, NEW	
4	MAIN BEARINGS, NEW	
2	FRONT MAIN BEARINGS, NEW	
1	CRANK SET, NEW	
4	CRANK MOUNTS, NEW	
1	VALVE HOSE BRACKET	
1	VALVE FILTER	
1	OIL PUMP BALL, NEW	
1	THRUST WASH	
1	GEAR BOL. CRANK, NEW	
1	SNAP RING CRANK, NEW	
4	VALVE LAMP NEW	
4	ROTOR CAPS, NEW	
3	PUSH RODS USED	
2	5 Hooks	
2	MAG. GUARDS, NEW	
8	SPRINGER PLUGS	
1	CRANK SEAL, NEW	
1	LAMP LITE	
2	HARDWARE	
2	OIL FILTERS	
	DUCTING	
	WELDED	
	TOTAL PARTS	

NEW TYPE

JULY 1993 TACH 3016
 THIS ENG. L-21906-30H
 REMOVE FOR DISASSEMBLY
 FOR REPAIR
 [REDACTED] [REDACTED] IA