



Motor Carrier Attachment

Executive's SMS Scores as of February 22, 2020

Pala Mesa, California, February 22, 2020

HWY20FH003

(8 pages)



EXECUTIVE LINES INC
 U.S. DOT#: 1215546
 Address: 11723 GARVEY
 AVE B
 EL MONTE, CA 91732
 Number of Vehicles: 7
 Number of Drivers: 11
 Number of Inspections: 20

Safety Rating & OOS Rates
 (As of 02/22/2020 updated daily from [SAFER](#))
SATISFACTORY
 (Rating Date: 04/27/2017)
Out of Service Rates

Type	OOS %	National Avg %
Vehicle	5.6	20.7
Driver	0.0	5.5
Hazmat		4.5

Licensing and Insurance
 (As of 02/22/2020 updated hourly from [L&I](#))

Active For-Hire Authority

Type	Yes/No	MC#/M
Property	No	
Passenger	Yes	MC-47698C
Household Goods	No	
Broker	No	

BASIC Status (Public Passenger Carrier View) ?

Behavior Analysis & Safety Improvement Categories (BASICS)

Based on a 24-month record ending January 31, 2020



Unsafe Driving	Not Public Crash Indicator	Hours-of-Service Compliance	Vehicle Maintenance	Controlled Substances and Alcohol	Not Public Hazardous Materials Compliance	Driver Fitness

On-Road Performance

0 Measure		1.46 Measure	4.32 Measure	0 Measure		0 Measure
0% Percentile	NOT PUBLIC	74% Percentile	48% Percentile	0% Percentile	NOT PUBLIC	0% Percentile


On-Road Performance Detail

Driver Inspections: NOT PUBLIC (for Crash Indicator and Driver Fitness)

with Unsafe Driving Violations: 0		Driver Inspections: 20	Vehicle Inspections: 19	Driver Inspections: 20		Driver Inspections: 20
Safety Event Group: No Safety Event Grouping		with HOS Compliance Violations: 6	with Vehicle Maint. Violations: 13	with Drugs/Alcohol Violations: 0		with Driver Fitness Violations: 0
Avg. PU × UF: 6.7		Safety Event Group: 11-20 relevant driver inspections	Safety Event Group: 11-20 relevant vehicle inspections	Safety Event Group: No Safety Event Grouping		Safety Event Group: 11-20 relevant driver inspections
Segment: Straight Carrier						

Investigation Results

No Acute/Critical Violations Discovered	N/A	No Acute/Critical Violations Discovered	No Acute/Critical Violations Discovered	No Acute/Critical Violations Discovered	NOT PUBLIC	No Acute/Critical Violations Discovered
---	-----	---	---	---	------------	---

 Denotes this carrier exceeds the FMCSA Intervention Threshold relative to its safety event grouping based upon roadside data and/or has been cited with one or more Acute/Critical Violations within the past 12 months during an investigation. Therefore, this carrier may be prioritized for an intervention action and roadside inspection.

VIOLATION SUMMARY

Violations: 40

Violations	Description	# Violations	# OOS Violations	Violation Severity Weight	BASIC
395.15(g)	Onboard recording device info not available	2	0	1	HOS Compliance
395.15G01	Driver failed to have instructions on-board CMV for installed automatic on-board recording device.	1	0	1	HOS Compliance
395.15I9	Driver not adequately trained in the operation of the automatic on-board recording device.	2	0	1	HOS Compliance
395.20B		2	0	5	

	The ELD's display screen cannot be viewed outside of the commercial motor vehicle.				HOS Compliance
395.22H1	Driver failing to maintain ELD user's manual	3	0	1	HOS Compliance
395.22H4	Driver failed to maintain supply of blank driver's records of duty status graph-grids	1	0	1	HOS Compliance
395.8(k)(2)	Driver failing to retain previous 7 days records of duty status	3	0	5	HOS Compliance
393.11	No or defective lighting devices or reflective material as required	1	0	3	Vehicle Maint.
393.209(d)	Steering system components worn, welded, or missing	1	0	6	Vehicle Maint.
393.24BR	Non-compliant fog or driving lamps	1	0	6	Vehicle Maint.
393.45(d)	Brake connections with leaks or constrictions	1	0	4	Vehicle Maint.
393.47(a)	Inadequate brakes for safe stopping	1	0	4	Vehicle Maint.
393.60(b)	Each bus and truck shall be equipped with a windshield	1	0	1	Vehicle Maint.
393.60(c)	Damaged or discolored windshield	4	0	1	Vehicle Maint.
393.75(a)(1)	Tire-ply or belt material exposed	1	1	8	Vehicle Maint.
393.75(c)	Tire-other tread depth less than 2/32 of inch measured in a major tread groove	1	0	8	Vehicle Maint.
393.78	Windshield wipers inoperative/defective	1	0	1	Vehicle Maint.
393.83(g)	Exhaust leak under truck cab and/or sleeper	2	0	1	Vehicle Maint.
393.9	Inoperable Required Lamp	1	0	2	Vehicle Maint.
393.95(b)	No spare fuses as required	2	0	2	Vehicle Maint.
393.95(f)	No / insufficient warning devices	1	0	2	Vehicle Maint.
396.3(a)(1)	Inspection, repair and maintenance of parts & accessories	2	0	2	Vehicle Maint.
396.3A1B	Brakes (general) Explain:	1	0	4	

					Vehicle Maint.
396.3A1BC	Brake-air compressor violation	1	0	4	Vehicle Maint.
396.3A1BD	Brake-defective brake drum	1	0	4	Vehicle Maint.
396.5(b)	Oil and/or grease leak	2	0	3	Vehicle Maint.

INSPECTION HISTORY

Total Inspections: 20

Report			Vehicle			Measure	
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)
11/5/2019	██████████	US	██████████	CA	BUS		3
	Vehicle Maint. Violation: 393.95(b) No spare fuses as required					2	
	Vehicle Maint. Violation: 393.78 Windshield wipers inoperative/defective					1	
10/23/2019	██████████	CA	██████████	TX	BUS		3
9/14/2019	██████████	CA	██████████	CA	BUS		3
	Vehicle Maint. Violation: 393.60(b) Each bus and truck shall be equipped with a windshield					1	
9/14/2019	██████████	CA	██████████	CA	BUS		3
	Vehicle Maint. Violation: 393.209(d) Steering system components worn, welded, or missing					6	
	Vehicle Maint. Violation: 393.60(c) Damaged or discolored windshield					1	
8/21/2019	██████████	US	██████████	TX	MOTOR COACH		3
8/8/2019	██████████	US	██████████	CA	MOTOR COACH		3
	Vehicle Maint. Violation: 393.95(f) No / insufficient warning devices					2	
	Vehicle Maint. Violation: 393.95(b) No spare fuses as required					2	
	Vehicle Maint. Violation: 396.3A1B Brakes (general) Explain:					4	
8/6/2019	██████████	US	██████████	CA	BUS		3
	Vehicle Maint. Violation: 396.5(b) Oil and/or grease leak					3	
6/18/2019	██████████	US	██████████	CA	MOTOR COACH		2
	HOS Compliance Violation: 395.15(g) Onboard recording device info not available					1	
	HOS Compliance Violation: 395.15G01 Driver failed to have instructions on-board CMV for installed automatic on-board recording device.					1	
	HOS Compliance Violation: 395.15I9 Driver not adequately trained in the operation of the automatic on-board recording device.					1	



Report			Vehicle			Measure	
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)
6/18/2019	[REDACTED]	US	[REDACTED]	CA	BUS		2
Vehicle Maint. Violation: 393.47(a) Inadequate brakes for safe stopping						4	
HOS Compliance Violation: 395.15(g) Onboard recording device info not available						1	
HOS Compliance Violation: 395.15I9 Driver not adequately trained in the operation of the automatic on-board recording device.						1	
HOS Compliance Violation: 395.22H1 Driver failing to maintain ELD user's manual						1	
Vehicle Maint. Violation: 396.3A1BC Brake-air compressor violation						4	
6/17/2019	[REDACTED]	US	[REDACTED]	CA	MOTOR COACH		2
Vehicle Maint. Violation: 393.75(a)(1) Tire-ply or belt material exposed (OOS)						8 + 2 (OOS)	
4/23/2019	[REDACTED]	US	[REDACTED]	CA	MOTOR COACH		2
Vehicle Maint. Violation: 393.45(d) Brake connections with leaks or constrictions						4	
Vehicle Maint. Violation: 393.83(g) Exhaust leak under truck cab and/or sleeper						1	
4/6/2019	[REDACTED]	CA	[REDACTED]	CA	BUS		2
Vehicle Maint. Violation: 393.11 No or defective lighting devices or reflective material as required						3	
Vehicle Maint. Violation: 393.24BR Non-compliant fog or driving lamps						6	
Vehicle Maint. Violation: 393.83(g) Exhaust leak under truck cab and/or sleeper						1	
3/16/2019	[REDACTED]	CA	[REDACTED]	CA	BUS		2
Vehicle Maint. Violation: 393.9 Inoperable Required Lamp						2	
Vehicle Maint. Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories						2	
Vehicle Maint. Violation: 396.3A1BD Brake-defective brake drum						4	
2/2/2019	[REDACTED]	CA	[REDACTED]	CA	BUS		2
HOS Compliance Violation: 395.20B The ELDs display screen cannot be viewed outside of the commercial motor vehicle.						5	
HOS Compliance Violation: 395.22H4 Driver failed to maintain supply of blank drivers records of duty status graph-grids						1	
HOS Compliance Violation: 395.8(k)(2) Driver failing to retain previous 7 days records of duty status						5	
2/2/2019	[REDACTED]	CA	[REDACTED]	CA	BUS		2
HOS Compliance Violation: 395.22H1 Driver failing to maintain ELD user's manual						1	
HOS Compliance Violation: 395.8(k)(2) Driver failing to retain previous 7 days records of duty status						5	



Report			Vehicle			Measure	
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)
2/2/2019	[REDACTED]	CA	[REDACTED]	CA	BUS		2
Vehicle Maint. Violation: 393.60(c) Damaged or discolored windshield						1	
Vehicle Maint. Violation: 393.75(c) Tire-other tread depth less than 2/32 of inch measured in 2 adjacent major tread grooves						8	
HOS Compliance Violation: 395.20B The ELDs display screen cannot be viewed outside of the commercial motor vehicle.						5	
HOS Compliance Violation: 395.22H1 Driver failing to maintain ELD user's manual						1	
11/4/2018	[REDACTED]	CA	[REDACTED]	CA	BUS		1
Vehicle Maint. Violation: 393.60(c) Damaged or discolored windshield						1	
Vehicle Maint. Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories						2	
Vehicle Maint. Violation: 396.5(b) Oil and/or grease leak						3	
10/13/2018	[REDACTED]	CA	[REDACTED]	CA	BUS		1
Vehicle Maint. Violation: 393.60(c) Damaged or discolored windshield						1	
HOS Compliance Violation: 395.8(k)(2) Driver failing to retain previous 7 days records of duty status						5	
9/23/2018	[REDACTED]	CA	[REDACTED]	CA	BUS		1
2/11/2018	[REDACTED]	CA	[REDACTED]	CA	BUS		1

CRASH ACTIVITY DETAIL (VEHICLES INVOLVED IN CRASHES) Number of Crashes: 0

This carrier has no crashes to display.

INVESTIGATION RESULTS Acute/Critical Violations: 0

This carrier has no Acute/Critical violations to display.

Summary of Activities

The summary includes information on the 5 most recent investigations and 24 months of inspections and crash history.

Carrier Registration

Subject to Passenger Threshold

Enforcement Cases

(Six years as of 02/22/2020 updated monthly from [FMCSA](#))

No penalties found



Most Recent Investigation:
10/28/2019 (Non-Ratable
Review)

Total Inspections: 20

Total Inspections
without Violations
used in SMS: 4

Total Inspections
with Violations used
in SMS: 16

Total Crashes* : 0


*Crashes listed represent a
motor carrier's
involvement in reportable
crashes, regardless of the
carrier's or driver's role in
the crash. Continue for
details.


USE OF SMS DATA/INFORMATION

FAST Act of 2015:

Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier has received an UNSATISFACTORY safety rating under part 385 of title 49, Code of Federal Regulations, or has otherwise been ordered to discontinue operations by the Federal Motor Carrier Safety Administration, it is authorized to operate on the Nation's roadways.

Safety Measurement System:

The data in the Safety Measurement System (SMS) is performance data used by the Agency and Enforcement Community. A  symbol, based on that data, indicates that FMCSA may prioritize a motor carrier for further monitoring.

The  symbol is not intended to imply any federal safety rating of the carrier pursuant to 49 USC 31144. Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier in the SMS has received an UNSATISFACTORY safety rating pursuant to 49 CFR Part 385, or has otherwise been ordered to discontinue operations by the FMCSA, it is authorized to operate on the nation's roadways.

Motor carrier safety ratings are available at <http://safer.fmcsa.dot.gov> and motor carrier licensing and insurance status are available at <http://li-public.fmcsa.dot.gov/>.