

# INSPECTION REPORT

Inspector's Name FIGUEROA, ROLAND S.		Inspector's Signature			Inspector's ID No. [REDACTED]	Report No. 79	Date yy mm dd 2020 08 01						
Railroad/Company Name & Address UNION PACIFIC RR CO. 2501 N. Fairland Stav.  Tucson AZ 85713				R/C R	Division SUNSET	RR/Co. Representative (Receipt Acknowledged) Name Jeff Vance Title SR. Manager Email [REDACTED] Signature _____							
From: City PHOENIX	Codes 0370	Destination City & County			Codes	From Latitude							
State AZ	04	City				From Longitude							
County MARICOPA	C013	County				To Latitude							
Mile Post: From To		Inspection Point UPRR MESA AND PHOENIX YARDS				To Longitude							
Activity Code:	215	231	232						CARS				
Units:	61	61	61						61				
Sub Units:	0	0	0						0				
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1									MTUPX-29	N	N	0	
Description - [** Comment to Railroad/Company **] No defects noted on the MTUPX-29 that did not derail, that would have contributed to a derailment on 7/29/2020 at Tempe, Arizona													
Seal Applied		Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			