


February 23, 2018 Test of Yard Line at 3534 Espanola – Test Connection at Meter



February 23, 2018 - 3534 Espanola Yard Line Plugged Where Pipe Broken at House



February 23, 2018 - Ten-minute Pressure Hold Test of 3534 Espanola Yard Line



February 24, 2018 Test of Gas Main

(Test conducted jointly by PHMSA, Texas Railroad Commission, Atmos and BakerRisk)



All gas meters disconnected from main along alley and connections plugged



Air supply and pressure gauge connected to the riser for 3503 Durango

February 24, 2018 - Locations Where Gas Main Capped for Test



Gas main cut and capped at west
end of alley



Gas main cut and capped at east
end of alley