



GOLDEN RAY

FARO S LASER SCANNER

CARGO ASSESSMENT



CARGO ASSESSMENT

Contents

Location	3
October 2, 2019	3
MS037-11	3
MS041-09 (unable to scan-blocked access)	5
MS068-07	6
MS070-11	8
October 3, 2019	10
MS085-09	10
MS099-11	12
MS099-04	14
October 4, 2019	16
MS107-09	16
MS118-09	18
MS145-11	20
October 5, 2019	22
MS166-09	22
MS171-11	24



CARGO ASSESSMENT

Figure 1 MS037-11	4
Figure 2 MS068-07	7
Figure 3 MS070-11	9
Figure 4 MS086-09	11
Figure 5 MS099-11	13
Figure 6 MS099-04	15
Figure 7 MS107-09	17
Figure 8 MS118-09	19
Figure 9 MS145-11	21
Figure 10 MS166-09	23
Figure 11 MS171-11	25




GOLDEN RAY

CARGO ASSESSMENT

Location

October 2, 2019

MS037-11



CARGO ASSESSMENT




Figure 1 MS037-11



CARGO ASSESSMENT


MS041-09 (unable to scan-blocked access)





CARGO ASSESSMENT

MS068-07



CARGO ASSESSMENT




Figure 2 MS068-07



GOLDEN RAY

CARGO ASSESSMENT

MS070-11



CARGO ASSESSMENT



Figure 3 MS070-11




GOLDEN RAY

CARGO ASSESSMENT

October 3, 2019

MS085-09



CARGO ASSESSMENT




Figure 4 MS086-09



GOLDEN RAY

CARGO ASSESSMENT

MS099-11



CARGO ASSESSMENT




Figure 5 MS099-11



GOLDEN RAY

CARGO ASSESSMENT

MS099-04



CARGO ASSESSMENT




Figure 6 MS099-04



CARGO ASSESSMENT

October 4, 2019
MS107-09



CARGO ASSESSMENT




Figure 7 MS107-09



GOLDEN RAY

CARGO ASSESSMENT

MS118-09



CARGO ASSESSMENT




Figure 8 MS118-09



GOLDEN RAY

CARGO ASSESSMENT

MS145-11



CARGO ASSESSMENT




Figure 9 MS145-11



CARGO ASSESSMENT

October 5, 2019
MS166-09



CARGO ASSESSMENT




Figure 10 MS166-09



CARGO ASSESSMENT

MS171-11



CARGO ASSESSMENT



Figure 11 MS171-11