

CONTACTS

ADMINISTRATION

Tracy Sessions Phone: +1 (707) 554-4611 TECHNICIAN

Bobby Licu

SALES

National Transportation Safety Board McAtee Nancy 490 L Enfant Plaza, SW

DC 20594 Washington USA


			Limits			
			TESTS	Min	Max	RESULTS
			ASTM D7303 ICP of Grease		1	
Online results			Aluminum ppm			60.6
https://sofia.sgs.com			Antimony ppm			3134.4
			Barium ppm			238.8
SAMPLE	23T3	39437	Boron ppm			53.2
Sampling date:	09/13/2023	Equipment (km/h): 0	Calcium ppm			32337.0
Reception date:	10/03/2023	Lubricant (km/h): 0	Cadmium ppm			1.4
Diagnosis date:	10/11/2023	Тор-ир (I): 0	Chromium ppm			62.7
Lubricant in use:		Test suite:	Copper ppm			18.4
	GREASE	ICP+WAKF+DRPC+FTAT+WKP3	Iron ppm			15208.7
PO			Lead ppm			3.4
EQUIPMENT 02209451/G001			Lithium ppm			2303.1
Equipment description: Grease			Magnesium ppm			268.4
			Manganese ppm			99.8
Component description: 99609 - ELLISTON, VA, GREASE			Molybdenum ppm			4.7
			Nickel ppm			132.6
Fleet no / Ref.: 99609 - Elliston, VA			Phosphorus ppm			155.8
Ref ID:			Potassium ppm			1179.6
Sample Ref ESI, OMAHA, NE			Silicon ppm			209.1
			Sodium ppm			135.6
			Sulfur ppm			5350.4
Result(s) meet the listed acceptance criteria of AAR M-942 specification for dropping point and cone penetration. However, Silicon and wear indicates there may be dirt in the lubricant. Bushing / Bearing wear is detected. FTIR scan is attached and			Tin ppm			13.6
			Zinc ppm			292.9
			Silver ppm			<0.5
			ASTM D6304			
suggests mineral oil, lithium based grease. Reference for Shell Alvania EP D and Mobil Arapen RB 320 is not available, but the			Water content ppm			371
greases are very similar in properties (lithium calcium grease). ICP analysis also confirms presence of lithium and calcium.			ASTM D2265			
			Dropping Point °C			188.7
			FTIR Scan by ATR			
			Fourier Transform Infrared			ENCLOSED
			ASTM D1403 1/4 scale 25°C/77°F			
			Worked Penetration mm/10			267

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole


responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Vallejo

SGS North America, Inc. 101 Corporate Place CA 94590 Vallejo Phone: +1 (707) 554-4611



Page 1



Page 1