


## National Transportation Safety Board Investigative Hearing

Norfolk Southern Railway general merchandise freight train 32N derailment with subsequent hazardous material release and fires, in East Palestine, Ohio, on February 3, 2023



Agency / Organization

## **Norfolk Southern Railway**

Title

## ICS 201- NS Incident Briefing February 4, 2023



1. Incident Name

32N East Palestine OH Derailment


2. Prepared by: (name)

Date: 02/04/2023

Time: 1113

INCIDENT BRIEFING ICS 201 – NS

3. Map/Sketch (include sketch, showing the total area of operations, the incident site/area, overflight results, trajectories, impacted shorelines, or other graphics depicting situational and response status)



**4. Incident Description / Current Situation:** Train 32N derailed an unknown number of railcars in the city of East Palestine, OH in the area of James St. and Taggart St.

Active fire footprint has been shrunk to immediate area of main derailment "pile"

9 loaded tank cars/2 residue HAZMAT

Active continuous venting from at least 1 vinyl chloride car from list inserted below



1. Incident Name2. Prepared by: (name)INCIDENT BRIEFING32N East Palestine OH DerailmentDate: 02/04/2023Time: 1113ICS 201 – NS

## 5. Initial Response Objectives, Current Actions, Planned Actions

7	27	UTLX 684543	EMPTY	TANK CAR		DOT 117J100W
8	28	TILX 402025	LOADED	TANK CAR	VINYL CHLORIDE, STABILIZED	DOT 105J300W
9	29	OCPX 80235	LOADED	TANK CAR	VINYL CHLORIDE, STABILIZED	DOT 105J300W
0	30	OCPX 80179	LOADED	TANK CAR	VINYL CHLORIDE, STABILIZED	DOT 105J300W
1	31	GATX 95098	LOADED	TANK CAR	VINYL CHLORIDE, STABILIZED	DOT 105J300W
12	32	RACX 51629	LOADED	TANK CAR	DIPROPYLENE GLLYCOL	DOT 111A100W1
13	33	LYBX 5191	LOADED	TANK CAR	PROPYLENE GLYCOL	DOT 117J100W
14	34	RACX 51435	LOADED	TANK CAR	PROPYLENE GLYCOL	DOT 111A100W1
15	35	UTLX 671772	LOADED	TANK CAR	DIETHYLENE GLYCOL	DOT 111A100W1
16	36	SHPX 211226	LOADED	TANK CAR	COMBUSTIBLE LIQ., NOS (ETHYLENE GLYCOL MONOBUTYL ETHER	DOT 111S100W1
17	37	TILX 331319	LOADED	HOPPER	SEMOLINA	
8	38	DOWX 73168	LOADED	TANK CAR	COMBUSTIBLE LIQ., NOS (ETHYLHEXYL ACRYLATE)	DOT 111S100W1
19	39	ROIX 57036	LOADED	HOPPER	POLYVINYL	



INCIDENT BRIEFING ICS 201-Norfolk Southern



1. Incident Name	2. Prepared by: (name)	INCIDENT BRIEFING			
32N East Palestine OH Derailment	Date: 02/04/2023 Time: 1113	ICS 201 – NS			
Objectives this operational period: Establish air monitoring assets with CTEH (NS) Monitor active vent from VC car to establish exh Set JIC with NS/local response  Plan next operational period beginning 2100	and Tetra Tech (EPA)				
	Protect life and health of persons in the area of the derailment site				
	Contain and control fire				
	Assess derailment scene to determine railcars involved in fire/derailment and identify contents				
	Mobilize response contractors to mitigate fire/spills				
	Contain spilled materials				
	Restore train operations				
Remediate spill areas	Remediate spill areas				
	_				

INCIDENT BRIEFING



Incident Name     32N East Palestine OH Derailment	2. Prepared by: (name) Date: 02/04/2023	INCIDENT BRIEFING ICS 201 – NS	
	Date: 02/04/2023	Time: 1113	100 201 110



1. Incident Name	2. Prepared by: (name)	INCIDENT BRIEFING			
32N East Palestine OH Derailment	Date: 02/04/2023 Time: 1113	ICS 201 – NS			
6. Current Organization (fill in additional appropriate organization)					
—— Safety Officer					
Liaison Officer					
Liaison Officer					
Public Information Office	r <u>Connor Spielmaker</u>				
Operations Section Planning Section	Logistics Section Fina	nce Section			
Mech – Josiah Saxe	Logistics Couldin 1 mid	1100 00011011			
Trans –					
Eng –					
ENV – S. Deutsch					
S. Gould					

INCIDENT BRIEFING ICS 201-Norfolk Southern



1. Incident Name		2. Prepared by: (name)			INCIDENT BRIEFING	
32N East Palestine OH Derailme	Date: 02	/04/2023	•	Гіте: 1113	ICS 201 – NS	
7. Resources Summary Resource	Resource Identifier	Date Time Ordered	ETA	On- Scene (X)	NOTES: (Loca	tion/Assignment/Status)
Hazmat Team 1	Нерасо				In route	
Hazmat Team 2	SPSI				In route	
Hazmat Team 3	Enviroserve				In route	
Wrecking Crew 1	Hulcher				In route	
Wrecking Crew 2	Corman				In route	
Wrecking Crew 3						



1. Incident Name2. Prepared by: (name)INCIDENT BRIEFING32N East Palestine OH DerailmentDate: 02/04/2023Time: 1113ICS 201 – NSTailgate HASP – Health and Safety Plan - "Any worker on site can stop work if an unsafe condition exist!"

Chemical **Primary Hazard Secondary Hazard Isolation Distance** Flammable Gas Large spill, fire, at night Vinyl Chloride Large spill, fire, at night Combustible Liquid ETHYLENE GLYCOL 0.5 mile MONOBUTYL ETHER) Combustible Liquid Large spill, fire, at night ETHYL HEXYL ACRYLATE ISOBUTYLENE Flammable Gas Large spill, fire, at night 1 mile **BUTYL ACRYLATES** Flammable Liquid Large spill, fire, at night 0.5 mile BENZENE Flammable Liquid Large spill, fire, at night (BENZOL) residue cars 0.5 mile **Track Protection Authority** Emergency Blue Flag Keystone Division Site Specific Physicals Hazards Fire, possible spills, derailed rail cars, twisted rail, bad footing, Personal Protective Equipment (Check all that apply) -Min level always required - Hard Hat, Safety Glasses, High Visibility Safety Vest, Approved Safety Boots, & Hearing protection Respirator: Type \_\_\_\_\_ Fire Resistant Clothing PPE LEVEL: A B C D □ Chemical Protective Clothing Type □ Glove Type: □ Personal Floatation ☐ Cold Weather Gear Other \_\_\_ Other \_\_\_ On Site **Phone Number** Contacts Name(s) NS-On Site Contact Scott Gould 717-461-6069 On-Site Contractor Hepaco, SPSI, Enviroserve 404/989-2523/412-439-2880 **NS Hazardous Materials** R Wood / **NS Environmental** B. Naranjo / 678-772-0998 M. Dudle / NS Industrial Hygiene 404-273-2082 Help Desk / 866-869-2834 CTEH Other Contact 

INCIDENT BRIEFING ICS 201-Norfolk Southern



Emergency Contact - 911 or Local Fire Dept	Nearest Hospital and Address		
911	East Liverpool City Hospital: Emergency Room 425 W 5th St, East Liverpool, OH 43920		